

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20009364/ABA3Q2
Date: 12/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0000347
Claimant Vehicle No :	SKV2571J	Insured Vehicle No :	SMH3909M
Date of Loss:	27/08/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001666

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV2571J	Engine No:	1ZR526504
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104537384
Reg. Date:	07/09/2015 (Man. Year: 2015)	Odometer:	99458 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,323.20	2,736.30	2,586.90	48.60
Miscellaneous Items	351.00	11.00	340.00	96.87
Labour	1,680.00	1,030.00	650.00	38.69
Paintwork Labour	900.00	600.00	300.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,254.20	4,377.30	3,876.90	46.97
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	8,254.20	3,500.00	4,754.20	57.60
+ GST 7.00/7.00% (S\$)	577.79	245.00	332.79	57.60
Nett Amount (S\$)	8,831.99	3,745.00	5,086.99	57.60
+ Car Rental (5.0 x S\$120.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,389.00		
Global Sum Settlement (S\$)		4,300.00		

INSPECTION

Date of Assignment:	02/09/2020	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	14/09/2020	Inspected At:	Progressive Car Care Pte Ltd (HQ)
			Blk 3022A Ubi Road 1, #01-45/46
			Singapore 408716
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV2571J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR BUMPER	Deformed	556.40 F	*556.40 F
2	1	NA	*REAR BUMPER SIDE HOLDER - LH	Not Necessary	109.00 F	*- F
3	1	NA	*REAR BUMPER SIDE HOLDER - RH	Necessary	109.00 F	*109.00 F
4	1	NA	*REAR BUMPER BRACKET - LH	Not Necessary	68.20 F	*- F
5	1	NA	*REAR BUMPER BRACKET - RH	Not Necessary	68.20 F	*- F
6	10	NA	*REAR BUMPER CLIPS	Necessary	55.00 F	*30.00 F
7	1	NA	*REAR BUMPER SIDE PROTECTOR SEAL - RH	Cut	65.10 F	*65.10 F
8	1	NA	*REAR BUMPER SIDE PROTECTOR CLIP	Necessary	5.50 F	*5.50 F
9	1	NA	*REAR RIM - RH	Cut	1,580.40 F	*1,580.40 F
10	1	NA	*REAR RIM HUPCAP - RH	Not Necessary	49.40 F	*- F
11	1	NA	*REAR ABSORBER - RH	Not Necessary	218.20 F	*- F
12	1	NA	*REAR WHEEL BEARING - RH	Not Necessary	960.50 F	*- F
13	1	NA	*REAR FENDER - RH	Repair	1,149.80 F	*- F
14	1	NA	*ROCKER PANEL - RH	Repair	482.80 F	*- F
15	1	NA	*REAR DOOR - RH	Dented	1,248.50 F	*1,248.50 F
16	1	NA	*REAR DOOR STICKER - RH	Necessary	53.50 F	*53.50 F
17	1	NA	*REAR DOOR RUBBER - RH	Not Necessary	180.10 F	*- F
18	1	NA	*REAR DOOR CHROME OUTER WINDOW - RH	Not Necessary	138.00 F	*- F

F=Franchise part.

Sub Total (S\$)	7,097.60	3,648.40
- Add. Disc. on L,N Items 25.00/25.00% (S\$)	1,774.40	912.10
Total Parts (S\$)	5,323.20	2,736.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR TYRE - RH (NOT NECESSARY)	280.00	0.00
2	2	SEALANT (NOT NECESSARY)	40.00	0.00
3	1	SPONGE TAPE (NOT NECESSARY)	20.00	0.00
4	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			351.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900.00	600.00
Labour Items				
2	TO KNOCK OUT DENTS; CUT/WELD RH REAR FENDER; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00	800.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO TUFF-KOTE	New	90.00	60.00
5	TO REMOVE; REFIX REAR GLASS	New	120.00	0.00
6	TO 4 WHEEL ALIGNMENT	New	70.00	70.00
7	TO REMOVE; REPLACE REAR UNDERCARRIAGE	New	200.00	0.00
8	TO TRANSFER DOOR AND DOOR FITTING	New	80.00	80.00
Gross Labour Cost (S\$)			2,580.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >