Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009371/KES3Q2

07319574N55B30A

Date: 16/04/2021

REFERENCE

Date of Loss: 01/09/2020 Nature of Claim: TP Claim No: 0240981887SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SY54M

Make & Model: BMW 540I, 3.0 SR LED NAV HUD RCP MSPORT Engine No:

(A)

Reg. Date: 15/11/2016 (Man. Year: 2016) Chassis No: WBA5B12000D327863

Colour: Metallic Blue Odometer: 59738 km

Engine Capacity: 2979 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 275/40 R18
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,710.89	1,779.08	1,931.81	52.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,390.00	460.00	24.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,560.89	3,169.08	2,391.81	43.01
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	5,560.89	2,500.00	3,060.89	55.04
+ GST 7.00/7.00% (S\$)	389.26	175.00	214.26	55.04
Nett Amount (S\$)	5,950.15	2,675.00	3,275.15	55.04
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/S	earch Fee (S\$)	2.00		
Ne	tt Liability (S\$)	3,077.00		

INSPECTION

Date of Assignment: 03/09/2020

Date Inspected: 09/09/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT RH DOOR	Bent	1,783.40 FL	*1,783.40 FL	
2	1		*FRONT RH DOOR INNER RUBBER (50%)	Necessary	161.22 FS	*84.85 FS	
3	1		*REAR RH DOOR	Repair	1,783.40 FL	*- FL	
4	1		*REAR RH DOOR INNER RUBBER	Not Necessary	169.70 FL	*- FL	
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc.	,			
				Sub Total (S\$)	3,897.72	1,868.25	
- List Item Discount on L Items 5.00/5.00% (S\$)					186.83	89.17	
				Total Parts (S\$)	3,710.89	1,779.08	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX FRT & REAR RH DOORS ,TRANSFER DOORS ATTACHMENT & REALIGN THE SAME	New	650.00	500.00
2	REMOVE & REFIX FRT & REAR RH DOOR GLASS	New	160.00	80.00
3	PUTTY & RESPRAY ON FRT & REAR RH DOORS ,REAR RH FENDER	New	800.00	680.00
4	TO RESET SYSTEM	New	180.00	100.00
5	RUST PROOFING	New	60.00	30.00
	Gross Labour Cost (S\$)		1,850.00	1,390.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.