

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20009373/EYF3E2
Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : FBN1274Y **Insured Vehicle No :** SLV2801J
 Date of Loss: 28/08/2020 Nature of Claim: TP Claim No: 0694232951SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN1274Y**
 Make & Model: HONDA CB150R, 149cc Engine No: KC32E0024341
 Reg. Date: 24/07/2018 (Man. Year: 2018) Chassis No: MLHKC2882J5024341
 Colour: Red Odometer: 18680 km
 Engine Capacity: 149 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70Z R17 Rear Tyre Size: 150/60Z R17
 Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/09/2020
 Date Inspected: 03/09/2020 Inspected At: Teamwork Garage Pte Ltd (HQ)
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park
 Singapore 408934
 Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
3	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*HANDLE GUARD RH	Cut	0.00 F	*- F
6	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
7	1		*SIDE FAIRING	Cut	0.00 F	*- F
8	1		*FAIRING LOWER	Cut	0.00 F	*- F
9	1		*ENGINE PROTECTOR MOUNTING (RH)	Bent	0.00 F	*- F
10	1		*ACCELERATOR CABLE	Torn	0.00 F	*- F
11	1		*FOOT BRAKE	Bent	0.00 F	*- F
12	1		*FRONT FOOT REST	Broken	0.00 F	*- F
13	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
14	1		*REAR BOX	Cut	0.00 F	*- F
15	1		*STICKER	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >