

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20009374/KPS3Q2

Date: 04/03/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00002268

Claimant
Vehicle No : PC990L **Insured Vehicle No :** SJW2026Z

Date of Loss: 01/09/2020 Nature of Claim: TP Claim No: 1202000020136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC990L		
Make & Model:	TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)	Engine No:	1KD2119208
Reg. Date:	24/11/2011 (Man. Year: 2011)	Chassis No:	JTFST22P800011583
Colour:	White	Odometer:	150511 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Delium 7 mm	Rear Left Side:	Delium 7 mm
Front Right Side:	Delium 7 mm	Rear Right Side:	Delium 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,200.80	600.80	600.00	49.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	450.00	300.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,950.80	1,050.80	900.00	46.13
Approved Total (Overridden) (\$\$)		850.00		
(\$\$)	1,950.80	850.00	1,100.80	56.43
+ GST 7.00/7.00% (\$\$)	136.56	59.50	77.06	56.43
Nett Amount (\$\$)	2,087.36	909.50	1,177.86	56.43
+ Loss of Use (2.0 x S\$120.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,156.95		

INSPECTION

Date of Assignment: 03/09/2020

Date Inspected: 07/09/2020 Inspected At:

Lim Tan Motor Pte Ltd (HQ)
Blk 176 Sin Ming Drive #03-09/10, Sin
Ming Auto Care
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2020)
Parts:	213	TOYOTA HIACE 3.0 D High-roof 14 Seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC990L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	396.80 FL	*396.80 FL
2	1		*REAR BUMPER RETAINER	Distorted	48.70 FL	*48.70 FL
3	1		*TAIL LAMP LOWER GARNISH	Dented	88.90 FL	*88.90 FL
4	1		*REAR BUMPER SENSOR	Scratched	200.00 FS	*200.00 FS
5	1		*COS LOGO	Not Necessary	600.00 FS	*- FS
					Sub Total (\$\$)	1,334.40 734.40
					- List Item Discount on L Items 25.00/25.00% (\$\$)	133.60 133.60
					Total Parts (\$\$)	1,200.80 600.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT	New	450.00	200.00
2	LABOUR CHARGES	New	300.00	250.00
Gross Labour Cost (\$)			750.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >