

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009376/UYP3E2

Date: 05/10/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30549919011
Claimant Vehicle No :	GBH4374D	Insured Vehicle No :	YN9175A
Date of Loss:	12/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D203174/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4374D	Engine No:	1KD2769633
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y30K209675
Reg. Date:	25/05/2018 (Man. Year: 2017)	Odometer:	74897 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,480.29	1,461.52	2,018.77	58.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,040.00	680.00	39.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,200.29	2,501.52	2,698.77	51.90
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	5,200.29	2,000.00	3,200.29	61.54

INSPECTION

Date of Assignment:	03/09/2020	
Date Inspected:	04/09/2020 Inspected At:	Leang Automotive (Kaki Bukit) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2020)

Parts: N/A TOYOTA DYNA 150 3.0 D 5MT (M) (Catalogue:Merimen Singapore 1.0) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH4374D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Repair	1,066.50 F	*- FL
2	1		*FRONT PANEL DYNA EMBLEM	Necessary	58.20 F	*58.20 FL
3	1		*FRONT VIEW MIRROR BRACKET W/MOTOR N/S	Bent / Cracked	509.23 F	*509.23 FL
4	1		*FRONT GRILLE	Cracked	420.16 F	*420.16 FL
5	1		*HEADLAMP N/S	Cracked	961.10 F	*961.10 FL
6	1		*FRONT BUMPER	Repair	465.10 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,480.29	1,948.69
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	487.17

Total Parts (S\$)	3,480.29	1,461.52
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	750.00	420.00
5	TO PUTTY & SPRAY PAINTING	New	750.00	600.00
Gross Labour Cost (S\$)			1,720.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >