

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG20009377/KQF3N2**Date:** 18/11/2021REFERENCE

|                              |                                      |                             |             |
|------------------------------|--------------------------------------|-----------------------------|-------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 30001320103 |
| <b>Claimant Vehicle No :</b> | YM6871Z                              | <b>Insured Vehicle No :</b> | XE2535A     |
| Date of Loss:                | 28/08/2020                           | Nature of Claim:            | TP          |
|                              |                                      | Claim No:                   | 247143      |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |  |             |              |
|-----------------------------|--|-------------|--------------|
| Reg No:                     | <b>YM6871Z</b>                         |             |              |
| Make & Model:               | MITSUBISHI FE83BEOSRDEA, 3.0 D B31 (A) | Engine No:  | 4M42A42866   |
| Reg. Date:                  | 10/07/2007 (Man. Year: 2007)           | Chassis No: | FE83BEA10140 |
| Colour:                     | White                                  | Odometer:   | 405497 km    |
| Engine Capacity:            | 2977 cc                                |             |              |
| Market Value/New Car Price: | N/A                                    |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>      |             |              |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |                 |
|-------------------|---------------|------------------|-----------------|
| Front Tyre Size:  | 700R16X10     | Rear Tyre Size:  | 185R14X8 (D)    |
| Front Left Side:  | Yokohama 9 mm | Rear Left Side:  | Yokohama 7/7 mm |
| Front Right Side: | Yokohama 9 mm | Rear Right Side: | Yokohama 7/7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 11,154.91         | 10,396.84         | 758.07            | 6.80          |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 1,950.00          | 1,450.00          | 500.00            | 25.64         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>13,104.91</b>  | <b>11,846.84</b>  | <b>1,258.07</b>   | <b>9.60</b>   |
| <b>+ GST 7.00/7.00% (S\$)</b> | 917.34            | 829.28            | 88.06             | 9.60          |
| <b>Nett Amount (S\$)</b>      | <b>14,022.25</b>  | <b>12,676.12</b>  | <b>1,346.13</b>   | <b>9.60</b>   |

INSPECTION

|                             |            |   |
|-----------------------------|------------|---|
| Date of Assignment:         | 03/09/2020 |   |
| Date Inspected:             | 23/02/2021 | Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)<br>Blk 9 Sector C, #01-42 Sin Ming Industrial Estate<br>Singapore 575644 |
| Estimated Period of Repair: | 10.0 days  |   |

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$317.14 NETT)

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | (Last Synchronised: 18 Nov 2021)   |   |
| <b>Parts:</b>        | N/A  | MITSUBISHI FE83BEOSRDEA 3.0 D B31 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for YM6871Z)   |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars  | Condition | Repairer's  | Amount       |
|-----|-----|----------|--|-----------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER  | Buckled   | 986.40 FL   | *986.40 FL   |
| 2   | 1   |          | *RH FRONT SIDE LAMP  | Cracked   | 159.73 FL   | *159.73 FL   |
| 3   | 1   |          | *RH FRONT DOOR   | Bent      | 2,071.55 FL | *2,071.55 FL |
| 4   | 1   |          | *RH FRONT WING MIRROR  | Missing   | 107.68 FL   | *107.68 FL   |
| 5   | 1   |          | *RH FRONT MIRROR BRACKET   | *Check    | 422.85 FL   | *- FL        |
| 6   | 1   |          | *RH FRONT MIRROR BRACKET COVER   | Missing   | 70.43 FL    | *70.43 FL    |
| 7   | 1   |          | *COMPANY LOGO STICKER  | Necessary | 600.00 FS   | *350.00 FS   |
| 8   | 1   |          | *TO REPLACE REAR COLD BOX PANEL, LOCK BAR, ALUMINIUM PLATE, LOCK BAR INCLUDING LABOUR AND PART | Bent      | 7,500.00 FS | *7,500.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                  |
|--|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>11,918.64</b> | <b>11,245.79</b> |
| <b>- List Item Discount on L Items 20.00/25.00% (\$\$)</b> | 763.73           | 848.95           |
| <b>Total Parts (\$\$)</b>                                  | <b>11,154.91</b> | <b>10,396.84</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars           | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                       |          |                 |                 |
| 1                               | PANEL BEATING         | New      | 500.00          | 400.00          |
| 2                               | SPRAY PAINTING CHARGE | New      | 1,400.00        | 1,000.00        |
| 3                               | TRANSFER OF DOOR      | New      | 50.00           | 50.00           |
| <b>Gross Labour Cost (\$\$)</b> |                       |          | <b>1,950.00</b> | <b>1,450.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >