

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 17 Mar 2021

**Preliminary Advice**

|                    |                                                                                                                 |                         |              |
|--------------------|-----------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : XE2535A                                                                                                       |                         |              |
| TP Vehicle No      | : YM6871Z                                                                                                       | Accident Date           | : 28/08/2020 |
| Make               | : MITSUBISHI FE83BEOSRDEA                                                                                       | Assignment Date         | : 03/09/2020 |
| Date of Inspection | : 23/02/2021                                                                                                    | Est. Duration of Repair | : 10         |
| Inspection At      | : BIFROST AUTO PTE LTD (SIN MING) (HQ)<br>BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE<br>SINGAPORE 575644 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 13,104.91 |
| Revised Amount              | :S\$ | 11,846.84 |
| Check Items (Estimated)     | :S\$ | 317.14    |
| Total                       | :S\$ | 12,163.98 |
| Lump Sum Repair             | :S\$ |           |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.