

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20009381/AVF3E2

Date: 12/04/2021

REFERENCE

Insured/Claimant:	ZOU QIBIN	Policy No:	1700050003	Claim No:	2485613956SG
Date of Loss:	02/09/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS1885P	Engine No:	CHZ528864
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V2J1013309
Reg. Date:	12/09/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,724.00	15,739.44	10,984.56	41.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,964.00	10,999.00	8,965.00	44.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,688.00	26,738.44	19,949.56	42.73
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	46,088.00	26,138.44	19,949.56	43.29
+ GST 7.00/7.00% (S\$)	3,226.16	1,829.69	1,396.47	43.29
Nett Amount (S\$)	49,314.16	27,968.13	21,346.03	43.29

INSPECTION

Date of Assignment:	03/09/2020		
Date Inspected:	03/09/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	13.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	38.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	159.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	530.00 FS	*424.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Cracked	293.00 FS	*234.40 FS
7	1		*FRONT BUMPER COVER TRIM - RH	Not Necessary	161.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	37.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,406.00 FS	*- FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	189.00 FS	*150.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Distorted	186.00 FS	*148.40 FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Bent	715.00 FS	*571.60 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	187.00 FS	*149.60 FS
14	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*- FS
15	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
17	1		*SIGNAL HORN - RH LOW TONE	Cracked	197.00 FS	*157.60 FS
18	1		*FRONT FENDER - LH / RH	O/S Distorted	1,682.00 FS	*672.80 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
20	1		*FRONT FENDER BRACKET - RH	Distorted	27.00 FS	*21.52 FS
21	1		*FRONT FENDER BRACKET - RH	Distorted	38.00 FS	*30.40 FS
22	1		*FRONT FENDER BRACE	Distorted	95.00 FS	*75.68 FS
23	1		*FRONT FENDER CLOSING ELEMENT - RH	Distorted	33.00 FS	*25.92 FS
24	1		*WHEEL HOUSING LINER SEAL - RH	Not Necessary	34.00 FS	*- FS
25	1		*FRONT FENDER INSULATION - RH	Not Necessary	42.00 FS	*- FS
26	1		*WHEEL HOUSING LINER - RH	Torn	167.00 FS	*133.20 FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	88.00 FS	*- FS
28	1		*BONNET	Distorted	3,134.00 FS	*2,507.20 FS
29	1		*BONNET ATTACHMENT PARTS	Not Necessary	163.00 FS	*- FS
30	2		*BONNET LID HINGE - LH / RH	Not Necessary	122.00 FS	*- FS
31	1		*BONNET CATCH HOOK	Not Necessary	89.00 FS	*- FS
32	1		*BONNET GAS FILLED STRUT	Not Necessary	118.00 FS	*- FS
33	1		*BONNET STRIKER - RH	Not Necessary	109.00 FS	*- FS
34	1		*BONNET EDGE PROTECTION	Necessary	28.00 FS	*21.84 FS
35	1		*FRONT FENDER TOP SUPPORT COVER - RH	Not Necessary	41.00 FS	*- FS
36	1		*BONNET CATCH HOOK	Not Necessary	63.00 FS	*- FS
37	1		*BONNET LID LOCK	Damaged	212.00 FS	*169.20 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
39	1		*BONNET LID LOCK CABLE	Not Necessary	73.00 FS	*- FS
40	1		*BONNET SOUND ABSORBER	Not Necessary	217.00 FS	*- FS
41	1		*PLENUM CHAMBER COVER	Cracked	177.00 FS	*141.60 FS
42	1		*LED HEADLIGHT - RH	Smashed	5,455.00 FS	*4,364.00 FS
43	1		*MAIN LIGHT ELECTRONICS POWER MODULE - RH	Cracked	749.00 FS	*599.20 FS
44	1		*LED WITH HEAT SINK - RH	Damaged	725.00 FS	*580.00 FS
45	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Damaged	551.00 FS	*440.80 FS
46	1		*HEADLAMP REPAIR KIT	Not Necessary	130.00 FS	*- FS
47	1		*HEADLIGHT HOSE - RH	Not Necessary	40.00 FS	*- FS
48	1		*LIFT CYLINER	Cracked	141.00 FS	*112.40 FS
49	1		*LIFT CYLINDER HOSE	Not Necessary	67.00 FS	*- FS
50	1		*FRONT FENDER TOP SUPPORT - RH	Buckled	73.00 FS	*58.40 FS
51	1		*LOCK CARRIER	Cracked	719.00 FS	*575.20 FS
52	1		*AIRCON CONDENSER	Not Necessary	517.00 FS	*- FS
53	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	18.00 FS	*- FS
54	1		*READY MIX COOLANT	Necessary	91.00 FS	*72.32 FS
55	1		*ADDITIONAL RADIATOR	Broken	859.00 FS	*687.20 FS
56	1		*RADIATOR	Not Necessary	941.00 FS	*- FS
57	1		*RADIATOR AIR GUIDE - RH	Cracked	24.00 FS	*19.20 FS
58	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
59	1		*AIR INTAKE AIR DUCT COVER	Not Necessary	28.00 FS	*- FS
60	1		*AIR INTAKE AIR GUIDE	Not Necessary	54.00 FS	*- FS
61	1		*AIR INTAKE AIR GUIDE	Not Necessary	64.00 FS	*- FS
62	1		*AIR INTAKE AIR FILTER	Not Necessary	269.00 FS	*- FS
63	1		*AIR INTAKE AIR GUIDE	Not Necessary	19.00 FS	*- FS
64	1		*WATER DRAINAGE HOSE	Not Necessary	32.00 FS	*- FS
65	1		*WINDOW SLOT SEAL - RH FRONT	Not Necessary	305.00 FS	*- FS
66	1		*WATER DEFLECTOR STRIP - RH	Missing	92.00 FS	*72.88 FS
67	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
68	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
69	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
70	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
71	1		*SUNDRIES	Necessary	400.00 FS	*36.32 FS
72	1		*AIRCON REFRIGERANT LINE (COMPRESSOR TO CUT OFF POINT)	Bent	476.00 FS	*380.40 FS
73	1		*SOCKET FOR SIGNAL HORN RHS	Cracked	20.00 FS	*15.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 26,724.00 15,739.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	800.00
3	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
4	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
5	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
6	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	350.00	280.00
7	TO PLACE VEHICLE ON CAR-O-LINER	New	1,800.00	1,800.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,700.00	3,250.00
9	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, RHS FRONT DOOR, RHS FRONT FENDER TOP SUPPORT AND RHS A-PILLAR. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,300.00	2,475.00
10	TO CARRY OUT PRE-WHEEL ALIGNMENT TEST	New	240.00	0.00
11	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK	New	384.00	384.00
12	TO RENEW AIRCOND REFRIGERANT LINE AND CARRY OUT VACUUM AND REGAS	New	280.00	280.00
Gross Labour Cost (\$\$)			19,964.00	10,999.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >