

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20009384/NSF3E2  
**Date:** 06/01/2021

### REFERENCE

Insured/Claimant: SITI NORKHAIRISHA BINTE KHAIRIL ANUAR Policy No: 1900265080  
Date of Loss: 31/08/2020 Nature of Claim: OD Claim No: 8247304017SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN9093A**  
Make & Model: HONDA NC750XA, 745cc Engine No: RC88E5201510  
Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: JH2RC90A1KK301418  
Colour: Blue Odometer: 9798 km  
Engine Capacity: 745 cc  
Market Value/New Car Price: S\$18,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 160/60 R17  
Front Left Side: Dunlop 3 mm Rear Left Side: Dunlop 3 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,595.70	7,116.70	3,479.00	32.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	690.00	1,500.00	68.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,785.70</b>	<b>7,806.70</b>	<b>4,979.00</b>	<b>38.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,250.00</b>		
<b>- Excess (S\$)</b>	750.00	750.00	0.00	0.00
<b>(S\$)</b>	12,035.70	5,500.00	6,535.70	54.30
<b>+ GST 7.00/7.00% (S\$)</b>	842.50	385.00	457.50	54.30
<b>Nett Amount (S\$)</b>	<b>12,878.20</b>	<b>5,885.00</b>	<b>6,993.20</b>	<b>54.30</b>

### INSPECTION

Date of Assignment: 03/09/2020  
Date Inspected: 04/09/2020 Inspected At: Bike Production (HQ)  
No 610 Serangoon Road  
Singapore 218216  
Estimated Period of Repair: 3.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cracked	345.00 FL	*280.00 FL
2	1		*FRONT MUDGUARD BRACE	Bent	145.00 FL	*100.00 FL
3	1		*FRONT WHEEL AXLE	Serviceable	135.00 FL	*- FL
4	1		*FRONT BRAKE DISK	Scratched	335.00 FL	*300.00 FL
5	1		*FRONT BRAKE ABS DISK	Serviceable	235.00 FL	*- FL
6	1		*FRONT BRAKE CALIPER	Serviceable	395.00 FL	*- FL
7	2		*STEERING STEM BEARING	Necessary	90.00 FL	*90.00 FL
8	1		*FRONT RIGHT FORK ASSEMBLY	Scratched	1,085.00 FL	*1,000.00 FL
9	1		*FRONT LEFT FORK ASSEMBLY	Serviceable	1,085.00 FL	*- FL
10	1		*STEERING HEAD CROWN	Serviceable	405.00 FL	*- FL
11	1		*STEERING STEM UNDERBRACKET	Deformed	440.00 FL	*440.00 FL
12	1		*CRASH BAR	Bent	395.00 FL	*395.00 FL
13	1		*BRAKE LEVER	Scratched	105.00 FL	*105.00 FL
14	1		*RIGHT BALANCER	Scratched	65.00 FL	*65.00 FL
15	1		*RIGHT VIEW MIRROR	Scratched	145.00 FL	*145.00 FL
16	1		*HANDLE BAR	Deformed	245.00 FL	*200.00 FL
17	1		*RIGHT FRONT SIGNAL	Scratched	165.00 FL	*120.00 FL
18	1		*RIGHT BODY FAIRING	Scratched	395.00 FL	*395.00 FL
19	1		*HONDA WING DECAL	Necessary	58.00 FL	*58.00 FL
20	1		*RIGHT BLACK COVER	Cracked	350.00 FL	*350.00 FL
21	1		*RADIATOR ASSEMBLY	Deformed	655.00 FL	*550.00 FL
22	1		*BRAKE PEDAL	Scratched	175.00 FL	*175.00 FL
23	1		*RIGHT FRONT FOOTREST	Scratched	85.00 FL	*85.00 FL
24	1		*RIGHT FRONT FOOTREST HOLDER	Serviceable	295.00 FL	*- FL
25	1		*RIGHT REAR FOOTREST	Scratched	65.00 FL	*65.00 FL
26	1		*EXHAUST HEAT SHIELD	Scratched	195.00 FL	*150.00 FL
27	1		*EXHAUST ASSEMBLY	Scratched	950.00 FL	*850.00 FL
28	1		*FRONT SPORT RIM	Damaged	750.00 FS	*650.00 FS
29	1		*COOLANT	Not Necessary	50.00 FS	*- FS
30	1		*BOX BRACKET	Deformed	250.00 FS	*250.00 FS
31	1		*TOP CASE	Missing	480.00 FS	*400.00 FS
32	1		*RIGHT REFLECTOR	Cracked	45.00 FL	*45.00 FL
33	1		*FAN MOTOR	Serviceable	235.00 FL	*- FL
34	1		*LEFT VIEW MIRROR	Not Necessary	145.00 FL	*- FL
35	1		*LEFT REAR COVER	Deformed	305.00 FL	*250.00 FL
36	1		*RIGHT REAR COVER	Deformed	305.00 FL	*250.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,603.00	7,763.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,007.30	646.30
Total Parts (\$)	10,595.70	7,116.70

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS.	New	800.00	450.00
3	REPAIR AND BALANCING FRONT WHEEL RIM.	New	90.00	40.00
4	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.	New	180.00	100.00
5	RESET METER	New	120.00	0.00
6	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	New	450.00	0.00
7	SPRAY PAINTING.	New	300.00	100.00
8	REPAIR LEFT FORK	New	150.00	0.00
Gross Labour Cost (\$\$)			2,190.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >