Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

CC3/III20009395/KBA3Q2 Our File No:

Date: 16/11/2020

Odometer:

**REFERENCE** 

India International Insurance Handling Insurer:

Pte Ltd

D18MPC0001603 01

Claimant

Date of Loss:

SHC5088D

**Insured Vehicle** No:

Nature of Claim:

Policy No:

SBF1S

TP

Vehicle No:

01/09/2020

Claim No:

MPC2020D0001693

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SHC5088D Reg No:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: Make & Model:

M9R8839C000556

Reg. Date: 27/12/2013 (Man. Year: 2013) Chassis No: VF1ABL15AUC275910 610511 km

Metallic White/Red Colour:

**Engine Capacity:** 1995 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

**Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Sailun 9 mm Rear Left Side: Falken 7 mm Front Right Side: Rear Right Side: Falken 7 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,903.85	3,279.12	4,624.73	58.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,005.00	2,875.00	74.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,783.85	4,284.12	7,499.73	63.64
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	11,783.85	3,450.00	8,333.85	70.72
+ GST 7.00/7.00% (S\$)	824.87	241.50	583.37	70.72
Nett Amount (S\$)	12,608.72	3,691.50	8,917.22	70.72
+ Car Rental (3.0 x S	881.13/day) (S\$)	243.39		
+ Loss of Earnings (3.0 x S\$40.00/day) (S\$)  + Doc/Search Fee (S\$)  Nett Liability (S\$)  Global Sum Settlement (S\$)		120.00		
		7.49		
		4,062.38		
		4,000.00		

**INSPECTION** 

Date of Assignment: 02/09/2020

Date Inspected: 02/09/2020 Inspected At: Adjuster Report Page 2 of 4

Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Page 3 of 4 Adjuster Report

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Oct 2020)

RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

Labour: (Price-denominated Standard List) Repairer's

Print Code: (Unsubmitted, no print-code for SHC5088D)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR REAR	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
8	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
9	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
10	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
11	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
12	1		*TAIL LAMP	Serviceable	401.40 FL	*- FL
13	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
14	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
19	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
20	1		*BOOT HINGE	Repair	254.20 FL	*- FL
21	1		*EXHAUST CAP REAR	Repair	125.40 FL	*- FL
22	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
23	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
24	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	55.00 FS	*- FS
25	1		*SET BUMPER RETAINER CLIP RR	Not Necessary	60.00 FS	*- FS
26	1		*SET BUMPER BRACKET SIDE CLIP RR	Not Necessary	65.00 FS	*- FS
27	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	69.00 FS	*- FS
28	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
29	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
30	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
31	1		*SET BOOT FINISHER CLIP	Not Necessary	55.00 FS	*- FS
32	1		*TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
33	1		*REAR BUMPER REFLECTOR	Necessary	170.00 FS	*30.00 FS
34	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
35	1		*END PANEL TRIM CLIP	Not Necessary	55.00 FS	*- FS
F=Fra	ınchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	8,591.06	3,616.80
			- List Item Discount on L Item	s 10.00/10.00% (S\$)	687.21	337.68

**Total Parts (S\$)** 7,903.85 3,279.12

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New )	380.00	0.00
PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,200.00	400.00
TO REINSTALL REAR BUMPER PARKING	New	170.00	60.00
TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	440.00
Gross Labour Cost (S\$)		3,880.00	1,005.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. TO REINSTALL REAR BUMPER PARKING TO CHECK ELECTRICAL LIGHTING CONCERNED TO REPAIR AND REALIGN REAR EXHAUST PIPE PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  TO TRANSFER OF REAR BUMPER New FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS  TO REMOVE AND REFIT INTERIOR New FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR  PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NEW NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.  TO REINSTALL REAR BUMPER PARKING New TO CHECK ELECTRICAL LIGHTING CONCERNED New PUTTY AND SPRAY PAINTING OF THE AFFECTED New PORTION	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  TO RUST-PROOFING AND APPLY UNDERCOAT OF THE New 250.00 AFFECTED AREAS  TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER, TO ENABLE REPAIR  PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NEW 1,200.00 NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.  TO REINSTALL REAR BUMPER PARKING New 170.00  TO CHECK ELECTRICAL LIGHTING CONCERNED New 170.00  PUTTY AND SPRAY PAINTING OF THE AFFECTED New 1,200.00  PORTION

< END OF ESTIMATES >

Report was unsubmitted during this print-out.