

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009398/AES3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700050003

Claimant
Vehicle No : SMN263E **Insured Vehicle No :** SLS1885P

Date of Loss: 02/09/2020 Nature of Claim: TP Claim No: 2485613956SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN263E		
Make & Model:	TOYOTA NOAH, 1.8 (A)	Engine No:	2ZR2D96699
Reg. Date:	23/07/2019 (Man. Year: 2019)	Chassis No:	ZWR800392556
Colour:	Silver	Odometer:	95254 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,849.20	9,787.15	41,062.05	80.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,180.00	3,710.00	3,470.00	48.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	58,029.20	13,497.15	44,532.05	76.74
Approved Total (Overridden) (S\$)		10,800.00		
(S\$)	58,029.20	10,800.00	47,229.20	81.39
+ GST 7.00/7.00% (S\$)	4,062.04	756.00	3,306.04	81.39
Nett Amount (S\$)	62,091.24	11,556.00	50,535.24	81.39
+ Loss of Use (12.0 x S\$90.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,638.00		
Global Sum Settlement (S\$)		12,600.00		

INSPECTION

Date of Assignment: 03/09/2020

Date Inspected: 03/09/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	3,325.00 F	*1,562.00 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	456.00 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Damaged	1,064.00 F	*588.00 FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	106.40 F	*106.40 FL
5	1		*REAR BOOT LID HYBRID SYNERGY DRIVE LOGO	Necessary	85.20 F	*85.20 FL
6	1		*REAR BOOT LID NOAH CHROME MOULDING	Cracked	1,121.00 F	*425.00 FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	197.60 F	*- FL
8	1		*REAR BOOT LID BRAKE LAMP	Not Necessary	342.00 F	*- FL
9	1		*REAR BOOT LID INNER LOCK	Damaged	627.00 F	*455.00 FL
10	1		*REAR BOOT LID INNER RUBBER	Cut	608.00 F	*327.00 FL
11	1		*REAR BOOT LID INNER TRIM BOARD LOGO	Not Necessary	1,330.00 F	*- FL
12	1		*REAR BOOT LID INNER TRIM BOARD LOWER	Deformed	495.00 F	*495.00 FL
13	20		*REAR BOOT LID INNER TRIM BOARD CLIP	Necessary	130.00 F	*30.00 FL
14	1		*REAR WINDSCREEN	Not Necessary	3,686.00 F	*- FL
15	1		*REAR WINDSCREEN SEAL	Necessary	85.00 F	*85.00 FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	107.00 F	*107.00 FL
17	1		*REAR WINDSCREEN WIPER ARM	Not Necessary	114.00 F	*- FL
18	1		*REAR WINDSCREEN WIPER MOTOR	Not Necessary	1,064.00 F	*- FL
19	1		*REAR TAILLAMP	N/S Cut	2,052.00 F	*781.00 FL
20	4		*REAR TAILLAMP CLIP	Necessary	32.00 F	*10.00 FL
21	1		*REAR TAILLAMP PANEL	N/S Distorted	722.00 F	*247.00 FL
22	1		*REAR TAILLAMP LOWER COVER	N/S Deformed	646.00 F	*198.00 FL
23	2		*REAR TAILLAMP LOWER COVER RUBBER STOPPER	Not Necessary	104.00 F	*- FL
24	1		*REAR TAILLAMP LOWER COVER RETAINER	N/S Damaged	456.00 F	*35.00 FL
25	1		*REAR BUMPER	Distorted	2,324.00 F	*1,050.00 FL
26	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
27	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	243.20 F	*58.00 FL
28	1		*REAR BUMPER TOWING COVER	Missing	68.40 F	*28.00 FL
29	1		*REAR END PANEL	Distorted	1,140.00 F	*683.00 FL
30	1		*REAR END PANEL TOP GARNISH	Deformed	456.00 F	*289.00 FL
31	1		*REAR FENDER	N/S Distorted	5,152.00 F	*1,339.00 FL
32	1		*REAR FENDER TOP GARNISH COVER	Deformed	1,368.00 F	*295.00 FL
33	2		*REAR FENDER AIR DUCT	Cracked	380.00 F	*78.00 FL
34	2		*REAR FENDER GLASS ASSY	Not Necessary	1,786.00 F	*- FL
35	1		*REAR FENDER INNER TRIM BOARD	N/S Deformed	1,520.00 F	*681.00 FL
36	1		*REAR FENDER INNER TRIM BOARD CLIP (16 PCS)	Necessary	104.00 F	*30.00 FL
37	1		*REAR FENDER INNER PANEL	Distorted	418.00 F	*418.00 FL
38	2		*REAR FENDER COWLING	Not Necessary	380.00 F	*- FL
39	12		*REAR FENDER COWLING CLIP	Not Necessary	78.00 F	*- FL
40	1		*REAR FENDER MUD SHIELD	N/S Torn	319.20 F	*65.00 FL
41	1		*REAR FENDER MUD SHIELD CLIP (16 PCS)	Necessary	104.00 F	*10.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR PETROL TANK	Not Necessary	1,216.00 F	*- FL
43	1		*REAR PETROL TANK COVER	Not Necessary	76.00 F	*- FL
44	1		*REAR PETROL TANK COVER LOCK CABLE	Not Necessary	114.00 F	*- FL
45	1		*REAR FLOOR PANEL	Repair	1,159.00 F	*- FL
46	1		*REAR FLOOR PANEL TOP COVER	Deformed	1,216.00 F	*525.00 FL
47	1		*REAR FLOOR PANEL INNER TRIM	Not Necessary	703.00 F	*- FL
48	1		*REAR EXHAUST	Not Necessary	1,330.00 F	*- FL
49	2		*REAR EXHAUST MOUNTING	Not Necessary	60.00 F	*- FL
50	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 FS	*- FS
51	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	1,330.00 FS	*- FS
52	1		*REAR BOOT LID VIDEO CAMERA	Not Necessary	950.00 FS	*- FS
53	1		*REAR BOOT LID TOP SPOILER	Not Necessary	2,736.00 FS	*- FS
54	1		*SET REAR BUMPER SIDE REFLECTOR	Cracked	480.00 FS	*60.00 FS
55	1		*SET REAR FENDER INNER TUBE LIGHT	Not Necessary	650.00 FS	*- FS
56	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
57	1		*REAR FLOOR PANEL CARPET	Not Necessary	850.00 FS	*- FS
58	1		*REAR TAIL LAMP INNER PANEL	Distorted	295.40 F	*295.40 FL
59	1		*REAR TAIL LAMP LOWER INNER PANEL	Distorted	206.90 F	*206.90 FL
60	1		*REAR L/H FENDER INNER PANEL	Repair	987.60 F	*- FL
61	1		*REAR END PANEL WIRE HARNESS	Snapped	255.90 F	*255.90 FL
62	1		*REAR L/H BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
63	1		*REAR END PANEL INNER	Buckled	562.40 F	*562.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	50,849.20	12,896.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,109.05
Total Parts (\$\$)	50,849.20	9,787.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT PETROL TANK	New	180.00	80.00
2	TO REMOVE & REFIT REAR VIDEO CAMERA	New	280.00	50.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
6	GUM	New	50.00	50.00
7	TO REMOVE & REFIT REAR L/H & R/H FENDER GLASS	New	240.00	60.00
8	GUM	New	100.00	20.00
9	TO REMOVE & REFIT REAR EXHAUST	New	280.00	0.00
10	TO REMOVE & INSTALL REAR FENDER TUBE LIGHT & REAR BUMPER SIDE REFLECTOR LIGHT	New	380.00	0.00
11	TO CHECK WIRING	New	120.00	30.00
12	TUFF KOTE	New	150.00	100.00
13	PANEL BEATING	New	3,000.00	1,600.00
14	SPRAY PAINTING	New	2,000.00	1,500.00
Gross Labour Cost (\$\$)			7,180.00	3,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >