

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009401/R1YF3E2

Date: 02/10/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00031022000
Claimant Vehicle No :	SKV5154K	Insured Vehicle No :	SLF3889J
Date of Loss:	01/09/2020	Nature of Claim:	TP
		Claim No:	SNM20D203173/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV5154K		
Make & Model:	NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)	Engine No:	HR16972782B
Reg. Date:	22/09/2015 (Man. Year: 2015)	Chassis No:	MNTBBAB17Z0024544
Colour:	Grey	Odometer:	76862 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,923.13	4,471.93	1,451.20	24.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	2,230.00	520.00	18.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,673.13	6,701.93	1,971.20	22.73
Approved Total (Overridden) (S\$)		5,350.00		
(S\$)	8,673.13	5,350.00	3,323.13	38.32
+ GST 7.00/7.00% (S\$)	607.12	374.50	232.62	38.32
Nett Amount (S\$)	9,280.25	5,724.50	3,555.75	38.32

INSPECTION

Date of Assignment: 03/09/2020
 Date Inspected: 04/09/2020 Inspected At:

Mova Automotive Pte Ltd (HQ)
 BLK 1008 BUKIT MERAH LANE 3 #01-
 04/06/08 .
 SINGAPORE 159722

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Oct 2020)

Parts: 143 NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV5154K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,263.00 FN	*1,263.00 FN
2	1		*BOOTLID LOGO	Necessary	59.70 FN	*59.70 FN
3	1		*BOOTLID EMBLEM - SYLPHY	Necessary	89.00 FN	*89.00 FN
4	1		*BOOTLID EMBLEM - PURE DRIVE (LIGHT BLUE)	Necessary	83.00 FN	*83.00 FN
5	1		*BOOTLID CHROME MOULDING TOP	Serviceable	185.00 FN	*- FN
6	1		*BOOTLID CHROME MOULDING BOTTOM	Serviceable	158.00 FN	*- FN
7	1		*BOOTLID LAMP LH	Serviceable	155.00 FN	*- FN
8	1		*BOOTLID HINGE LH	Serviceable	69.00 FN	*- FN
9	1		*BOOTLID HINGE RH	Serviceable	69.00 FN	*- FN
10	1		*BOOTLID LOCK	Bent	78.00 FN	*78.00 FN
11	1		*BOOTLID RUBBER	Necessary	89.00 FN	*89.00 FN
12	1		*TAILLAMP LH	Scratched	379.00 FN	*379.00 FN
13	1		*TAILLAMP PANEL LH	Repair	240.00 FN	*- FN
14	2		*TAILLAMP CLIPS	Necessary	16.00 FN	*16.00 FN
15	1		*REAR BUMPER	Deformed	690.00 FN	*690.00 FN
16	1		*REAR BUMPER REFLECTOR LH	Missing	65.00 FN	*65.00 FN
17	1		*REAR BUMPER REFLECTOR RH	Serviceable	65.00 FN	*- FN
18	10		*REAR BUMPER CLIPS	Necessary	50.00 FN	*50.00 FN
19	1		*REAR BUMPER SIDE RETAINER LH	Necessary	36.00 FN	*36.00 FN
20	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	36.00 FN	*- FN
21	1		*REAR BUMPER SPONGE CTR	Serviceable	45.00 FN	*- FN
22	1		*REAR BUMPER SPONGE LH	Cracked	85.00 FN	*85.00 FN
23	1		*REAR BUMPER SPONGE RH	Serviceable	85.00 FN	*- FN
24	1		*REAR BUMPER IMPACT DAMPER LH (METAL)	Bent	55.00 FN	*55.00 FN
25	1		*END PANEL TOP GARNISH	Deformed	98.00 FN	*98.00 FN
26	1		*END PANEL	Bent	468.00 FN	*468.00 FN
27	1		*REAR FENDER INNER TRIM LH	Deformed	471.00 FN	*471.00 FN
28	1		*REAR FENDER INNER TRIM RH	Deformed	471.00 FN	*471.00 FN
29	1		*SPARE TYRE TOP BOARD	Serviceable	411.00 FN	*- FN
30	1		*SPARE TYRE SPONGE	Deformed	162.00 FN	*162.00 FN
31	1		*FLOOR PANEL (NPA)	Repair	0.00 FN	*- FN
32	1		*REAR FENDER LH (NPA)	Repair	0.00 FN	*- FN
33	1		*REAR FENDER RH (NPA)	Repair	0.00 FN	*- FN
34	1		*REAR NUMBER PLATE	Scratched	40.00 FS	*35.00 FS
35	1		*REVERSE SENSOR	Cut	280.00 FS	*200.00 FS
36	1		*RR CHASSIS LH (NPA)	Repair	0.00 FN	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,545.70	4,942.70
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	622.57	470.77

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	5,923.13	4,471.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO INSPECT REAR LIGHTING MECHANISM	New	50.00	30.00
2	TO INSTALL REVERSE SENSOR & DIAGNOSE FUNCTION	New	80.00	60.00
3	TO TRANSFER REVERSE CAMERA & RESETTING	New	80.00	60.00
4	TO CUT OFF END PANEL, TO REPAIR ON REAR FENDER LH & RH & SPARE TYRE PANEL. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION	New	1,000.00	900.00
5	TO REMOVE & REFIT REAR COMPARTMENT FITTING	New	180.00	80.00
6	TO APPLY BODY JOINT SEALANT ON REPAIRED AREAS	New	80.00	40.00
7	TO RUST PROOF ON REPAIRED AREAS	New	80.00	60.00
8	TO SPRAY PAINT IN REPAIRED AREAS	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			2,750.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >