

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Sep 2020 16:02 Edit Reg		03 Sep 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: -, Co. Reg. No.: -									
Main Claimant: ANG JUN SIONG									
Vehicle Reg. No.: SMN5492C		Date of Loss: 01/09/2020 15:00 - :59 [12 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SHA5765T		Policy No. (Claimant):							
		Excess:							
Repairer: Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT, 415675 Kaki Bukit - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 14/09/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMN5492C
[SHA5765T]
TP
ANG JUN SIONG
Sep 1 2020 3:00PM
[-]
Xin Yun Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/20 20:56	General View	 Load JPG	
2	04/09/20 20:56	General View	 Load JPG	
3	04/09/20 20:56	General View	 Load JPG	
4	04/09/20 20:56	Odometer Reading	 Load JPG	
5	04/09/20 20:56	Chassis Number	 Load JPG	
6	04/09/20 20:56	General View	 Load JPG	
7	04/09/20 20:56	General View	 Load JPG	
8	04/09/20 20:56	General View	 Load JPG	
9	04/09/20 20:56	General View	 Load JPG	
10	04/09/20 20:56	General View	 Load JPG	
11	04/09/20 20:56	General View	 Load JPG	
12	04/09/20 20:56	General View	 Load JPG	
13	04/09/20 20:56	General View	 Load JPG	
14	04/09/20 20:56	General View	 Load JPG	
15	04/09/20 20:56	General View	 Load JPG	
16	04/09/20 20:56	General View	 Load JPG	
17	04/09/20 20:56	General View	 Load JPG	
18	04/09/20 20:56	General View	 Load JPG	
19	04/09/20 20:56	General View	 Load JPG	
20	04/09/20 20:56	General View	 Load JPG	
21	04/09/20 20:56	General View	 Load JPG	
22	04/09/20 20:56	General View	 Load JPG	
23	04/09/20 20:56	General View	 Load JPG	
24	04/09/20 20:56	General View	 Load JPG	
25	04/09/20 20:56	General View	 Load JPG	
26	04/09/20 20:56	General View	 Load JPG	
27	04/09/20 20:56	General View	 Load JPG	
28	04/09/20 20:56	General View	 Load JPG	
29	04/09/20 20:56	General View	 Load JPG	
30	04/09/20 20:56	General View	 Load JPG	
31	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
32	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
33	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
34	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
35	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
36	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
37	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
38	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
39	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	
40	04/09/20 20:57	Photographs of Damaged Parts	 Load JPG	

Photos/Images			3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
42	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
43	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
44	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
45	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
46	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
47	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
48	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
49	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
50	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
51	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
52	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
53	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
54	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
55	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
56	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
57	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
58	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
59	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
60	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
61	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
62	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
63	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
64	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
65	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
66	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
67	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
68	04/09/20 20:57	Photographs of Damaged Parts		Load JPG	☒
69	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
70	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
71	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
72	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
73	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
74	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
75	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
76	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
77	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
78	04/09/20 20:58	Photographs of Damaged Parts		Load JPG	☒
79	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
80	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
81	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
82	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
83	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
84	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
85	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
86	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
87	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
88	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
89	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
90	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
91	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
92	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒
93	08/09/20 19:31	Photographs of Damaged Parts		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
94	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
95	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
96	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
97	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
98	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
99	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
100	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
101	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
102	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
103	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
104	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
105	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
106	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
107	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
108	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
109	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
110	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
111	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
112	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
113	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
114	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
115	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
116	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
117	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
118	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
119	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
120	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
121	08/09/20 19:31	Photographs of Damaged Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/09/20 08:42	ASSIGNMENT FROM III	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/09/20 08:29	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20009410/EQF3S2**Date:** 16/09/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SMN5492C**Insured Vehicle No :** SHA5765T

Date of Loss: 01/09/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMN5492C**

Make & Model: HONDA FIT, 1.3 GF CVT (A)

Engine No: L13B3937036

Reg. Date: 16/08/2019 (Man. Year: 2019)

Chassis No: GK33422546

Colour: Blue

Odometer: 20341 km

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R14

Rear Tyre Size: 185/60 R14

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/09/2020

Date Inspected: 04/09/2020 Inspected At:

Xin Yun Auto Pte Ltd (HQ)
BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER
@KAKI BUKIT
Singapore 415675

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2020)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN5492C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >