



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102331

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/04/2021
Reference CC6/CTI20009413/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBE 7712H
Insured Veh. SJH 8992Z
Claim No. SNM20D203165
Policy No. DMPCSNW00078432001
Accident Date 31/08/2020
Inspection Date 03/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20009413/Kea3q2 Date: 08/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 8992Z	Veh. Inspected	GBE 7712H	
Policy No.	DMPCSNW00078432001	Coverage (\$)	0.00	
Claim No.	SNM20D203165	Excess (\$)	0.00	
Assign From		Assign Date	03/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFAT35Y60K206060	Colour	WHITE	
Odometer	197613 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	YOKOHAMA	3 mm	
L/H Front Tyre	195/75 R15	YOKOHAMA	3 mm	
R/H Rear Tyre	155 R12X8 (D)	WINDFORCE	2/2 mm	
L/H Rear Tyre	155 R12X8 (D)	WINDFORCE	2/2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/08/2020	Inspection Date	03/09/2020	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 7712H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	BENT	356.20	356.20
1	FRONT GRILE	MTG CRACKED	450.50	450.50
1	FRONT GRILE EMBLEM	NECESSARY	74.60	74.60
2	HEAD LAMPS @\$573.50	MTG CRACKED	1,147.00	1,147.00
1	FRONT PANEL	BENT	856.40	856.40
1	FRONT PANEL DYNA EMBLEM	NECESSARY	64.40	64.40
1	FRONT PANEL TOP GARNISH	CRACKED	328.50	328.50
1	FRONT WINDSCREEN GLASS (SN)	CRACKED	1,564.50	1,564.50
1	AIR-CON COOLING COIN	CRACKED	1,776.30	1,776.30
1	REAR NUMBER PLATE BRACKET	BENT	112.60	112.60
2	REAR NUMBER PLATE LAMPS @\$36.50	CRACKED	73.00	73.00
1	O/S TAIL LAMP BRAKET	BENT	78.80	78.80
1	O/S TAIL LAMP	CRACKED	227.70	227.70
2	TAIL GATE LOCK PIN @\$35.00	TO REPAIR SEE LABOUR	70.00	-
	LESS 25% DISCOUNT		-1,795.13	-1,777.63
			5,385.37	5,332.87
1	FRONT WINDSCREEN RUBBER (50%)	NECESSARY	369.40	184.70
	LESS 25% DISCOUNT		-92.35	-
			277.05	184.70
<u>SPECIAL NETT ITEMS</u>				
1	FRONT WINDSCREEN IU BRACKET (SN)	NECESSARY	25.00	25.00
1	FRONT PANEL CO'S LOGO STICKER (SN)	NECESSARY	380.00	200.00
1	FRONT NUMBER PLATE (SN)	DENTED	80.00	25.00
1	FRONT REAR SENSOR (SN)	TORN	200.00	200.00
1	70KM/H STICKER (SN)	NOT NECESSARY	20.00	-
2	POWER TAIL GATE HYDRAULIC PIPES @\$300.00 (SN)	PUNCTURE	600.00	600.00
4	POWER TAIL GATE HYDRAULIC CYLINDER @\$1200.00 (SN)	BENT	4,800.00	2,400.00

Report Ref No. CC6/CTI20009413/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HYDRAULIC OIL (50%) (SN)	NECESSARY	120.00	60.00
			6,225.00	3,510.00
	LABOUR			
	TO PUTTY & SPRAY PAINT .		700.00	600.00
	TO REPLACE REAR PANEL GATE HYDRAULIC PIPES & REPLACE AND REALIGHT REAR PANEL.		1,800.00	900.00
	TO REPLACE FRONT WINDSCREEN GLASS .		120.00	60.00
	TO REMOVE & REFIX FRONT ABSORBER ASSY ,REPAIR AIRCON COOLING COIL.}		350.00	100.00
	TO TOP UP GAS.}		80.00	-
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF TAIL GATE LOCK PIN .		800.00	600.00
			3,850.00	2,260.00
GRAND TOTAL			15,737.42	11,287.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,900.00

Report Ref No. CC6/CTI20009413/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 7712H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 7712H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 7712H

RE-INSPECTION

