



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2101125

INV Date 22/02/2021

Reference CC4/LPC20009415/Eba3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SDT 8141X
Insured Veh. YM 8518G
Claim No. 20/20/20/VC05/023616
Policy No. Z/20/VC05/005198-001
Accident Date 01/09/2020
Inspection Date 11/09/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20009415/Eba3q2 Date: 22/02/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 8518G	Veh. Inspected	SDT 8141X	
Policy No.	Z/20/VC05/005198-001	Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023616	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	03/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X4	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBAUJ12090LA94315	Colour	BLACK	
Odometer	21288 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R19	BRIDGESTONE	5 mm	
L/H Front Tyre	245/50 R19	BRIDGESTONE	5 mm	
R/H Rear Tyre	245/50 R19	BRIDGESTONE	5 mm	
L/H Rear Tyre	245/50 R19	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/09/2020	Inspection Date	11/09/2020	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			11 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDT 8141X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
8	PLASTIC NUT FOR COARSE THREADED PIN (SN)	NECESSARY	6.80	6.80
1	ALLOY RIM 7.5X18 Y SPEICHE 694 (SN)	NOT NECESSARY	1,214.55	-
1	REAR RH SIDE PANEL (SN)	DENTED	2,415.60	2,415.60
1	RH REINFORCEMENT PLATE SILL (SN)	BENT	53.75	53.75
1	RH REINFORCEMENT PLATE D PILLAR (SN)	BENT	53.75	53.75
1	RH REINFORCEMENT PLATE C PILLAR (SN)	BENT	53.75	53.75
1	POSITIONING AID T-BOLT (SN)	NOT NECESSARY	5.80	-
10	T WELD BOLT L=5.4MM (SN)	NOT NECESSARY	9.00	-
1	REAR RH DOOR (SN)	DENTED	1,538.20	1,538.20
1	REAR BUMPER RH SIDE GUIDE (SN)	BROKEN	102.85	102.85
1	BUMPER REAR PRIMED (SN)	NOT NECESSARY	1,555.40	-
1	REAR BUMPER TRIM PANEL BOTTOM (SN)	NOT NECESSARY	710.80	-
8	PLASTIC NUT (SN)	NECESSARY	6.80	6.80
1	REAR RH SIDE WINDOW FIXED (SN)	NECESSARY	384.65	384.65
1	REAR DOOR EDGE PROTECTION (SN)	NECESSARY	192.95	192.95
1	TRUNK LID GASKET (SN)	NECESSARY	170.20	170.20
1	REAR RH WHEEL ARCH TRIM (SN)	CUT	189.70	189.70
1	SET MOUNTING PDC /PMA SENSOR REAR (SN)	NOT NECESSARY	126.60	-
1	CAVITY PROTECTION WAX REMOVER 500ML (SN)	NOT NECESSARY	18.45	-
15	BLIND RIVET AVIBVLB (SN)	NECESSARY	8.25	8.25
3	SCREW (SF PLUS M5X15) (SN)	NECESSARY	1.65	1.65
1	(S/L) CLEANER R2 500ML (SN)	NECESSARY	14.80	14.80
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN)	NECESSARY	331.80	331.80
45	PUNCH RIVET N5 (SN)	NECESSARY (10 PCS ONLY)	23.65	5.50
1	(DG) BODYWORK ADHESIVE K5A (50ML) (SN)	NECESSARY	114.45	114.45
1	(DG) CLEANER R1 (100ML) (SN)	NECESSARY	26.15	26.15
10	PUNCH RIVET N4 (SN)	NECESSARY	5.50	5.50
1	(S/L) SEAM SEAL 300ML (SN)	NECESSARY	33.80	33.80
5	BLIND PLUG D=12MM (SN) (ADDITIONAL)	NECESSARY	5.00	5.00

Report Ref No. CC4/LPC20009415/Eba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
5	CLIP WITH WASHER NATUR (SN) (ADDITIONAL)	NECESSARY	10.00	10.00
5	EXPANDING NUT (SN) (ADDITIONAL)	NECESSARY	10.50	10.50
2	PLUG -IN RETAINER (SN) (ADDITIONAL)	NECESSARY	2.80	2.80
1	REAR BUMPER PANEL PRIMED (X LINE) (SN) (ADDITIONAL)	NECESSARY	1,555.40	1,555.40
1	CLIP UPPER PART (SN) (ADDITIONAL)	NECESSARY	1.55	1.55
1	CLIP,BOTTOM PART (SN) (ADDITIONAL)	NECESSARY	1.70	1.70
1	(S/L) DOOR WEATHERSTRIP (SN) (ADDITIONAL)	NECESSARY	160.25	160.25
			11,266.85	7,608.10
	LABOUR			
	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL). (ADDITIONAL)		451.00	451.00
	TO SUPPLY PAINT PROTECTION FILM ON REAR BUMPER ,REAR RIGHT DOOR ,RIGHT 'A' PILLAR . (BY OWNER). (ADDITIONAL)		2,030.00	2,030.00
	TO REPLACE BUMPER REAR COVER ,REAR RIGHT SIDE PANEL AND REAR RIGHT DOOR .		7,225.00	7,225.00
	TO SPRAY PAINT BUMPER REAR COVER ,REAR RIGHT SIDE PANEL ,ROOF FRAME RIGHT ,TAIL END PANEL ,RUNNING BOARD AND REAR RIGHT DOOR .		4,482.00	3,557.00
	TO REPLACE WHEEL RIM REAR RIGHT INCLUDING BALANCING .	NOT NECESSARY	94.00	-
	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION .	NOT NECESSARY	531.00	-
	TO REPLACE REAR RIGHT FIXED SIDE WINDOW GLASS .		398.00	398.00
	TO SUPPLY AND INSTALL REAR RIGHT WINDOW FIXED GLASS SOLAR FILM .	NOT NECESSARY	500.00	-
	TO CONDUCT WATER LEAK TESTS.		75.00	75.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION . (1 DOOR).		531.00	432.00
	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION .		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		236.00	106.00

Report Ref No. CC4/LPC20009415/Eba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .		177.00	150.00
			16,907.00	14,574.00
GRAND TOTAL			28,173.85	22,182.10
RECOMMENDED COST OF REPAIRS				22,182.10

Report Ref No. CC4/LPC20009415/Eba3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDT 8141X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDT 8141X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

