

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009417/BGS3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993767
Claimant Vehicle No :	SLU2336R	Insured Vehicle No :	SLA5455R
Date of Loss:	03/09/2020	Nature of Claim:	TP
		Claim No:	4297805060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU2336R	Engine No:	1NZR505471
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Chassis No:	NKE1657145318
Reg. Date:	27/11/2017 (Man. Year: 2017)	Odometer:	114525 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,208.54	1,532.07	3,676.47	70.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,130.00	1,500.00	57.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,838.54	2,662.07	5,176.47	66.04
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	7,838.54	2,100.00	5,738.54	73.21
+ GST 7.00/7.00% (S\$)	548.70	147.00	401.70	73.21
Nett Amount (S\$)	8,387.24	2,247.00	6,140.24	73.21
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,054.45		

INSPECTION

Date of Assignment:	03/09/2020		
Date Inspected:	04/09/2020	Inspected At:	160 SIN MING DRIVE#01-14
Estimated Period of Repair:	5.0 days		Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,058.00 FL	*- FL
2	1		*BOOTLID LOGO	Necessary	81.00 FL	*59.80 FL
3	1		*BOOTLID EMBLEM HYBRID	Necessary	140.00 FL	*59.80 FL
4	1		*BOOTLID INNER LOCK	Not Damaged	195.20 FL	*- FL
5	1		*BOOTLID INNER LOCK STICKER	Not Damaged	65.20 FL	*- FL
6	1		*BOOTLID WEATHERSTRIP	Not Damaged	298.50 FL	*- FL
7	1		*REAR BUMPER	Broken	995.95 FL	*780.00 FL
8	1		*REAR BUMPER SIDE RETAINER	O/S Broken	211.60 FL	*96.10 FL
9	1		*REAR BUMPER BRACKET	O/S Broken	250.20 FL	*91.70 FL
10	1		*REAR BUMPER REFLECTOR RH	Broken	283.10 FL	*62.70 FL
11	1		*TAILLAMP RH	Broken	684.80 FL	*546.00 FL
12	1		*TAILLAMP LOWER BRACKET RH	Not Necessary	98.70 FL	*- FL
13	1		*REAR END PANEL	Repair	620.40 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Damaged	258.60 FL	*- FL
15	1		*REAR FENDER INNER TRIM BOARD RH	Not Damaged	164.00 FL	*- FL
16	1		*REAR FENDER AIR VENT	Not Damaged	152.80 FL	*- FL
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
20	1		*TAILLAMP SEAL	Necessary	60.00 FS	*30.00 FS
21	1		*TAILLAMP CLIPS	No such part	50.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
25	2		*REVERSE SENSOR C/W MODULE	Scratched	500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,598.05	1,956.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,389.51	424.03
Total Parts (\$\$)	5,208.54	1,532.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BOOTLID COMPONENT	New	150.00	0.00
2	R&R REVERSE SENSOR	New	100.00	60.00
3	UPHOLSTERY	New	200.00	0.00
4	CHECK WIRING	New	80.00	30.00
5	PANEL BEAT	New	1,000.00	400.00
6	RUST PROOFING	New	100.00	40.00
7	SPRAY PAINTING	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,630.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >