

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20009421/T1VF3E2

**Date:** 08/09/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MG000389

**Claimant Vehicle No :** SHD4849B

**Insured Vehicle No :** SFL3311Z

Date of Loss: 02/09/2020

Nature of Claim: TP

Claim No: M2004325

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD4849B**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU408929

Reg. Date: 14/11/2019 (Man. Year: 2019)

Chassis No: KMHCH851CVLU189935

Colour: Blue

Odometer: 90462 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

### CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	896.22	760.52	135.70	15.14
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	780.00	550.00	230.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,687.22</b>	<b>1,321.52</b>	<b>365.70</b>	<b>21.67</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>118.11</b>	<b>92.51</b>	<b>25.60</b>	<b>21.67</b>
<b>Nett Amount (S\$)</b>	<b>1,805.33</b>	<b>1,414.03</b>	<b>391.30</b>	<b>21.67</b>

### INSPECTION

Date of Assignment: 07/09/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 03/09/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2020)
<b>Parts:</b>	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD4849B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		<b>*REAR BUMPER ASSY</b>	Deformed	499.40 FL	-	*499.40 FL
2	1		<b>*REAR BUMPER CENTRE MOULDING</b>	Deformed	451.25 FL	-	*451.25 FL
3	1		<b>*REVERSE SENSOR</b>	Not Necessary	135.70 F	-	*- FS
					<b>Sub Total (\$)</b>	<b>1,086.35</b>	<b>950.65</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	190.13	190.13
					<b>Total Parts (\$)</b>	<b>896.22</b>	<b>760.52</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>780.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >