

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20009422/EYF3E2

Date: 03/11/2020

REFERENCE

Insured/Claimant: HAYRER PTE LTD Policy No: Z20VC05004503
Date of Loss: 02/09/2020 Nature of Claim: OD Claim No: 20/20/20/VC05/023617

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE7767P**
Make & Model: MITSUBISHI FUSO, 12.0 D FV51SS3VDEA (M) Engine No: OM457LA457972C0331851
Reg. Date: 17/02/2017 (Man. Year: 2016) Chassis No: FV51SSA20064
Colour: White Odometer: 59398 km
Engine Capacity: 11967 cc
Market Value/New Car Price: S\$220,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5/5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,037.40	11,966.90	3,070.50	20.42
Miscellaneous Items	30.00	30.00	0.00	0.00
Labour	1,010.00	630.00	380.00	37.62
Paintwork Labour	820.00	700.00	120.00	14.63
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,897.40	13,326.90	3,570.50	21.13
Approved Total (Overridden) (S\$)		10,650.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	15,897.40	9,650.00	6,247.40	39.30
+ GST 7.00/7.00% (S\$)	1,112.82	675.50	437.32	39.30
Nett Amount (S\$)	17,010.22	10,325.50	6,684.72	39.30

INSPECTION

Date of Assignment: 04/09/2020 Present Location: Kan Fook Sing Motor Workshop (Defu)
Date Inspected: 04/09/2020 Inspected At: Kan Fook Sing Motor Workshop (Defu)
No. 61 Defu Lane 12
Singapore 539147

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Nov 2020)	
Parts:	N/A	MITSUBISHI FUSO 12.0 D FV51SS3VDEA (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE7767P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Dented	2,250.00 F	*2,250.00 F
2	1		*FRONT BONNET LOCK RH (WCP)	Not Necessary	90.00 F	*- F
3	1		*FRONT BONNET LOCK LH (WCP)	Not Necessary	90.00 F	*- F
4	1		*FRONT BONNET FUSO EMBLEM (WCP)	Necessary	120.00 F	*120.00 F
5	1		*FRONT GRILLE TOP (WCP)	Broken	300.00 F	*300.00 F
6	1		*FRONT GRILLE LOWER (WCP)	Broken	350.00 F	*350.00 F
7	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	65.00 F	*65.00 F
8	1		*FRONT GRILLE SUPER GREAT EMBLEM (WCP)	Necessary	85.00 F	*85.00 F
9	1		*FRONT CORNER PANEL RH (WCP)	Not Necessary	650.00 F	*- F
10	1		*FRONT CORNER PANEL LH (WCP)	Not Necessary	650.00 F	*- F
11	1		*FRONT BUMPER (WCP)	Dented	185.00 F	*185.00 F
12	1		*FRONT BUMPER TOP RH (WCP)	Broken	140.00 F	*140.00 F
13	1		*FRONT BUMPER TOP LH (WCP)	Bent	140.00 F	*140.00 F
14	1		*FRONT BUMPER (WCP)	Bent	1,500.00 F	*1,500.00 F
15	1		*FRONT BUMPER LOWER PANEL RH (WCP)	Broken	150.00 F	*150.00 F
16	1		*FRONT BUMPER LOWER PANEL LH (WCP)	Missing	150.00 F	*150.00 F
17	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	840.00 F	*840.00 F
18	1		*FRONT BUMPER BRACKET RH (WCP)	Bent	98.00 F	*98.00 F
19	1		*FRONT BUMPER BRACKET LH (WCP)	Bent	98.00 F	*98.00 F
20	1		*FRONT BUMPER CENTRE GARNISH (WCP)	Cut	120.00 F	*120.00 F
21	1		*FRONT BUMPER LAMP RH (WCP)	Cut	185.00 F	*185.00 F
22	1		*FRONT BUMPER LAMP LH (WCP)	Cut	185.00 F	*185.00 F
23	1		*FRONT BUMPER LAMP RIM RH (WCP)	Broken	90.00 F	*90.00 F
24	1			Cut	90.00 F	*90.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT BUMPER LAMP RIM LH (WCP)			
25	1		*FRONT HEADLAMP RH (WCP)	Cracked	650.00 F	*650.00 F
26	1		*FRONT HEADLAMP LH (WCP)	Cut	650.00 F	*650.00 F
27	1		*FRONT HEADLAMP RIM RH (WCP)	Crushed	95.00 F	*95.00 F
28	1		*FRONT HEADLAMP RIM LH (WCP)	Cut	95.00 F	*95.00 F
29	1		*AIR CON CONDENSER (WCP)	Not Necessary	1,190.00 F	*- F
<u>Supplementary #1</u>						
30	1		*FRONT HEADLAMP BRACKET RH (WCP)	Broken	450.00 F	*450.00 F
31	1		*FRONT HEADLAMP BRACKET LH (WCP)	Broken	450.00 F	*450.00 F
32	1		*FRONT STEP GARNISH TOP LH (WCP)	Broken	465.00 F	*465.00 F
33	1		*FRONT STEP GARNISH CENTRE LH (WCP)	Broken	220.00 F	*220.00 F
34	2		*HORN (WCP)	Bent	190.00 F	*190.00 F

F=Franchise part.

Sub Total (S\$)	13,076.00	10,406.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,961.40	1,560.90
Total Parts (S\$)	15,037.40	11,966.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (BENT)	30.00	30.00
Sub Total (S\$)			30.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	820.00	700.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	30.00	30.00
3	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00	0.00
4	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	900.00	600.00
Gross Labour Cost (S\$)			1,830.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >