

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER RH <i>Dented</i>	1	\$ 398.20	\$ 398.20
2	FRONT FENDER EMBLEM 'HYBRID' RH <i>new</i>	1	\$ 58.40	\$ 58.40
3	FRONT FENDER INNER COWLING RH <i>Dented</i>	1	\$ 115.90	\$ 115.90
4	FRONT WHEEL CAP RH <i>cut</i>	1	\$ 186.40	\$ 186.40
5	FRONT ABS SENSOR RH <i>new</i>	1	\$ 265.80	\$ 265.80
6	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 1,680.40	\$ 1,680.40
7	FRONT DRIVESHAFT RH <i>new</i>	1	\$ 1,350.90	\$ 1,350.90
8	FRONT LOWER ARM RH <i>Best</i>	1	\$ 285.70	\$ 285.70
9	FRONT KNUCKLE ARM RH <i>Dented</i>	1	\$ 330.60	\$ 330.60
10	FRONT KNUCKLE ARM BEARING RH <i>new</i>	1	\$ 168.90	\$ 168.90
11	FRONT SHOCK ABSORBER RH <i>Best</i>	1	\$ 420.70	\$ 420.70
12	FRONT WHEEL HUP RH <i>Dented</i>	1	\$ 138.40	\$ 138.40
13	FRONT LINKAGE RH <i>new</i>	1	\$ 87.10	\$ 87.10
14	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 169.60	\$ 169.60
15	SIDE SKIRT RH <i>Repis</i>	1	\$ 393.20	\$ 393.20
16	FRONT DOOR SIDE MIRROR RH <i>cracked</i>	1	\$ 754.30	\$ 754.30
17	FRONT DOOR RH <i>Distorted</i>	1	\$ 1,267.80	\$ 1,267.80
18	FRONT DOOR OUTER HANDLE RH <i>new</i>	1	\$ 386.20	\$ 386.20
19	FRONT DOOR HINGE RH <i>Best</i>	2	\$ 49.80	\$ 99.60
20	FRONT DOOR CHECKER RH <i>new</i>	1	\$ 106.40	\$ 106.40
21	FRONT DOOR GLASS CHANNEL RH <i>new</i>	1	\$ 84.30	\$ 84.30
22	FRONT DOOR GLASS FRAME BLACK STICKER RH <i>new</i>	2	\$ 98.90	\$ 197.80
23	FRONT DOOR GLASS RH <i>new</i>	1	\$ 468.70	\$ 468.70
24	FRONT DOOR WEATHER STRIP RH <i>lt</i>	1	\$ 89.40	\$ 89.40
25	FRONT DOOR INNER LOCK RH <i>Damaged</i>	1	\$ 297.50	\$ 297.50
26	FRONT DOOR FRAME WEATHER STRIP RH <i>new</i>	1	\$ 167.40	\$ 167.40
27	FRONT DOOR OUTER STRIP RH <i>new</i>	1	\$ 96.70	\$ 96.70

TO	:	CHINA TAIPING	MOTOR CLAIMS DEPTS
VEHICLE NO	:	SME347U	
MODEL	:	HONDA SHUTTLE	
DATE OF ACCIDENT	:	03.09.20	
TIME OF ACCIDENT	:	12:10HRS	

28	FRONT DOOR LOCK CATCH RH <i>Neu</i>	1	\$ 20.10	\$ 20.10
29	FRONT DOOR INNER TRIM BOARD RH <i>Good</i>	1	\$ 649.80	\$ 649.80
30	FRONT DOOR REGULATOR RH <i>Damaged</i>	1	\$ 353.50	\$ 353.50
31	FRONT DOOR POWER WINDOW MOTOR RH <i>Neu</i>	1	\$ 459.60	\$ 459.60
32	FRONT DOOR OUTER KEY LOCK RH <i>?</i>	1	\$ 168.70	\$ 168.70
33	FRONT DOOR SPEAKER RH <i>Neu</i>	1	\$ 197.60	\$ 197.60
34	FRONT DOOR STOPPER RH <i>in</i>	2	\$ 18.90	\$ 37.80
35	FRONT DOOR STEP INNER GARNISH RH <i>Neu</i>	1	\$ 101.70	\$ 101.70
36	FRONT DOOR PILLAR INNER GARNISH (LOWER) RH <i>Neu</i>	1	\$ 323.60	\$ 323.60
37	FRONT DOOR PILLAR (OUTER) RH <i>Regis</i>	1	\$ 986.40	\$ 986.40
38	FRONT DOOR PILLAR QUARTER GLASS C/W MOULDING <i>Neu</i>	1	\$ 395.60	\$ 395.60
39	CENTER PILLAR RH (OUTER) <i>3 Regis Dented</i>	1	\$ 787.50	\$ 787.50
40	CENTER PILLAR RH (INNER) <i>Regis</i>	1	\$ 694.60	\$ 694.60
41	REAR DOOR RH <i>Distorted</i>	1	\$ 986.70	\$ 986.70
42	REAR DOOR GLASS CHANNEL RH <i>Best</i>	1	\$ 82.40	\$ 82.40
43	REAR DOOR POWER WINDOW MOTOR RH <i>Neu</i>	1	\$ 598.70	\$ 598.70
44	REAR DOOR FRAME WEATHERSTRIP RH <i>Neu</i>	1	\$ 176.40	\$ 176.40
45	REAR DOOR INNER LOCK RH <i>Damaged</i>	1	\$ 264.70	\$ 264.70
46	REAR DOOR INNER TRIM RH <i>Good</i>	1	\$ 765.80	\$ 765.80
47	REAR DOOR WEATHERSTRIP RH <i>at</i>	1	\$ 184.80	\$ 184.80
48	REAR DOOR OUTER MOULDING RH <i>Dented</i>	1	\$ 127.10	\$ 127.10
49	REAR DOOR GLASS SIDE GARNISH RH <i>Neu</i>	1	\$ 98.70	\$ 98.70
50	REAR DOOR HINGE RH <i>Best</i>	2	\$ 49.80	\$ 99.60
51	REAR DOOR CHECKER RH <i>Neu</i>	1	\$ 106.40	\$ 106.40
52	REAR DOOR FRONT WEATHER STRIP RH <i>Neu</i>	1	\$ 158.60	\$ 158.60
53	REAR DOOR LOCK CATCH RH <i>Neu</i>	1	\$ 20.10	\$ 20.10
54	REAR DOOR SPEAKER RH <i>Neu</i>	1	\$ 197.60	\$ 197.60
55	REAR DOOR GLASS REGULATOR GEAR RH <i>Damaged</i>	1	\$ 353.10	\$ 353.10
56	REAR DOOR GLASS RH <i>Neu</i>	1	\$ 459.30	\$ 459.30
57	REAR DOOR OUTER HANDLE RH <i>Damaged</i>	1	\$ 351.20	\$ 351.20
58	REAR FENDER RH <i>Dented</i>	1	\$ 1,010.20	\$ 1,010.20
59	REAR FENDER COWLING RH <i>Neu</i>	1	\$ 197.90	\$ 197.90
60	REAR FENDER INNER TRIM RH <i>Neu</i>	1	\$ 399.60	\$ 399.60
61	REAR FENDER INNER PANEL RH <i>Regis</i>	1	\$ 485.00	\$ 485.00
62	REAR WHEEL HOUSE INSULATOR MATT RH <i>Neu</i>	1	\$ 296.70	\$ 296.70
63	REAR QUATER GLASS C/W MOULDING RH <i>Neu</i>	1	\$ 652.40	\$ 652.40

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SME347U
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 03.09.20
 TIME OF ACCIDENT : 12:10HRS

64	REAR WHEEL CAP RH <i>ut</i>	1	\$ 186.40	\$ 186.40	<i>100(SN)</i>
65	REAR ABS SENSOR RH	1	\$ 265.40	\$ 265.40	+
66	REAR AXLE	1	\$ 1,080.60	\$ 1,080.60	+
67	REAR WHEEL HUB C/W BEARING RH <i>2</i>	1	\$ 371.40	\$ 371.40	+
68	REAR SHOCK ABSORBER RH	1	\$ 350.60	\$ 350.60	+
69	REAR BUMPER <i>Repair</i>	1	\$ 1,150.60	\$ 1,150.60	+
70	REAR BUMPER REFLECTOR GARNISH RH <i>new</i>	1	\$ 45.00	\$ 45.00	+
71	REAR BUMPER INNER SPONGE <i>2 new</i>	1	\$ 65.70	\$ 65.70	+
72	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 37.40	\$ 74.80	+

S-N-280 9676-20
 7740-96

TOTAL PRICE \$ 26,906.30
 LESS 20% \$ 5,381.26
SUB TOTAL PRICE \$ 21,525.04

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
2	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	FRONT DOOR PILLAR (OUTER) SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	FRONT DOOR PILLAR INNER GARNISH (LOWER) CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	FRONT DOOR PILLAR QUARTER GLASS SEALANT RH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
6	FRONT DOOR PILLAR QUARTER GLASS INNER SHIELD RH <i>new</i>	1	\$ 40.00	\$ 40.00	+
7	FRONT DOOR PILLAR QUARTER GLASS SOLAR FILM RH <i>new</i>	1	\$ 80.00	\$ 80.00	+
8	FRONT DOOR TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
9	FRONT DOOR GLASS SOLAR FILM RH <i>new</i>	1	\$ 250.00	\$ 250.00	+
10	FRONT WHEEL RIM RH <i>ut</i>	1	\$ 250.00	\$ 250.00	<i>180(SN)</i>
11	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 480.00	\$ 480.00	+
12	FRONT WINDSCREEN SEALANT <i>2</i>	1	\$ 80.00	\$ 80.00	+
13	FRONT WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	+
14	REAR DOOR GLASS SOLAR FILM RH <i>new</i>	1	\$ 250.00	\$ 250.00	+
15	REAR FENDER SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00	+
16	REAR WHEEL HOUSE INSULATOR MATT CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
17	REAR FENDER GLASS SEALANT LH <i>new</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
18	REAR FENDER GLASS INNER SEAL LH <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
19	REAR FENDER GLASS SOLAR FILM LH <i>new</i>	1	\$ 250.00	\$ 250.00	+
20	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
21	REAR WHEEL RIM RH <i>2</i>	1	\$ 250.00	\$ 250.00	+
22	REAR WHEEL TYRE LH <i>new</i>	1	\$ 480.00	\$ 480.00	+
23	POWER STEERING OIL <i>new</i>	1	\$ 180.00	\$ 180.00	+

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SME347U
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 03.09.20
 TIME OF ACCIDENT : 12:10HRS

24	BRAKE OIL <i>ble m</i>	1	\$ 40.00	\$ 40.00
----	------------------------	---	----------	----------

330 TOTAL \$ 3,570.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 3,500.00	<i>1400.</i>
2	TO SPRAY PAINT	\$ 2,600.00	<i>1200.</i>
3	TUFF COAT	\$ 250.00	<i>80.</i>
4	WIRING, BULB CHECKING	\$ 80.00	<i>30.</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 450.00	<i>100.</i>
6	REMOVE & REFIX FRONT WINDSCREEN	\$ 120.00	<i>x</i>
7	REMOVE AND REFIX FRONT DOOR PILLAR QUARTER GLASS RH	\$ 80.00	<i>60.</i>
8	TRANSFER FRONT DOOR MECHANISM RH	\$ 80.00	<i>✓</i>
9	REMOVE & REFIX FRONT DOOR AUDIO SPEAKER	\$ 120.00	<i>x</i>
10	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>220</i>
11	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80.</i>
12	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	<i>x</i>
13	TRANSFER REAR DOOR MECHANISM	\$ 80.00	<i>✓</i>
14	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>x</i>
15	REMOVE AND REFIX REAR FENDER GLASS	\$ 100.00	<i>60.</i>
16	CONDUCT WATER LEAKAGE TEST	\$ 150.00	<i>x</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SME347U
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 03.09.20
 TIME OF ACCIDENT : 12:10HRS

17	RESET ABS LIGHT	\$ 350.00	X
18	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 550.00	X

TOTAL \$ 10,280.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 25,095.04
 TOTAL LABOUR COST : \$ 10,280.00
 TOTAL REPAIR COST : \$ 35,375.04

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
 CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
 ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian L
 L/S 07/09/20
 10 days.

total: 11740.96
 L/S: 93k.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: