

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20009458/APS3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLK9090E	<b>Insured Vehicle No :</b>	SH8395R
Date of Loss: 04/09/2020	Nature of Claim: TP	Claim No: MCT20090041

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9090E		
Make & Model:	NISSAN TEANA, 2.0 (A)	Engine No:	MR20043020R
Reg. Date:	22/11/2016 (Man. Year: 2016)	Chassis No:	MNTBBAL33Z0005945
Colour:	White	Odometer:	44896 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,120.80	1,885.20	235.60	11.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,358.00	1,328.00	1,030.00	43.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,478.80</b>	<b>3,213.20</b>	<b>1,265.60</b>	<b>28.26</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>313.52</b>	<b>224.92</b>	<b>88.60</b>	<b>28.26</b>
<b>Nett Amount (S\$)</b>	<b>4,792.32</b>	<b>3,438.12</b>	<b>1,354.20</b>	<b>28.26</b>
<b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b>		<b>400.00</b>		
	<b>Nett Liability (S\$)</b>	<b>3,838.12</b>		

### INSPECTION

Date of Assignment:	04/09/2020	
Date Inspected:	08/09/2020	Inspected At:
		Autolution Industrial Pte Ltd (Ubi)
		19 Ubi Road 4
		Singapore 408623
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Oct 2020)
<b>Parts:</b>	143	NISSAN TEANA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK9090E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP	Cut	459.10 FN	*459.10 FN
2	1		*FRT LH FENDER WHEELHOUSE PROTECTOR	Deformed	119.70 FN	*119.70 FN
3	1		*FRT LH FENDER SEAL	Not Necessary	197.20 FN	*- FN
4	1		*FRT LH FENDER STAY	Not Necessary	59.80 FN	*- FN
5	1		*FRT LH FENDER	Buckled	680.00 FN	*680.00 FN
6	1		*STIFFENER LH SIDE FRT BUMPER	Necessary	65.00 FN	*65.00 FN
7	1		*LH SIDE BRACKET RETAINER FRT BUMPER	Necessary	23.40 FN	*23.40 FN
8	1		*FRONT BUMPER	Deformed	984.30 FN	*984.30 FN
9	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					<b>Sub Total (\$\$)</b>	<b>2,638.50 2,351.50</b>
					<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	<b>517.70 466.30</b>
					<b>Total Parts (\$\$)</b>	<b>2,120.80 1,885.20</b>

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR LH SIDE RADIATOR SUPPORT RENEW FRT LH FENDER AND FRONT BUMPER	New	1,560.00	780.00
2	CHARGES TO SPRAY PAINTING SAME	New	750.00	500.00
3	RENEW LH HEADLAMP AND FOCUS	New	48.00	48.00
<b>Gross Labour Cost (S\$)</b>			<b>2,358.00</b>	<b>1,328.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >