

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Sep 2020		04 Sep 2020 17:50 Edit Adj Rpt	S\$5,522.04 Edit Estimates	S\$5,522.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	WANG DINGXIANG , ID: S26719731								
Vehicle Reg. No.:	SKS2528B	Date of Loss:	02/09/2020 14:00 - :59 [65 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D203176/C02/LOWCT	Policy/Cover Note No.:	DMCVSNW00002381900						
Vehicle Reg. No. (Insured):	YP1200C	Policy No. (Claimant):	MS/00779930						
		Excess:	S\$0.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/09/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐ View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKS2528B (SNM20D203176/C02/LOWCT)**
[YP1200C]

TP
WANG DINGXIANG
Sep 2 2020 2:00PM

[-]
Cycle & Carriage Industries Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/20 10:56	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/20 08:21	Odometer Reading	Load JPG	
2	09/09/20 08:21	Chassis Number	Load JPG	
3	09/09/20 08:21	General View	Load JPG	
4	09/09/20 08:21	General View	Load JPG	
5	09/09/20 08:21	General View	Load JPG	
6	09/09/20 08:21	General View	Load JPG	
7	09/09/20 08:21	General View	Load JPG	
8	09/09/20 08:21	General View	Load JPG	
9	09/09/20 08:21	General View	Load JPG	
10	09/09/20 08:21	General View	Load JPG	
11	09/09/20 08:21	General View	Load JPG	
12	09/09/20 08:21	General View	Load JPG	
13	09/09/20 08:21	General View	Load JPG	
14	09/09/20 08:21	General View	Load JPG	
15	09/09/20 08:21	General View	Load JPG	
16	09/09/20 08:21	General View	Load JPG	
17	09/09/20 08:21	General View	Load JPG	
18	09/09/20 08:21	General View	Load JPG	
19	09/09/20 08:21	General View	Load JPG	
20	09/09/20 08:21	General View	Load JPG	
21	09/09/20 08:21	General View	Load JPG	
22	09/09/20 08:21	General View	Load JPG	
23	09/09/20 08:21	General View	Load JPG	
24	09/09/20 08:21	General View	Load JPG	
25	09/09/20 08:21	General View	Load JPG	
26	09/09/20 08:21	General View	Load JPG	
27	09/09/20 08:21	General View	Load JPG	
28	09/09/20 08:21	General View	Load JPG	
29	09/09/20 08:21	General View	Load JPG	
30	09/09/20 08:21	General View	Load JPG	
31	09/09/20 08:21	General View	Load JPG	
32	09/09/20 08:21	General View	Load JPG	
33	09/09/20 08:21	General View	Load JPG	
34	09/09/20 08:21	General View	Load JPG	
35	09/09/20 08:21	General View	Load JPG	
36	09/09/20 08:21	General View	Load JPG	
37	09/09/20 08:21	General View	Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	09/09/20 08:21	General View	Load JPG	☒
39	09/09/20 08:21	General View	Load JPG	☒
40	09/09/20 08:21	General View	Load JPG	☒
41	09/09/20 08:21	General View	Load JPG	☒
42	09/09/20 08:21	General View	Load JPG	☒
43	09/09/20 08:21	General View	Load JPG	☒
44	09/09/20 08:21	General View	Load JPG	☒
45	09/09/20 08:21	General View	Load JPG	☒
46	09/09/20 08:21	General View	Load JPG	☒
47	05/10/20 17:17	Reinspection Photo	Load JPG	☒
48	05/10/20 17:17	Reinspection Photo	Load JPG	☒
49	05/10/20 17:17	Reinspection Photo	Load JPG	☒
50	05/10/20 17:17	Reinspection Photo	Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	02/09/20 17:57	Accident Statement	Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	02/09/20 17:55	Accident Photo	Load JPG	☒
2	02/09/20 17:55	Accident Photo	Load JPG	☒
3	02/09/20 17:55	Accident Photo	Load JPG	☒
4	02/09/20 17:55	Accident Photo	Load JPG	☒
5	02/09/20 17:55	Accident Photo	Load JPG	☒
6	02/09/20 17:55	Accident Photo	Load JPG	☒
7	02/09/20 17:55	Accident Photo	Load JPG	☒
8	02/09/20 17:56	Accident Photo	Load JPG	☒
9	02/09/20 17:56	Accident Photo	Load JPG	☒
10	02/09/20 17:56	Accident Photo	Load JPG	☒
11	02/09/20 17:56	Accident Photo	Load JPG	☒
12	02/09/20 17:56	Accident Photo	Load JPG	☒
13	02/09/20 17:56	Accident Photo	Load JPG	☒
14	02/09/20 17:56	Accident Photo	Load JPG	☒
15	02/09/20 17:56	Accident Photo	Load JPG	☒

Documentation			1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	02/09/20 17:55	Accident Sketch Plan	Load JPG	☒
2	02/09/20 17:55	Accident Sketch Plan	Load JPG	☒
3	02/09/20 17:55	Accident Sketch Plan	Load JPG	☒
4	02/09/20 17:55	Driving License	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20009482/R1VF3S2**Date:** 06/10/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00002381900

Claimant Vehicle No : SKS2528B **Insured Vehicle No :** YP1200C

Date of Loss: 02/09/2020 Nature of Claim: TP Claim No: SNM20D203176/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS2528B**

Make & Model: MERCEDES-BENZ A180, 1.6 (A) Engine No: 27091030606556

Reg. Date: 01/04/2015 (Man. Year: 2015) Chassis No: WDD1760422J360902

Colour: Black Odometer: 153354 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,267.54	1,622.04	645.50	28.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,860.00	3,900.00	1,960.00	33.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,127.54	5,522.04	2,605.50	32.06
+ GST 7.00/7.00% (S\$)	568.93	386.54	182.39	32.06
Nett Amount (S\$)	8,696.47	5,908.58	2,787.89	32.06

INSPECTION

Date of Assignment: 04/09/2020

Date Inspected: 08/09/2020 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Oct 2020)	
Parts:	N/A	MERCEDES-BENZ A180 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS2528B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSHEILD	Broken	672.17 FS	*672.17 FS
2	12		*FRT WINDSHIELD PAD	Necessary	62.52 FS	*62.52 FS
3	2		*GLAZING REPAIR KIT	Necessary	313.66 FS	*313.66 FS
4	1		*LEFT ROOF MOULDING	Serviceable	322.75 FS	*- FS
5	1		*RIGHT ROOF MOULDING	Serviceable	322.75 FS	*- FS
6	1		*WIPER BLADE	Missing	123.50 FS	*123.50 FS
7	1		*LEFT WIPER ARM	Scratched	150.19 FS	*150.19 FS
8	1		*FRONT WINDSHIELD SOLAR FILM	Necessary	300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,267.54	1,622.04
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.	New	380.00	380.00
2	RENEW FRONT WINDSHIELD.	New	560.00	560.00
3	REMOVE, REPAIR & INSTALL FRONT BUMPER, FRONT BONNET, ROOF PANEL & SUPPORT ASSY FROM VEHICLE FRAME.	New	1,920.00	960.00
4	RESPRAY FRONT BUMPER, FRONT BONNET, ROOF PANEL, LEFT A PILLAR & RIGHT A PILLAR.	New	3,000.00	2,000.00
Gross Labour Cost (\$\$)			5,860.00	3,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >