

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20009486/R1QF3E2

**Date:** 15/09/2020

### REFERENCE

|  |                             |                        |
|--|-----------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100379165             |
| <b>Claimant Vehicle No :</b> SLK5282U                  | <b>Insured Vehicle No :</b> | GBD1561X               |
| Date of Loss: 02/09/2020                               | Nature of Claim: TP         | Claim No: 0253426446SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SLK5282U                          | Engine No:  | K24W72012841      |
| Make & Model:               | HONDA ODYSSEY, 2.4 EX-S (A)       | Chassis No: | JHMRC1880GC206718 |
| Reg. Date:                  | 19/01/2017 (Man. Year: 2016)      | Odometer:   | 109691 km         |
| Colour:                     | Gold                              |             |                   |
| Engine Capacity:            | 2356 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 215/55 R17 | Rear Tyre Size:  | 215/55 R17 |
| Front Left Side:  | Giti 6 mm  | Rear Left Side:  | Giti 6 mm  |
| Front Right Side: | Giti 6 mm  | Rear Right Side: | Giti 6 mm  |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |            |   |
|-----------------------------|------------|---|
| Date of Assignment:         | 07/09/2020 |   |
| Date Inspected:             | 07/09/2020 | Inspected At: Sincerelead Garage Pte Ltd - Buroh (HQ)<br>2 Buroh Crescent, #02-09 Ace@Buroh<br>Singapore 627546 |
| Estimated Period of Repair: | 8.0 days   |   |

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition   | Repairer's | Amount |
|-----|-----|----------|-------------------------------|-------------|------------|--------|
| 1   | 1   |          | *REAR BUMPER                  | Deformed    | 0.00 F     | *- F   |
| 2   | 1   |          | *REAR BUMPER SIDE RH          | Deformed    | 0.00 F     | *- F   |
| 3   | 1   |          | *REAR BUMPER CLIPS            | Necessary   | 0.00 F     | *- F   |
| 4   | 1   |          | *REAR BUMPER BRACKET RH       | Necessary   | 0.00 F     | *- F   |
| 5   | 1   |          | *REAR BUMPER SIDE RETAINER RH | Cracked     | 0.00 F     | *- F   |
| 6   | 1   |          | *REAR BUMPER REFLECTOR RH     | Cracked     | 0.00 F     | *- F   |
| 7   | 1   |          | *REVERSE SENSOR               | Not Working | 0.00 F     | *- F   |
| 8   | 1   |          | *REAR END PANEL               | Bent        | 0.00 F     | *- F   |
| 9   | 1   |          | *REAR END PANEL TOP GARNISH   | Deformed    | 0.00 F     | *- F   |
| 10  | 1   |          | *REAR END PANEL INNER TRIM    | Deformed    | 0.00 F     | *- F   |
| 11  | 1   |          | *TAILGATE                     | Buckled     | 0.00 F     | *- F   |
| 12  | 1   |          | *TAILGATE EMBLEM              | Necessary   | 0.00 F     | *- F   |
| 13  | 1   |          | *TAILGATE INNER HANDLE        | Deformed    | 0.00 F     | *- F   |
| 14  | 1   |          | *TAILGATE REFLECTOR           | Cracked     | 0.00 F     | *- F   |
| 15  | 1   |          | *TAILGATE LAMP RH             | Cracked     | 0.00 F     | *- F   |
| 16  | 1   |          | *TAILGATE GLASS               | Broken      | 0.00 F     | *- F   |
| 17  | 1   |          | *TAILGATE GLASS MOULDING      | Necessary   | 0.00 F     | *- F   |
| 18  | 1   |          | *TAILGATE GLASS SEALANT       | Necessary   | 0.00 F     | *- F   |
| 19  | 1   |          | *TAILGATE LOCK                | Bent        | 0.00 F     | *- F   |
| 20  | 1   |          | *TAILGATE RUBBER              | Necessary   | 0.00 F     | *- F   |
| 21  | 1   |          | *TAILGATE INNER BOARD         | Cracked     | 0.00 F     | *- F   |
| 22  | 1   |          | *SPARE TYRE PANEL             | Buckled     | 0.00 F     | *- F   |
| 23  | 1   |          | *REAR RH CHASSIS MEMBER       | Repair      | 0.00 F     | *- F   |
| 24  | 1   |          | *REAR RH FENDER INNER TRIM    | Cracked     | 0.00 F     | *- F   |
| 25  | 1   |          | *AIR-CON BLOWER               | Cracked     | 0.00 F     | *- F   |
| 26  | 1   |          | *TAILGATE CHROME MOULDING     | Cracked     | 0.00 F     | *- F   |
| 27  | 1   |          | *REAR RH TAILLAMP             | Cracked     | 0.00 F     | *- F   |

F=Franchise part.

**Total Parts (S\$)****0.00****0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

**< END OF ESTIMATES >**