

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20009487/R1ES3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900140058

Claimant
Vehicle No : SMH6683T **Insured Vehicle No :** SLH429M

Date of Loss: 02/09/2020 Nature of Claim: TP Claim No: 6866872829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH6683T	Engine No:	CHH254490
Make & Model:	VOLKSWAGEN PASSAT VARIANT, 2.0 (A)	Chassis No:	WVWZZZ3CZJE247040
Reg. Date:	29/01/2019 (Man. Year: 2018)	Odometer:	21370 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R19	Rear Tyre Size:	225/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	55,862.00	49,796.64	6,065.36	10.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	33,235.00	18,255.00	14,980.00	45.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	89,097.00	68,051.64	21,045.36	23.62
+ GST 7.00/7.00% (S\$)	6,236.79	4,763.61	1,473.18	23.62
Nett Amount (S\$)	95,333.79	72,815.25	22,518.54	23.62
+ Loss of Use (29.0 x S\$100.00/day) (S\$)		2,900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		75,717.25		

INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 07/09/2020 Inspected At: Volkswagen Group Singapore Pte Ltd
NO 17 TUAS AVE 9
SINGAPORE 639197

Estimated Period of Repair: 22.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$136,000

LTA REBATE: \$64,549

NETT VALUE:\$71,451

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DASHBOARD TITANIUM BLACK	Torn	4,110.44 FS	*4,110.44 FS
2	1		*DASH PANEL TRIM BLACK-GLO: AIR VENT (LH)	Cracked	571.15 FS	*571.15 FS
3	1		*AIRBAG UNIT: AIRBAG (PASSENGER)	Activated	2,793.94 FS	*2,793.94 FS
4	1		*AIRBAG UNIT FOR STEERING	Activated	3,464.67 FS	*3,464.67 FS
5	1		*CONTROL UNIT FOR STEERING: S/WHEEL SPRING CLOCK	Activated	749.33 FS	*749.33 FS
6	1		*MULT STEERING WHEEL	Deformed	2,006.76 FS	*2,006.76 FS
7	1		*THREE-POINT AUTOMATIC SEA: SEAT BELT LH	Activated	740.28 FS	*740.28 FS
8	1		*SEAT BELT HEIGHT ADJUSTER 2pcs	Jammed 1pc Only	188.70 FS	*94.35 FS
9	1		*THREE-POINT AUTOMATIC SEA: SEAT BELT RH	Activated	740.28 FS	*740.28 FS
10	1		*AIR BAG CONTROL MODULE	Activated	1,637.79 FS	*1,637.79 FS
11	1		*LINING PILLAR A WHITE ST: A-PILLAR TRIM LH	Deformed	119.57 FS	*119.57 FS
12	2		*CLAMP	Necessary	6.58 FS	*6.58 FS
13	1		*WINDSHIELD GLASS: FRT WINDSCREEN	Broken	1,182.81 FS	*1,182.81 FS
14	1		*RETAINING PLATE FOR REAR	Necessary	8.97 FS	*8.97 FS
15	1		*ERP STICKER	Necessary	9.81 FS	*9.81 FS
16	2		*1K WINDOW ADHESIVE	Necessary	99.02 FS	*99.02 FS
17	1		*ALL PURPOSE CLEANER	Necessary	89.22 FS	*89.22 FS
18	1		*PRIMER	Necessary	25.74 FS	*25.74 FS
19	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.77 FS	*23.77 FS
20	2		*APPLICATOR	Necessary	18.78 FS	*18.78 FS
21	1		*HOOD: FRT BONNET	Bent	1,495.85 FS	*1,495.85 FS
22	1		*HOOD SILENCER: BONNET INSULATOR	Deformed	196.33 FS	*196.33 FS
23	1		*FLAP HINGE: LH	Bent	97.91 FS	*97.91 FS
24	1		*FLAP HINGE: RH	Bent	97.91 FS	*97.91 FS
25	1		*LOCKING CATCH: LATCH	Bent	75.07 FS	*75.07 FS
26	1		*HOOD LATCH: LOCK	Bent	255.59 FS	*255.59 FS
27	2		*HEXAGON SOCKET OVAL HEAD	Necessary	4.74 FS	*4.74 FS
28	1		*COVER FOR BUMPER PRIMED	Torn	1,634.49 FS	*1,634.49 FS
29	1		*FOAM INSERT	Cracked	108.36 FS	*108.36 FS
30	1		*IMPACT BEAM: REINFORCEMENT	Bent	602.22 FS	*602.22 FS
31	1		*LICENCE PLATE BRACKET SAT	Deformed	108.36 FS	*108.36 FS
32	4		*RIVET	Necessary	2.12 FS	*2.12 FS
33	1		*GUIDE PICECE: BUMPER INNER BRACKET LH	Cracked	36.24 FS	*36.24 FS
34	1		*GUIDE PIECE: BUMPER INNER BRACKET RH	Serviceable	36.24 FS	*- FS
35	1		*GUIDE PIECE: BUMPER SIDE BRACKET LH	Necessary	40.50 FS	*40.50 FS
36	1		*GUIDE PIECE: BUMPER SIDE BRACKET RH	Necessary	40.50 FS	*40.50 FS
37	1		*GUIDE PIECE: BUMPER CTR BRACKET	Cracked	86.58 FS	*86.58 FS
38	1		*SET SENSOR BRACKETS	Necessary	43.74 FS	*43.74 FS
39	1		*SENSOR PRIMED	Serviceable	164.62 FS	*- FS
40	2		*SEAL RING SATIN BLACK	Necessary	2.42 FS	*2.42 FS
41	1		*2K PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
42	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
43	1		*RADIATOR GRILLE SATIN BLA	Broken	1,681.08 FS	*1,681.08 FS
44	1		*VW SIGN BLACK/BRIGHT CHRO	Missing	82.23 FS	*82.23 FS
45	1		*COOLING AIR GRILL BLACK: CENTRE LOWER GRILLE	Scratched	229.25 FS	*229.25 FS
46	1		*COOLING AIR GRILL BLACK: FOG LAMP GRILLE LH	Scratched	108.89 FS	*108.89 FS
47	1		*TRIM PRIMED: FOG LAMP GRILE TRIM LH	Repair	116.01 FS	*- FS
48	1		*DECORATIVE MOULDING BRIGH: FOG LAMP GRILLE CHROME LH	Cracked	79.95 FS	*79.95 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*DECORATIVE MOULDING BRIGH: BUMPER LOWER CHROM LH	Serviceable	90.40 FS	*- FS
50	1		*DECORATIVE MOULDING BRIGH: BUMPER LOWER CHROM CTR	Serviceable	218.09 FS	*- FS
51	10		*DECORATIVE LOWER CHROM RH: HEXAGON SOCKET HEAD PANEL	Necessary	10.90 FS	*10.90 FS
52	1		*LED HEADLIGHT: H/LAMP RH	Broken	2,311.49 FS	*2,311.49 FS
53	1		*TRIM COVER: H/LAMP TOP CHROM RH	Cracked	35.04 FS	*35.04 FS
54	1		*LED HEADLIGHT: H/LAMP LH	Broken	2,311.49 FS	*2,311.49 FS
55	1		*POWER MODULE FOR MAIN LIG	Shorted	412.61 FS	*412.61 FS
56	1		*POWER MODULE FOR LED HEAD		303.04 FS	*303.04 FS
57	1		*POWER MODULE FOR DAY DRIV		392.42 FS	*392.42 FS
58	1		*LED LAMP	Cracked	326.10 FS	*326.10 FS
59	1		*GASKET	Necessary	10.52 FS	*10.52 FS
60	1		*TRIM COVER: H/LAMP TOP CHROM LH	Cracked	35.04 FS	*35.04 FS
61	1		*REPAIR KIT	Necessary	12.48 FS	*12.48 FS
62	4		*HEX SOCKET HEAD BOLT	Necessary	7.88 FS	*7.88 FS
63	1		*LOCK CARRIER WITH MOUNTIN	Cracked	1,220.10 FS	*1,220.10 FS
64	1		*SUPPORT FOR LOCK CARRIER	Bent	29.43 FS	*29.43 FS
65	1		*CROSS SUPPORT: H/LAMP TOP PANEL LH	Bent	33.29 FS	*33.29 FS
66	1		*CROSS SUPPORT: H/LAMP TOP PANEL RH	Bent	33.29 FS	*33.29 FS
67	2		*HEXAGON SOCKET OVAL HEAD	Necessary	4.04 FS	*4.04 FS
68	1		*REFRIGERANT CONDENSER WIT	Bent	711.09 FS	*711.09 FS
69	1		*REFRIGERANT LINE: A/C HOSE SHORT	Cut	482.48 FS	*482.48 FS
70	1		*REFRIGERANT LINE: A/C PIPE	Bent	482.48 FS	*482.48 FS
71	1		*CHARGE AIR COOLER	Bent	523.08 FS	*523.08 FS
72	1		*PRESSURE HOSE: CTR PRESSURE HOSE	Serviceable	78.41 FS	*- FS
73	1		*PRESSURE PIPE: PRESSURE PIPE LONG (SIDE)	Serviceable	231.84 FS	*- FS
74	1		*RADIATOR	Bent	656.77 FS	*656.77 FS
75	3		*COOLANT	Necessary	62.64 FS	*62.64 FS
76	1		*AIR DUCT: AIR GUIDE UPPER	Cracked	42.50 FS	*42.50 FS
77	1		*AIR DUCT: AIR GUIDE LH	Cracked	27.92 FS	*27.92 FS
78	1		*AIR DUCT: AIR GUIDE RH	Cracked	27.92 FS	*27.92 FS
79	2		*BRACKET: RADIATOR BRACKET	Necessary	60.32 FS	*60.32 FS
80	1		*WATER TUBE	Cracked	81.07 FS	*81.07 FS
81	1		*WATER HOSE WITH QUICK COU: RADIATOR TOP HOSE	Cracked	127.24 FS	*127.24 FS
82	1		*THERMOSTAT	Serviceable	772.27 FS	*- FS
83	1		*MOULDED SEAL	Serviceable	34.05 FS	*- FS
84	1		*ELECTRIC FAN WITH FAN COW	Cracked	1,845.52 FS	*1,845.52 FS
85	1		*ENGINE TOP COVER	Scratched	227.70 FS	*227.70 FS
86	1		*AIR DUCT: AIR INTAKE UPPER HOUSING	Cracked	54.80 FS	*54.80 FS
87	1		*AIR DUCT: AIR INTAKE CTR HOUSING	Cracked	32.99 FS	*32.99 FS
88	1		*AIR DUCT: AIR INTAKE LOWER HOUSING	Cracked	18.94 FS	*18.94 FS
89	1		*AIR CLEANER	Cracked	336.22 FS	*336.22 FS
90	1		*INTAKE MANIFOLD	Cracked	580.28 FS	*580.28 FS
91	1		*THROTTLE BODY	Scratched	772.90 FS	*772.90 FS
92	1		*FLAT CONTACT HOUSING WITH: THROTTLE VALVE WIRE HOUSING	Cracked	8.39 FS	*8.39 FS
93	1		*FUEL RAIL	Cracked	171.84 FS	*171.84 FS
94	1		*SENSOR: PRESSURE SENSOR	Cracked	114.76 FS	*114.76 FS
95	1		*O-RING	Necessary	7.32 FS	*7.32 FS
96	1		*ADAPTOR	Necessary	5.51 FS	*5.51 FS
97	1		*RETAINING CLIP	Necessary	1.48 FS	*1.48 FS
98	4		*O-RING	Necessary	36.44 FS	*36.44 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	4		*O-RING	Necessary	31.16 FS	*31.16 FS
100	1		*BATTERY FILLED AND CHARGE	Deformed	610.42 FS	*610.42 FS
101	1		*BATTERY TRAY: BATTERY BRACKET	Cracked	108.37 FS	*108.37 FS
102	1		*BATTERY PROTECTION COVER	Deformed	77.33 FS	*77.33 FS
103	1		*FLAT CONTACT HOUSING WITH: STARTER WIRE HOUSING	Cut	9.13 FS	*9.13 FS
104	1		*GROMMET: STARTER WIRE COVER	Cut	5.88 FS	*5.88 FS
105	1		*WASH WATER RESERVOIR: WIPER TANK	Deformed	120.22 FS	*120.22 FS
106	2		*GASKET	Necessary	3.90 FS	*3.90 FS
107	1		*WINDSHIELD CLEANER CONCEN	Necessary	15.71 FS	*15.71 FS
108	1		*FENDER: FENDER RH	Bent	662.17 FS	*662.17 FS
109	1		*FENDER: FENDER LH	Bent	662.17 FS	*662.17 FS
110	1		*BRACKET: FENDER BRACKET LH	Bent	55.39 FS	*55.39 FS
111	1		*DEFORMATION ELEMENT: FENDER TOP BRACKET (FRT)	Bent	20.21 FS	*20.21 FS
112	2		*RIVETTED CAP NUT	Necessary	4.46 FS	*4.46 FS
113	1		*WHEELHOUSE LINER: LHS FENDER INNER (UPPER)	Cut	159.47 FS	*159.47 FS
114	1		*RADHAUSSCHALE-KUNSTSTOFF: LHS FENDER LINER (LOWER)	Serviceable	118.95 FS	*- FS
115	6		*EXPANDING NUT	Necessary	11.82 FS	*11.82 FS
116	4		*BUTT CONNECTOR WATERTIGJHT: WIRE CONNECTOR	Cut	29.96 FS	*29.96 FS
117	1		*REAR TRUNK LID	Repair	2,436.24 FS	*- FS
118	1		*SPOILER BLACK: RR W/SCREEN SIDE TRIM LH	Serviceable	306.22 FS	*- FS
119	1		*SPOILER BLACK: RR W/SCREEN SIDE TRIM RH	Serviceable	306.22 FS	*- FS
120	1		*1K WINDOW ADHESIVE	Not Necessary	49.51 FS	*- FS
121	1		*PRIMER	Not Necessary	25.74 FS	*- FS
122	2		*APPLICATOR	Not Necessary	18.78 FS	*- FS
123	1		*ACTIVATOR FOR PRECOATED W	Not Necessary	23.77 FS	*- FS
124	1		*PACKING ADHESIVE: RR NUMBER PLATE PACKING	Necessary	27.82 FS	*27.82 FS
125	2		*RIVETTED CAP NUT	Not Necessary	4.46 FS	*- FS
126	1		*INSCRIPTION BRIGHT CHROME: NAME PLATE (PASSAT)	Necessary	66.37 FS	*66.37 FS
127	1		*COVER FOR DOOR PRIMED: LHF DOOR LOWER MLDG	Scratched	67.60 FS	*67.60 FS
128	1		*DECORATIVE MOULDING CHROM	Scratched	118.96 FS	*118.96 FS
129	1		*COVER PRIMED: REAR BUMPER	Deformed	1,544.88 FS	*1,544.88 FS
130	1		*SPOILER PRIMED: REAR BUMPER SPOILER	Scratched	286.50 FS	*286.50 FS
131	20		*POP RIVET	Necessary	22.80 FS	*22.80 FS
132	1		*BUMPER: REAR REINFORCEMENT	Bent	541.33 FS	*541.33 FS
133	1		*ATTACHMENT STRIP: RR BUMPER CTR BRACKET	Cracked	58.90 FS	*58.90 FS
134	1		*GUIDE: TAILLIGHT LOWER BRACKET LH	Serviceable	21.96 FS	*- FS
135	1		*GUIDE: TAILLIGHT LOWER BRACKET RH	Serviceable	21.96 FS	*- FS
136	1		*GUIDE PIECE: BUMPER SIDE BRACKET LH	Serviceable	37.61 FS	*- FS
137	1		*GUIDE PIECE: BUMPER SIDE BRACKET RH	Serviceable	37.61 FS	*- FS
138	1		*SET SENSOR BRACKETS	Necessary	43.74 FS	*43.74 FS
139	2		*SENSOR PRIMED	Serviceable	329.24 FS	*- FS
140	1		*SEAL RING SATIN BLACK	Serviceable	2.42 FS	*- FS
141	1		*REFLECTOR: LHS REFLECTOR INNER	Not Necessary	65.92 FS	*- FS
142	1		*REFLECTOR: RHS REFLECTOR INNER	Scratched	65.92 FS	*65.92 FS
143	1		*DECORATIVE MOULDING BRIGH: REAR BUMPER LOWER CHROM (CTR)	Scratched	216.66 FS	*216.66 FS
144	1		*DECORATIVE MOULDING BRIGH: RR BUMPER LOWER CHROM (LH)	Serviceable	166.56 FS	*- FS
145	1		*DECORATIVE MOULDING BRIGH: RR BUMPER LOWER CHROM (RH)	Serviceable	166.56 FS	*- FS
146	1		*FRT NUMBER PLATE	Missing	80.00 FS	*80.00 FS
147	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
148	1		*FRET W/SCREEN SOLAR FILM	Necessary	400.00 FS	*400.00 FS
149	1		*DECORATIVE MOULDING BRIGH: BUMPER LOWER CHROM RH	Serviceable	89.35 FS	*- FS
150	1		*FRT LOCK CABLE	Cracked	33.99 FS	*33.99 FS
151	1		*SEALING STRIP	Cut	14.36 FS	*14.36 FS
152	1		*SEALING STRIP	Cut	14.36 FS	*14.36 FS
153	1		*WATER HOSE WITH QUICK COU	Cut	82.97 FS	*82.97 FS
154	1		*ALTERNATOR	Cracked	2,257.65 FS	*2,257.65 FS
155	1		*HARNESS FOR BATTERY	Bent	122.23 FS	*122.23 FS
156	1		*H/LAMP WIRE HOUSING	Cut	18.43 FS	*18.43 FS
157	1		*REAR BUMPER LOWER TRIM (BLACK)	Cracked	211.44 FS	*211.44 FS
158	1		*AIR CLEANER WATER DRAIN HOSE	Cut	24.95 FS	*24.95 FS
159	1		*MOUNTING	Cracked	10.22 FS	*10.22 FS
160	1		*GEL FILM FOR RAIN SENSOR	Necessary	58.00 FS	*58.00 FS
161	1		*GROMMET	Necessary	10.10 FS	*10.10 FS
					Total Parts (\$\$)	55,862.00 49,796.64

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING ASSISTANCE - AWP.	New	195.00	195.00
2	LABOUR FRT.	New	7,560.00	4,200.00
3	SPRAY PAINT FRT.	New	5,600.00	4,800.00
4	R&R FRT W/SCREEN	New	840.00	840.00
5	LABOUR REAR.	New	3,360.00	840.00
6	SPRAY PAINT REAR.	New	4,000.00	2,000.00
7	R&R REAR W/SCREEN.	New	840.00	0.00
8	TRANSFER REAR BOOT LID MECHANISM.	New	840.00	0.00
9	CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	280.00	280.00
10	DIAGNOSTIC AND PROGRAMMING.	New	480.00	480.00
11	LEAKED CHECK, VACUUM & REGAS.	New	420.00	420.00
12	A/C GAS.	New	60.00	60.00
13	R&R D/BOARD	New	2,520.00	1,260.00
14	R&R SEAT BELT & AIRBAG CONTROL UNIT.	New	1,680.00	840.00
15	R&R MANIFOLD.	New	1,680.00	840.00
16	R&R THERMOSTAT.	New	840.00	0.00
17	R&R ENGINE MTG TO R&R A/C HOSE.	New	840.00	420.00
18	R&R ALTERNATOR.	New	840.00	420.00
19	WHEEL ALIGNMENT: PERFORM WHEEL ALIGNMENT AFTER REPLACING OR REMOVE AND REFIX STEERING WHEEL.	New	360.00	360.00
Gross Labour Cost (\$\$)			33,235.00	18,255.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >