

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009498/ATF3E2
Date: 15/10/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00000391900
Claimant Vehicle No :	GBJ3351R	Insured Vehicle No :	SLR1842T
Date of Loss:	12/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D203066/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ3351R	Engine No:	1GD8340501
Make & Model:	TOYOTA REGIUSACE DX, 2.8 (A)	Chassis No:	GDH2012003245
Reg. Date:	21/03/2019 (Man. Year: 2018)	Odometer:	41769 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,830.18	4,453.40	7,376.78	62.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,160.00	550.00	2,610.00	82.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,990.18	5,003.40	9,986.78	66.62
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	14,990.18	4,000.00	10,990.18	73.32
+ GST 7.00/7.00% (S\$)	1,049.31	280.00	769.31	73.32
Nett Amount (S\$)	16,039.49	4,280.00	11,759.49	73.32

INSPECTION

Date of Assignment:	04/09/2020	
Date Inspected:	08/09/2020 Inspected At:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4., #08-09 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Oct 2020)	
Parts:	N/A	TOYOTA REGIUSACE DX 2.8 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3351R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	571.60 FL	*571.60 FL
2	1		*FRONT BUMPER TOW HOOK COVER LH	Not Necessary	25.10 FL	*- FL
3	1		*FRONT BUMPER FOGLAMP COVER LH	Not Necessary	48.70 FL	*- FL
4	2		*FRONT BUMPER SIDE RETAINER	Necessary	297.40 FL	*240.00 FL
5	1		*FRONT BUMPER CENTRE BEAM	Not Necessary	176.90 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	357.10 FL	*357.10 FL
7	1		*HEADLAMP	N/S Cracked	6,066.20 FL	*2,584.50 FL
8	1		*FRONT GRILLE (UPPER) BASE	Cracked	568.90 FL	*568.90 FL
9	1		*FRONT GRILLE (LOWER)	Deformed	383.70 FL	*383.70 FL
10	1		*FRONT GRILLE COVER GARNISH (UPPER)	Cracked	221.70 FL	*221.70 FL
11	1		*FRONT GRILLE COVER GARNISH (LOWER)	Cracked	383.70 FL	*383.70 FL
12	1		*FRONT STEP PANEL GARNISH LH	Not Necessary	186.20 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Not Necessary	377.91 FL	*- FL
14	1		*FRONT BRACE PANEL	Not Necessary	75.20 FL	*- FL
15	1		*AIR CON CONDENSER	Not Necessary	1,949.60 FL	*- FL
16	1		*ADBLUE TANK	Not Necessary	1,365.80 FL	*- FL
17	1		*ADBLUE TANK WIRE HARNESS	Not Necessary	451.20 FL	*- FL
18	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
19	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*SET FRONT GRILLE COVER GARNISH (UPPER) CLIP	Necessary	50.00 FS	*20.00 FS
21	1		*SET FRONT GRILLE COVER GARNISH (LOWER) CLIP	Necessary	50.00 FS	*20.00 FS
22	1		*SET FRONT STEP PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
23	1		*FRONT GRILLE STICKER (SPECIAL TYPE)	Necessary	850.00 FS	*400.00 FS
24	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
25	1		*FRONT BRACE PANEL SEALANT	Not Necessary	150.00 FS	*- FS
26	1		*SET FRONT AIR GUARD CLIP	Not Necessary	60.00 FS	*- FS
27	1		*COOLANT	Not Necessary	60.00 FS	*- FS
28	1		*ADBLUE PANEL	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,206.91	5,781.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,376.73	1,327.80
Total Parts (\$\$)	11,830.18	4,453.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,000.00	350.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	200.00
3	TUFF COAT	New	250.00	0.00
4	REFOCUS HEADLAMP BEAM	New	60.00	0.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
7	REMOVE AND REFIX AIR COLLER	New	120.00	0.00
8	REMOVE AND REFIX ADBLUE TANK	New	350.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (S\$)	3,160.00
				550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >