

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009506/APS3Q2

Date: 18/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800105137

Claimant
Vehicle No : SLB490R **Insured Vehicle No :** SMD8861D

Date of Loss: 30/08/2020 Nature of Claim: TP Claim No: 1641535165SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SLB490R | | |
| Make & Model: | SUBARU FORESTER, 2.0 XT CVT AWD SR (A) | Engine No: | FA20A882966 |
| Reg. Date: | 26/03/2016 (Man. Year: 2016) | Chassis No: | JF1SJGK85GG068694 |
| Colour: | White | Odometer: | 99216 km |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/55 R18 | Rear Tyre Size: | 225/55 R18 |
| Front Left Side: | Continental 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 6,716.00 | 2,831.36 | 3,884.64 | 57.84 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,730.00 | 680.00 | 2,050.00 | 75.09 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 9,446.00 | 3,511.36 | 5,934.64 | 62.83 |
| Approved Total (Overridden) (S\$) | | 2,800.00 | | |
| (S\$) | 9,446.00 | 2,800.00 | 6,646.00 | 70.36 |
| + GST 7.00/7.00% (S\$) | 661.22 | 196.00 | 465.22 | 70.36 |
| Nett Amount (S\$) | 10,107.22 | 2,996.00 | 7,111.22 | 70.36 |
| + Loss of Use (3.0 x S\$100.00/day) (S\$) | | 300.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 3,298.00 | | |

INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 07/09/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------------|---------------|------------|--------------|
| 1 | 1 | | *FRONT R/H HEAD LAMP | Cut | 2,504.30 F | *2,380.00 FL |
| 2 | 1 | | *FRONT R/H HEAD LAMP LOWER BRACKET | Not Necessary | 55.00 F | *- FL |
| 3 | 1 | | *FRONT R/H FENDER | Repair | 380.30 F | *- FL |
| 4 | 1 | | *FRONT R/H FENDER COWLING | Not Necessary | 125.20 F | *- FL |
| 5 | 8 | | *FRONT R/H FENDER COWLING CLIP | Not Necessary | 52.00 F | *- FL |
| 6 | 1 | | *FRONT BUMPER | Deformed | 694.50 F | *694.50 FL |
| 7 | 10 | | *FRONT BUMPER CLIP | Necessary | 65.00 F | *30.00 FL |
| 8 | 1 | | *FRONT R/H BUMPER SIDE RETAINER | Necessary | 26.00 F | *26.00 FL |
| 9 | 1 | | *FRONT R/H BUMPER FOGLAMP | Cracked | 360.40 F | *360.40 FL |
| 10 | 1 | | *FRONT R/H BUMPER FOGLAMP COVER | Deformed | 48.30 F | *48.30 FL |
| 11 | 1 | | *FRONT R/H BUMPER AIR DUCT | Not Necessary | 65.30 F | *- FL |
| 12 | 1 | | *FRONT R/H SPORT RIM | Not Necessary | 980.00 F | *- FL |
| 13 | 1 | | *FRONT R/H SPORT ABSORBER | Not Necessary | 340.60 F | *- FL |
| 14 | 4 | | *FRONT R/H KNUCKLE ARM | Not Necessary | 264.90 F | *- FL |
| 15 | 4 | | *FRONT R/H KNUCKLE ARM BEARING | Not Necessary | 261.00 F | *- FL |
| 16 | 1 | | *FRONT R/H LOWER ARM | Not Necessary | 493.20 F | *- FL |

F=Franchise part. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$) | 6,716.00 | 3,539.20 |
| - List Item Discount on L Items 0.00/20.00% (\$) | 0.00 | 707.84 |
| Total Parts (\$) | 6,716.00 | 2,831.36 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|------------------------------------|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | REMOVE & REFIT FRONT UNDERCARRIAGE | New | 350.00 | 0.00 |
| 2 | WHEEL ALIGNMENT | New | 150.00 | 0.00 |
| 3 | TUFF KOTE | New | 150.00 | 0.00 |
| 4 | TO CHECK WIRING | New | 80.00 | 30.00 |
| 5 | PANEL BEATING | New | 1,000.00 | 250.00 |
| 6 | SPRAY PAINTING | New | 1,000.00 | 400.00 |
| Gross Labour Cost (\$) | | | 2,730.00 | 680.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >