

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. QQ 3988

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | DISTORTED | 1,700.00 | 1,250.00 |
| 1 | REAR BUMPER SIDE TOP GARNISH @ \$220.00 | DISTORTED | 440.00 | 440.00 |
| 1 | REAR TAILGATE | BADLY DENTED | 1,850.00 | 1,500.00 |
| 1 | REAR TAILGATE SIDE BRACKET | NOT NECESSARY | 198.00 | - |
| 2 | REAR TAILGATE LAMP @ \$375.00 | CRACKED | 750.00 | 750.00 |
| 1 | REAR TAILGATE BRAKELAMP | CRACKED | 150.00 | 150.00 |
| 1 | REAR LH CHASSIS BRACKET | TO REPAIR SEE LABOUR | 240.00 | - |
| 1 | REAR LH FENDER | TO REPAIR SEE LABOUR | 2,100.00 | - |
| 1 | REAR LH LOWER TAILLAMP PANEL | TO REPAIR SEE LABOUR | 220.00 | - |
| 1 | REAR END PANEL | BENT | 1,278.00 | 1,100.00 |
| | LESS 25% DISCOUNT | | -2,231.50 | -1,297.50 |
| | | | 6,694.50 | 3,892.50 |
| | SPECIAL NETT ITEMS | | | |
| 1 | TOYOTA EMBLEM (SN) | NECESSARY | 60.00 | 60.00 |
| 1 | HILUX EMBLEM (SN) | NECESSARY | 60.00 | 60.00 |
| 1 | SET REVERSE SENSOR (SN) | SHORTED | 200.00 | 200.00 |
| 1 | REAR NUMBER PLATE W/FRAME (SN) | CRACKED / MISSING | 60.00 | 14.00 |
| | | | 380.00 | 334.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR LH CHASSIS BRACKET, REAR LH FENDER AND REAR LH LOWER TAILLAMP PANEL. | | 2,400.00 | 1,100.00 |
| | TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED. | | 1,600.00 | 880.00 |
| | TO REMOVE, REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS. | | 250.00 | 30.00 |

Report Ref No. CS/SMO20009513/Uvf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|----------------------------|----------------------|
| | TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS. | | 250.00 | 50.00 |
| | | | 4,500.00 | 2,060.00 |
| | GRAND TOTAL | | 11,574.50 | 6,286.50 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 5,000.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |

Report Ref No. CS/SMO20009513/Uvf3s2

CHUA KANG SENG

Licensed Appraiser