



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20009513/Uvf3s2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 30-09-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 1273C	Veh. Inspected	QQ 3988	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2002591/IJH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	07/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HILUX D/CAB (A)	c.c	2393	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	PN1KB3CD803300614	Colour	BLACK	
Odometer	75673	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/65 R17	HABILEAD	6 mm	
L/H Front Tyre	265/65 R17	HABILEAD	6 mm	
R/H Rear Tyre	265/65 R17	HABILEAD	6 mm	
L/H Rear Tyre	265/65 R17	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/09/2020	Inspection Date	09/09/2020	
Survey held at	15 KAKI BUKIT ROAD 4 BARTLEY BIZ CENTER #01-53			
Repairer	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		