

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20009518/R1YF3E2

Date: 19/10/2020

REFERENCE

Insured/Claimant:	HIZAM BIN HASHIM	Policy No:	1700070241	
Date of Loss:	06/09/2020	Nature of Claim:	OD	Claim No: 9012423923SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU447R			
Make & Model:	MITSUBISHI ASX, 2.0 (A)	Engine No:	4B11TR9008	
Reg. Date:	30/10/2017 (Man. Year: 2017)	Chassis No:	JMFXTGA2WJZ000506	
Colour:	Grey	Odometer:	70137 km	
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$72,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,897.02	6,617.31	1,279.71	16.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	3,120.00	2,540.00	44.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,557.02	9,737.31	3,819.71	28.18
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,957.02	9,137.31	3,819.71	29.48
+ GST 7.00/7.00% (S\$)	906.99	639.61	267.38	29.48
Nett Amount (S\$)	13,864.01	9,776.92	4,087.09	29.48

INSPECTION

Date of Assignment: 07/09/2020
Date Inspected: 07/09/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PNL,HEADLAMP SUPT,UPR LH	Not Necessary	78.00 FL	*- FL
2	1		*HEADLAMP ASSY,LH	Cracked	824.00 FL	*824.00 FL
3	1		*REINFORCEMENT,FR BUMPER	Serviceable	53.00 FL	*- FL
4	1		*CORE,FR BUMPER	Necessary	13.00 FL	*13.00 FL
5	1		*CORE,FR BUMPER	Not Necessary	13.00 FL	*- FL
6	2		*GROMMET	Necessary	4.00 FL	*4.00 FL
7	1		*FACE,FR BUMPER	Cracked	806.00 FL	*806.00 FL
8	1		*COVER,FR BUMPER	Cracked	307.00 FL	*307.00 FL
9	1		*GRILLE,FR BUMPER	Deformed	205.00 FL	*205.00 FL
10	1		*EXTENSION,FR BUMPER	Deformed	191.00 FL	*191.00 FL
11	1		*GRILLE ASSY,RADIATOR	Scratched	342.00 FL	*342.00 FL
12	1		*COVER,F/BMPR AIR INTAKE,LH	Serviceable	44.00 FL	*- FL
13	1		*CHROME GARNISH,FR BUMPER SIDE	Cracked	123.00 FL	*123.00 FL
14	1		*COVER,FR BUMPER,LH	Cracked	37.00 FL	*37.00 FL
15	1		*CHROME GARNISH,FR BUMPER SIDE	Cracked	77.00 FL	*77.00 FL
16	1		*GARNISH,FR BUMPER,LH	Cracked	27.00 FL	*27.00 FL
17	1		*LH LAMP ASSY,FOG,FR	Serviceable	223.00 FL	*- FL
18	1		*COVER,ENG ROOM UNDER,FR	Serviceable	187.00 FL	*- FL
19	18		*CLIP,ENG ROOM COVER	Not Necessary	36.00 FL	*- FL
20	10		*CLIP,SPLASH SHIELD	Not Necessary	40.00 FL	*- FL
21	1		*FENDER,FR LH	Cracked	510.00 FL	*510.00 FL
22	1		*GARNISH,FR FENDER,LH	Serviceable	89.00 FL	*- FL
23	1		*SHIELD,FR WHEELHOUSE,LH	Serviceable	146.00 FL	*- FL
24	10		*CLIP,RR BUMPER	Serviceable	30.00 FL	*- FL
25	1		*MOULDING,FR WHEEL ARCH,LH	Scratched	132.00 FL	*132.00 FL
26	1		*HOOD	Bent	797.00 FL	*797.00 FL
27	1		*HINGE,HOOD,LH	Serviceable	68.00 FL	*- FL
28	1		*HINGE,HOOD,RH	Serviceable	68.00 FL	*- FL
29	1		*LATCH,HOOD	Serviceable	76.00 FL	*- FL
30	1		*MIRROR ASSY,DOOR,LH	Serviceable	472.00 FL	*- FL
31	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
32	1		*REINFORCEMENT, FR BUMPER	Bent	415.00 FL	*415.00 FL
33	1		*PANEL, HEADLAMP SUPPORT	Bent	366.00 FL	*366.00 FL
34	1		*COVER, ENG ROOM UNDER, FR	Cracked	187.00 FL	*187.00 FL
35	1		*SHIEL, FR WHEELHOUSE, LH	Cracked	146.00 FL	*146.00 FL
36	1		*LAMP ASSY, SIDE MARKER, LH	Broken	665.00 FL	*665.00 FL
37	1		*CONDENSER ASSY, A/C REFRIGE	Bent	1,134.00 FL	*1,134.00 FL
38	1		*RADIATOR ASSY	Bent	1,151.00 FL	*1,151.00 FL
39	8		*CLIP, SPLASH SHIELD	Necessary	32.00 FL	*32.00 FL
40	6		*CLIP, ENG ROOM COVER	Necessary	12.00 FL	*12.00 FL
41	1		*FRONT NUMBER PLATE WITH FRAME	Cracked	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,226.00	8,573.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,328.98	1,955.69
Total Parts (\$\$)	7,897.02	6,617.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON PNL HEADLAMP SUPT UPR LH,FRONT BUMPER FACE,LH FRONT FENDER,FRONT BONNET,LH SIDE MIRROR,REPAIR LH FRONT DOOR,REPAIR LH REAR DOOR	New	2,250.00	1,350.00
2	PAINT WORK SPRAY PNL HEADLAMP SUPT UPR LH,FROTN BUMPER FACE,LH FRONT FENDER,FRONT BONNET,LH FRONT DOOR,LH SIDE MIRROR,LH REAR DOOR AND AFFECTED PORTION	New	2,800.00	1,400.00
3	SUPPLY BODY SEALANT	New	80.00	40.00
4	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	PERFORM RUST PREVENTION	New	80.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
8	TOP UP AIRCON GAS	New	80.00	80.00
9	R/I RADIATOR & AIRCON CONDENSER	New	100.00	100.00
Gross Labour Cost (\$\$)			5,660.00	3,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >