

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009525/T1RS3Q2
Date: 20/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800012236
Claimant Vehicle No :	SHD3317B	Insured Vehicle No :	SDE8318H
Date of Loss:	07/09/2020	Nature of Claim:	TP
		Claim No:	8503570919SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3317B		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU655900
Reg. Date:	08/07/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU091886
Colour:	Blue	Odometer:	490260 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,742.76	2,981.88	1,760.88	37.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,190.00	1,660.00	530.00	24.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,932.76	4,641.88	2,290.88	33.04
Approved Total (Overridden) (S\$)		3,700.00		

(S\$)	6,932.76	3,700.00	3,232.76	46.63
+ GST 7.00/7.00% (S\$)	485.29	259.00	226.29	46.63
Nett Amount (S\$)	7,418.05	3,959.00	3,459.05	46.63
+ Car Rental (3.0 x S\$114.95/day) (S\$)		344.85		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,305.85		

INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 07/09/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Bent	663.00 FL	*663.00 FL
2	1		*FRT DOOR RH	Bent	2,256.40 FL	*2,256.40 FL
3	1		*REAR DOOR RH	Repair	2,201.10 FL	*- FL
4	2		*FRT RH & REAR RH WHEEL CAP	Cut	214.20 FL	*214.20 FL
5	1		*FRT DOOR COMFORTDELGRO RH	Necessary	75.00 FS	*75.00 FS
6	1		*REAR DOOR APPS STICKER RH	Necessary	80.00 FS	*80.00 FS
7	1		*FRT FENDER ADV STICKER RH	Cut	100.00 FS	*100.00 FS
8	1		*BOTH RH DOORS ADV STICKER	Cut	200.00 FS	*200.00 FS
9	1		*REAR FENDER ADV.STICKER RH	Cut	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,809.70	3,608.60
- List Item Discount on L Items 20.00/20.00% (\$)	1,066.94	626.72
Total Parts (\$)	4,742.76	2,981.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING -REAR FENDER RH ETC	New	600.00	560.00
2	SPRAYPAINT -ROCKER PANEL GARNISH RH	New	1,250.00	1,000.00
3	TUFF COAT ON AFFECTED PARTS	New	100.00	40.00
4	TRANSFER OF DOORS	New	240.00	60.00
Gross Labour Cost (S\$)			2,190.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >