

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20009529/R1TF3E2

Date: 02/11/2020

REFERENCE

Insured/Claimant:	LOW MAGGIE	Policy No:	
Date of Loss:	04/09/2020	Nature of Claim:	OD Claim No: 1382152131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDQ1191M		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UHT1659
Reg. Date:	03/09/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH001878
Colour:	Maroon	Odometer:	12665 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,085.34	6,092.04	993.30	14.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,290.00	7,555.00	735.00	8.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,375.34	13,647.04	1,728.30	11.24
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	15,075.34	13,347.04	1,728.30	11.46
+ GST 7.00/7.00% (S\$)	1,055.27	934.29	120.98	11.46
Nett Amount (S\$)	16,130.61	14,281.33	1,849.28	11.46

INSPECTION

Date of Assignment: 07/09/2020
Date Inspected: 07/09/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, RR BUMPER	Dented	748.00 FL	*748.00 FL
3	4		*CLIP, RR BUMPER	Necessary	16.00 FL	*16.00 FL
4	1		*BRACKET, RR BUMPER, LH	Cracked	28.00 FL	*28.00 FL
5	1		*BRACKET, RR BUMPER, RH	Cracked	28.00 FL	*28.00 FL
6	1		*REFLECTOR LH	Serviceable	23.00 FL	*- FL
7	1		*REFLECTOR RH	Serviceable	23.00 FL	*- FL
8	1		*LAMP ASSY, COMB, RR LH	Cracked	335.00 FL	*335.00 FL
9	1		*LAMP ASSY, COMB, RR RH	Cracked	335.00 FL	*335.00 FL
10	1		*PANEL, RR END	Bent	425.00 FL	*425.00 FL
11	1		*BOARD, TRUNK ROOM FLOOR	Serviceable	195.00 FL	*- FL
12	1		*TRIM, RR END	Serviceable	66.00 FL	*- FL
13	1		*MUD GUARD, RR LH	Serviceable	41.00 FL	*- FL
14	1		*MUD GUARD, RR RH	Serviceable	41.00 FL	*- FL
15	1		*DUCT, RR VENTILATOR	Serviceable	30.00 FL	*- FL
16	1		*COVER, RR VENTILATOR	Serviceable	40.00 FL	*- FL
17	1		*BUZZER, KEYLESS OPERATIO, RR	Serviceable	91.00 FL	*- FL
18	1		*ANT, KEYLESS OPERATION, RR	Serviceable	96.00 FL	*- FL
19	1		*PANEL, TRUNK LID	Bent	791.00 FL	*791.00 FL
20	1		*WEATHERSTRIP, TRUNK LID	Necessary	157.00 FL	*157.00 FL
21	1		*HINGE, TRUNK LID, LH	Serviceable	203.00 FL	*- FL
22	1		*HINGE, TRUNK LID, RH	Serviceable	203.00 FL	*- FL
23	1		*LATCH, TRUNK LID	Serviceable	218.00 FL	*- FL
24	1		*STRIKER, TRUNK LID LATCH	Serviceable	20.00 FL	*- FL
25	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
26	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
27	1		*GARNISH, RR END PANEL	Cracked	336.00 FL	*336.00 FL
28	1		*PANEL, QTR, OTR RH	Buckled	763.00 FL	*763.00 FL
29	1		*PANEL, RR COMB LAMP HSG, RH	Bent	60.00 FL	*60.00 FL
30	1		*EXTN, QTR PANEL, UPR OTR RH	Bent	118.00 FL	*118.00 FL
31	2		*STOPPER WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
32	3		*SPACER,RR WINDOW	Necessary	27.00 FL	*27.00 FL
33	1		*UNPAINTED BODYKITS	Cracked	1,643.00 F	*1,643.00 F
34	1		*CAP, TAIL LAMP (X2)	Necessary	6.00 FL	*6.00 FL
35	1		*GROMMET, TAIL LAMP (X2)	Necessary	6.00 FL	*6.00 FL
36	1		*GROMMET, RR END TRIM (X4)	Necessary	12.00 FL	*12.00 FL
37	1		*CLIPS (X4)	Necessary	12.00 FL	*12.00 FL
38	1		*MUFFLER, EXHAUST MAIN	Bent	784.00 FL	*784.00 FL
39	1		*HANGER, EXHAUST MUFFIER	Necessary	22.00 FL	*22.00 FL
40	1		*HANGER, EXHAUST MMUFFIER (X2)	Necessary	44.00 FL	*44.00 FL
41	1		*PIPE, EXHAUST TAIL	Bent	603.00 FL	*603.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,705.00	7,415.00
- List Item Discount on L Items 23.00/23.00% (\$)	1,619.66	1,322.96
Total Parts (\$)	7,085.34	6,092.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER, BODY KIT, BOOTLID, RR END & RHR FENDER REPAIR LHR FENDER & RR FLR PNL	New	4,050.00	3,600.00
2	RESURVEY RR BUMPER, RR BUMPER BODY KIT, RR END PNL, RR LR PNL, BOOTLID, BOOT LID SPOILER, LHF FENDER & RHR FENDER	New	2,800.00	2,625.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
4	REMOVE & REFIT RR FLR BOARD, TRIM, SEAT & CARPET	New	120.00	120.00
5	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
8	SUPPLY BODY PNL SEALANT	New	80.00	60.00
9	REMOVE & REFIT RR WINDSCREEN GLASS	New	240.00	240.00
10	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
11	SUPPLY RR NUMBER PLATE WITH CASING	New	50.00	0.00
12	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
13	SUPPLY REVERSE SENSOR	New	220.00	220.00
14	SUPPLY C&C BADGE	New	40.00	40.00
15	REMOVE & REPLACE REAR EXHAUSTMUFFLER AND OTHER ATTACHED PARTS	New	200.00	200.00
Gross Labour Cost (\$\$)			8,290.00	7,555.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >