



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11985/LOW MAGGIE Reg No/Reg Date SDQ1191M / 03/09/201 Date In/Mileage / 12665 Chassis No MMBSTA13AKH001878 Engine No 3A92UHT1659 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	07/09/2020/ 13:40	BLE	261 / Edwin Caina	57049			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER , BODY KIT , BOOTLID , RR END & RHR FENDER REPAIR LHR FENDER & RR FLR PNL								3600 4050.00
E PNT98000 RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL , RR FLR PNL , BOOTLID , BOOTLID SPOILER , LHF FENDER & RHR FENDER								2625 2800.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT								120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD,TRIM,SEAT & CARPET								120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								40 80.00
M SUNDRY SUPPLY BODY PNL SEALANT								60 80.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS								240.00
M SUNDRY SUPPLY WINDSCREEN SEALANT								80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING								50.00X
E PNT88000 REMOVE & REFIT REVERSE SENSOR								60.00
M SUNDRY SUPPLY REVERSE SENSOR								? 220.00
M SUNDRY SUPPLY C&C BADGE								40.00
M SUNDRY Sundries								20.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11985/LOW MAGGIE Reg No/Reg Date SDQ1191M / 03/09/201 Date In/Mileage / 12665 Chassis No MMBSTA13AKH001878 Engine No 3A92UHT1659 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	07/09/2020/ 13:40	BLE	261 / Edwin Caina	57049
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FACE,RR BUMPER <i>de</i>		1.00	748.00	23.00	575.96
M CLIP,RR BUMPER <i>re</i>		4.00	4.00	23.00	12.32
M BRACKET,RR BUMPER,LH ?		1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH ?		1.00	28.00	23.00	21.56
M REFLECTOR LH X		1.00	X 23.00	23.00	17.71
M REFLECTOR RH X		1.00	X 23.00	23.00	17.71
M LAMP ASSY,COMB,RR LH <i>ca</i>		1.00	335.00	23.00	257.95
M LAMP ASSY,COMB,RR RH <i>ca</i>		1.00	335.00	23.00	257.95
M PANEL,RR END <i>ca</i>		1.00	425.00	23.00	327.25
M BOARD,TRUNK ROOM FLOOR ?		1.00	195.00	23.00	150.15
M TRIM,RR END ?		1.00	66.00	23.00	50.82
M MUD GUARD,RR LH X		1.00	X 41.00	23.00	31.57
M MUD GUARD,RR RH X		1.00	X 41.00	23.00	31.57
M DUCT,RR VENTILATOR X		1.00	X 30.00	23.00	23.10
M COVER,RR VENTILATOR X		1.00	X 40.00	23.00	30.80
M BUZZER,KEYLESS OPERATIO,RR ?		1.00	91.00	23.00	70.07
M ANT,KEYLESS OPERATION,RR ?		1.00	96.00	23.00	73.92
M PANEL,TRUNK LID <i>ca</i>		1.00	791.00	23.00	609.07
M WEATHERSTRIP,TRUNK LID <i>re</i>		1.00	157.00	23.00	120.89
M HINGE,TRUNK LID,LH ?		1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH ?		1.00	203.00	23.00	156.31
M LATCH,TRUNK LID X		1.00	X 218.00	23.00	167.86
M STRIKER,TRUNK LID LATCH X		1.00	X 20.00	23.00	15.40
M MARK,THREE-DIA <i>re</i>		1.00	69.00	23.00	53.13
M MARK,ATTRAGE <i>re</i>		1.00	21.00	23.00	16.17
M GARNISH,RR END PANEL ?		1.00	336.00	23.00	258.72
M PANEL,QTR,OTR RH <i>ca</i>		1.00	763.00	23.00	587.51
M PANEL,RR COMB LAMP HSG,RH ?		1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR RH ?		1.00	118.00	23.00	90.86
M STOPPER,WINDSHIELD GLASS <i>re</i>		2.00	3.00	23.00	4.62
M SPACER,RR WINDOW <i>re</i>		3.00	9.00	23.00	20.79
M UNPAINTED BODYKITS <i>ca</i>		1.00	1643.00	20.00	1314.40

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: *Rahul - Hp 90010066*SURVEYOR SIGNATURE: *Rahul*DATE: *07/09/2020 @ 1620*REMARKS: *14 days**EXCESS: TBA / REVERT*

Confirm & accepted by

Authorized signatory and company stamp

Nett 13,700.21
7% GST on 13700.21 959.01
Total Payable 14,659.22

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Person Contacted: