

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20009532/KBA3Q2

Date: 07/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800130432

Claimant
Vehicle No : SMP4931Z **Insured Vehicle No :** SMD1246B

Date of Loss: 03/09/2020 Nature of Claim: TP Claim No: 2816760566SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP4931Z		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0E27390
Reg. Date:	27/09/2019 (Man. Year: 2019)	Chassis No:	ZWR800402802
Colour:	Metallic Black	Odometer:	109739 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Double Star 8 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	Double Star 8 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,697.28	3,279.83	417.45	11.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	860.00	1,040.00	54.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,597.28	4,139.83	1,457.45	26.04
+ GST 7.00/7.00% (S\$)	391.81	289.79	102.02	26.04
Nett Amount (S\$)	5,989.09	4,429.62	1,559.47	26.04
+ Loss of Use (4.0 x S\$140.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		17.00		
Nett Liability (S\$)		5,006.62		
Global Sum Settlement (S\$)		4,886.00		

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	727.20 FL	*727.20 FL
2	10		*FRONT BUMPER CLIPS	Necessary	58.00 FL	*58.00 FL
3	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	97.40 FL	*97.40 FL
4	1		*FRONT HEADLAMP RH	Mtg Cracked	2,228.21 FL	*2,228.21 FL
5	1		*FRONT FENDER RH	Buckled	1,152.20 FL	*850.10 FL
6	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	107.00 FL	*107.00 FL
7	1		*FRONT FOGLAMP COVER RH	Serviceable	126.90 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	305.20 FL	*305.20 FL
9	1		*FRONT BUMPER CENTER GARNISH	Serviceable	127.60 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,929.71	4,373.11
- List Item Discount on L Items 25.00/25.00% (\$)	1,232.43	1,093.28
Total Parts (\$)	3,697.28	3,279.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST ,DISMANTLE ACCIDENT AREA	New	800.00	400.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	700.00	440.00
3	LABOUR CHARGES TO DIAGNOSE FAULTY CODE & RESET MEMOR (HEADLAMP)	New	150.00	0.00
4	LABOUR CHARGES TO DISCONNECT & RECONNECT FRONT WIRING SYSTEM & ETC.TO EFFECT REPAIR AT FRONT ACCIDENT AREAS & ETC	New	150.00	20.00
5	TO WHEEL ALIGNMENT & BALANCING	New	100.00	0.00
Gross Labour Cost (\$)			1,900.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >