

ASS. REC. BY:

REF:

102/20009542/KK

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

B 180k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDR 1086L

Yr Regn:

01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 330i

c.c

1998

Colour:

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

63530

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA BA 760 50 NU 0753

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/45R18

R:

255/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/8/20

D.O.I.

8/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Mia N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Est not ready

2/10

B 1996.91 Car burnt

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

ESTIMATE : SDR 1066 L

Vehicle & Document Information

Date: 7/9/2020
Vehicle No: SDR 1066 L
Make/Model: BMW 330i

S/N	Description	Qty		Repairer's Est
1	REAR BUMPER	1	\$	1,652.12
2	REAR BUMPER BRACKET	1	\$	86.45
3	REAR BUMPER REFLECTOR LH	1	\$	58.94
4	REAR BUMPER EXHAUST TIP	1	\$	173.96
			List Total:	\$ 1,971.47
			-10%	\$ 1,774.32

S/N	Special Nett	Qty		Repairer's Est
1	REAR PDS SENSOR SET	1	\$	287.12
1	TO CHECK LIGHTING & WIRINGS		\$	100 120.00
2	ANTI RUST PROOFING ON REAR AFFECTED & REPLACEMENT PARTS		\$	200 300.00
3	TO REMOVE, RE-ALIGN REAR, REPLACE ITEMS AS ABOVE		\$	250 600.00
4	TO PUTTY & RESPRAY REAR BUMPER		\$	250 500.00
			Labour Total:	\$ 1,520.00
			Parts + Labour Total:	\$ 3,581.44
			GRAND TOTAL (-20%) PART BY PART	\$ 2,865.15

CHUAN HO AUTO SERVICE



[Handwritten signature]

*Not authorized
Henry Bepain*

2 days

@ 1996-91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: