

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20009548/KGA3Q2

**Date:** 14/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900107819

**Claimant**  
**Vehicle No :** SML3892E **Insured Vehicle No :** SML9100T

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: 9103745970SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SML3892E</b>	Engine No:	G4FGKU146162
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMKU909905
Reg. Date:	17/05/2019 (Man. Year: 2019)	Odometer:	27013 km
Colour:	Metallic Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,482.52	3,177.84	304.68	8.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,380.00	230.00	14.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,092.52</b>	<b>4,557.84</b>	<b>534.68</b>	<b>10.50</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,600.00</b>		
<b>(\$\$)</b>	5,092.52	3,600.00	1,492.52	29.31
<b>+ GST 7.00/7.00% (\$\$)</b>	356.48	252.00	104.48	29.31
<b>Nett Amount (\$\$)</b>	<b>5,449.00</b>	<b>3,852.00</b>	<b>1,597.00</b>	<b>29.31</b>
<b>+ Car Rental (8.0 x \$100.00/day) (\$\$)</b>		800.00		
<b>Nett Liability (\$\$)</b>		<b>4,652.00</b>		

### INSPECTION

Date of Assignment: 07/09/2020

Date Inspected: 08/09/2020 Inspected At:

S & H Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #07-02, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	907.00 FL	*907.00 FL
2	1		*REAR TAILGATE EMBLEM	Necessary	35.80 FL	*35.80 FL
3	1		*REAR TAILGATE BADGE AVANTE	Necessary	38.20 FL	*38.20 FL
4	1		*REAR TAILGATE BADGE S	Necessary	89.60 FL	*89.60 FL
5	1		*REAR TAILGATE INNER LOCK	Dented	117.20 FL	*117.20 FL
6	1		*RH OUTER TAILLAMP	Dented / Cut	282.50 FL	*282.50 FL
7	1		*REAR TAILGATE WEATHERSTRIP	Deformed	84.30 FL	*84.30 FL
8	1		*REAR BUMPER	Buckled	447.00 FL	*447.00 FL
9	1		*REAR BUMPER SPONGE	Repair	129.30 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	279.00 FL	*279.00 FL
11	1		*RH BUMPER RETAINER	Distorted	79.20 FL	*79.20 FL
12	1		*RH BUMPER INNER BRACKET	Cracked	70.30 FL	*70.30 FL
13	1		*LH BUMPER INNER BRACKET	Repair	70.30 FL	*- FL
14	1		*REAR END PANEL	Bent	559.50 FL	*559.50 FL
15	1		*REAR END PANEL TOP TRIM BOARD	Distorted	98.30 FL	*98.30 FL
16	1		*SET REAR BUMPER NUMBER PLATE LIGHT	Cracked	75.20 FL	*75.20 FL
17	1		*REAR BUMPER MOULDING	Serviceable	85.00 FS	*- FS
18	1		*RH BUMPER SIGNAL LAMP	Cracked	65.00 FS	*65.00 FS
19	1		*RH BUMPER PARKING SENSOR	Cut	260.00 FS	*200.00 FS
20	1		*REAR BUMPER LOWER COVER	Cracked	68.20 FL	*68.20 FL
21	1		*REAR BUMPER INNER ANTENNA	Damaged	353.50 FL	*353.50 FL
22	1		*REAR NUMBER PLATE	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,239.40</b>	<b>3,894.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	756.88	716.96
<b>Total Parts (\$)</b>	<b>3,482.52</b>	<b>3,177.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY TO FOCUS HEADLAMP	New	30.00	20.00
2	TO REMOVE AND REINSTALL REAR WINDSCREEN AND CONDUCT WATER LEAK TEST	New	80.00	0.00
3	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL AND REAR FLOOR PANEL TO REWELD ,RESHAPE AND REPAIR REAR END PANEL, REAR FLOOR PANEL ,REAR BODY PANEL,TO STRAIGHTEN OUT REAR CHASSIS MEMBER AND ADJUST REAR BODY AND BOOT ALIGNMENT	New	650.00	600.00
4	TO SPRAY PAINT REAR BUMPER ,TAILGATE ,REAR END PANEL,AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	750.00	700.00
5	TO SPRAY TUFF COAT ACCIDENT AFFECTED AREAS	New	100.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,610.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >