

ASS. REC. BY:

REF:

A/G/ 20009548/Kp a3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SmL 38P2E Yr Regn: 05, 19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 27013 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM11D841CMKU 909905Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Sumitomo

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 4/9/20

Survey held at _____

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 8/9/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/10 11pm @ 3600d Car frame

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. \$ _____

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

TAY CHIN HOON
NO. 31 #02-07
PUNGGOL FIELD
SINGAPORE 828816

Not Resurvey
Resurvey by paint
61 Sing 83600 5 days

File No :
Date : 07-September-2020

Estimated cost of repair for vehicle no: **SML3892E** HYUNDAI AVANTE
Accident involving vehicle no: SML3892E & SML9100T on 04-September-2020

Description	Quantity	List Price
Rear tailgate	1	\$ <i>RM</i> 907.00 ✓
Rear tailgate emblem	1	\$ <i>RM</i> 35.80 ✓
Rear tailgate badge 'Avante'	1	\$ <i>RM</i> 38.20 ✓
Rear tailgate badge 'S'	1	\$ <i>RM</i> 89.60 ✓
Rear tailgate inner lock	1	\$ <i>RM</i> 117.20 ✓
RH outer taillamp	1	\$ <i>RM</i> 282.50 ✓
Rear tailgate weather strip	1	\$ <i>RM</i> 84.30 ✓
Rear bumper	1	\$ <i>RM</i> 447.00 ✓
Rear bumper sponge	1	\$ <i>RM</i> 129.30 ✗
Rear bumper reinforcement	1	\$ <i>CRA</i> 279.00 ✓
RH bumper retainer	1	\$ <i>RM</i> 79.20 ✓
RH bumper inner bracket	1	\$ <i>CRA</i> 70.30 ✗
LH bumper inner bracket	1	\$ <i>RM</i> 70.30 ✗
Rear end panel	1	\$ <i>RM</i> 559.50 ✓
Rear end panel top trim board	1	\$ <i>RM</i> 98.30 ✓
Rear bumper number plate light @ set	1	\$ <i>CRA</i> 75.20 ✓
		\$ 3,362.70
	Less 20%	\$ 672.54
		\$ 2,690.16
Rear bumper moulding	1	SN \$ <i>RM</i> 85.00 ✗
RH bumper signal lamp	1	SN \$ <i>CRA</i> 65.00 ✓
RH bumper parking sensor	1	SN \$ <i>2001</i> 260.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 30.00 <i>201</i>
To remove and reinstall rear windscreen and conduct water leak test.	1	\$ <i>RM</i> 80.00 ✗
To remove rear damaged parts, to jack out rear end panel and rear floor panel to reweld, reshape and repair rear end panel, rear floor panel, rear body panel, to straighten out rear chassis member and adjust rear body and boot alignment.	1	\$ 650.00 <i>600</i>
To spray paint rear bumper, tailgate, rear end panel, affected rear and inner damaged portion inclusive of preparatory works and material.	1	\$ 750.00 <i>700</i>
To spray tuff coat accident affected areas.	1	\$ 100.00 <i>60</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TAY CHIN HOON
NO. 31 #02-07
PUNGGOL FIELD
SINGAPORE 828816

File No :
Date : 07-September-2020

Estimated cost of repair for vehicle no: SML3892E HYUNDAI AVANTE
Accident involving vehicle no: SML3892E & SML9100T on 04-September-2020

Description	Quantity	List Price
		\$ 4,710.16

T/Party: AIG ASIA PACIFIC INSURANCE PTE LTD

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	707Z
Vehicle Details	
Vehicle No.:	SML3892E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Sep 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A) S
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G4FGKU146162
Chassis No.:	KMHD841CMKU909905
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,664.00
Original Registration Date:	17 May 2019
First Registration Date:	17 May 2019
Transfer Count:	0
Actual ARF Paid:	\$14,664.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2029
PARF Rebate Amount:	\$10,998.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,704.00
COE Rebate Amount:	\$29,363.00
Total Rebate Amount:	\$40,361.00

The information contained herein is correct as at 07 Sep 2020

OK