



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2008111  
INV Date 03/12/2020  
Reference CC4/FCI20009561/R1pa3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. YP 1555D  
Insured Veh. SHA 4368M  
Claim No. D20000780MFSH  
Policy No. D-20094922MFSH  
Accident Date 31/01/2020  
Inspection Date 07/09/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20009561/R1pa3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 03-12-2020		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SHA 4368M	<b>Veh. Inspected</b>	YP 1555D	
<b>Policy No.</b>	D-20094922MFSH	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	D20000780MFSH	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	RACHEL WU	<b>Assign Date</b>	07/09/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	MITSUBISHI FUSO FM65FM	<b>c.c</b>	7545	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016	
<b>Chassis No.</b>	FM65FMA30027	<b>Colour</b>	WHITE	
<b>Odometer</b>	388634	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL	
<b>General</b>	FAIR			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	295/80 R22.5	SAILUN	7 mm	
<b>L/H Front Tyre</b>	295/80 R22.5	SAILUN	7 mm	
<b>R/H Rear Tyre</b>	295/80 R22.5 (D)	SAILUN	7/7 mm	
<b>L/H Rear Tyre</b>	295/80 R22.5 (D)	SAILUN	7/7 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
<b>Accident Date</b>	31/01/2020	<b>Inspection Date</b>	07/09/2020	
<b>Survey held at</b>	8 TUAS AVE 18			
<b>Repairer</b>	VENDA ENGINEERING & TRADING PTE LTD			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR: <b>6 Working Days</b>			



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 1555D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BUMPER	BENT	1,125.19	1,125.19
1	FRT RIGHT HEADLAMP	CRACKED	1,002.32	1,002.32
1	FRT RIGHT FOG LAMP	CRACKED	293.25	293.25
1	FRT RIGHT HEADLAMP RIM	CRACKED	302.73	302.73
1	FRT RIGHT CORNER PANEL	CRACKED	1,183.63	1,183.63
1	FRT CORNER PANEL SIGNAL LAMP	SCRATCHED	211.91	211.91
1	FRT RIGHT DOOR	TO REPAIR SEE LABOUR	3,323.86	-
1	FRT RIGHT STAP GARNISH	CRACKED	267.84	267.84
	LESS 25% DISCOUNT		-1,927.68	-1,096.72
			5,783.05	3,290.15
	<b><u>LABOUR</u></b>			
	REMOVE & RENEW FRT BUMPER ,CORNER PANEL ,RIGHT DOOR,STEP GARNISH ,HEADLAMP ,SIGNALLAMP.INCLUSIVE OF THE REPAIR OF FRT RIGHT DOOR .		1,400.00	600.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	120.00	-
	PUTTY & SPRAY PAINT RENEW PARTS.		1,000.00	700.00
			2,520.00	1,300.00
	<b>GRAND TOTAL</b>		<b>8,303.05</b>	<b>4,590.15</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,650.00</b>

Report Ref No. CC4/FCI20009561/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 1555D

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 1555D

RE-INSPECTION

