

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009562/KPS3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900121526

Claimant
Vehicle No : SDU1750D **Insured Vehicle No :** SKP5287S

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: 6237118732SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDU1750D		
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Engine No:	27191031357638
Reg. Date:	27/08/2012 (Man. Year: 2012)	Chassis No:	WDD2040452A741423
Colour:	Metallic Dark Grey	Odometer:	90692 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,394.40	8,636.80	1,757.60	16.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,570.00	570.00	26.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,534.40	10,206.80	2,327.60	18.57
Approved Total (Overridden) (S\$)		8,150.00		
(S\$)	12,534.40	8,150.00	4,384.40	34.98
+ GST 7.00/7.00% (S\$)	877.41	570.50	306.91	34.98
Nett Amount (S\$)	13,411.81	8,720.50	4,691.31	34.98
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,082.50		

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 10/09/2020 Inspected At:

Lim Tan Motor Pte Ltd (HQ)
Blk 176 Sin Ming Drive #03-09/10, Sin
Ming Auto Care
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,370.00 FL	*1,370.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent / Buckled	740.00 FL	*615.00 FL
3	2		*REAR BUMPER RETAINER	Serviceable	84.00 FL	*- FL
4	1		*REAR BUMPER CHROME MOULDING -CENTRE	Necessary	200.00 FL	*200.00 FL
5	2		*REAR BUMPER CHROME MOULDING -SIDE	Necessary	288.00 FL	*288.00 FL
6	1		*REAR END PANEL	Repair	1,380.00 FL	*- FL
7	1		*REAR BOOT LID	Bent	1,380.00 FL	*1,380.00 FL
8	1		*REAR BOOT LOCK	Dented	325.00 FL	*325.00 FL
9	1		*REAR BOOT STAR	Necessary	50.00 FL	*50.00 FL
10	1		*REAR BOOT C180 EMBLEM	Necessary	90.00 FL	*90.00 FL
11	1		*REAR BOOT KOMPRESSOR EMBLEM	Necessary	116.00 FL	*116.00 FL
12	1		*FRONT BUMPER	Buckled	1,310.00 FL	*1,310.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Buckled	380.00 FL	*380.00 FL
14	1		*FRONT BUMPER NUMBER PLATE GRILLE	Serviceable	145.00 FL	*- FL
15	2		*FRONT BUMPER RETAINER	Serviceable	180.00 FL	*- FL
16	1		*FRONT GRILLE	Cracked	750.00 FL	*750.00 FL
17	1		*FRONT GRILLE INNER BRACKET	Cracked	28.00 FL	*28.00 FL
18	2		*HEAD LAMPS	Mtg Cracked	2,200.00 FL	*2,200.00 FL
19	1		*SET REAR BUMPER SENSOR	Dented	400.00 FS	*400.00 FS
20	1		*SET NUMBER PLATE	Dented	80.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,496.00	9,547.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,101.60	910.20
Total Parts (S\$)	10,394.40	8,636.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT	New	1,200.00	800.00
2	TO CHECK FRONT WIRING & FOCUS HEAD LIGHTS	New	30.00	20.00
3	TO CHECK REAR WIRING & WATER LEAKAGE	New	30.00	20.00
4	TO ANTI-RUST	New	80.00	30.00
5	LABOUR CHARGES	New	800.00	700.00
Gross Labour Cost (\$\$)			2,140.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >