Attn:

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Sim, Priscilla-LK

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Date: 24 Sep 2020

Preliminary Advice

Vehicle No : SMJ6492S Accident Date : 05/09/2020 Policy No. Make : KIA CERATO : 1900059207 Assignment Date : 08/09/2020 Excess : S\$600.00 : 0

Date of Inspection : 08/09/2020 Est. Duration of Repair

Inspection At : CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS)

209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value (Normal Car)	:S\$	87,999.00
New for Old Value (Off Peak Car)	:S\$	70,999.00
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	18,088.00
Salvage Value	:S\$	
Margin for Repair (New for Old-Off Peak Car)	:S\$	52,911.00
Margin for Repair (Pre-Accident Value)	:S\$	31,912.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(X	()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :