

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20009572/BGA3Q2

Date:

06/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900249369

Claimant Vehicle No : SMA4422E**Insured Vehicle No :**

SMH2482H

Date of Loss: 07/08/2020

Nature of Claim:

TP

Claim No:

5161904875SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMA4422E**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR0B46889

Reg. Date: 08/01/2018 (Man. Year: 2018)

Chassis No: ZVW400029163

Colour: Black

Odometer: 214328 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Citi 5 mm

Rear Left Side: Citi 5 mm

Front Right Side: Citi 5 mm

Rear Right Side: Citi 5 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,913.47	3,613.32	3,300.15	47.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,770.00	1,580.00	47.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,263.47	5,383.32	4,880.15	47.55
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	10,263.47	4,300.00	5,963.47	58.10
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		

+ Car Rental (6.0 x S\$120.00/day) (S\$)	720.00
+ Doc/Search Fee (S\$)	29.00
Nett Liability (S\$)	5,369.00

INSPECTION

Date of Assignment: 03/09/2020

Date Inspected: 04/09/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Singapore 575722

Adjuster: Lim Teow Guan

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	786.90 FL	*665.10 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	284.00 FL	*242.50 FL
3	1		*FRONT FOG LAMP LH	Not Damaged	385.60 FL	*- FL
4	1		*FRONT FOG LAMP GARNISH LH	Not Damaged	347.00 FL	*- FL
5	1		*HEADLAMP LH	Broken	978.30 FL	*978.30 FL
6	1		*HEADLAMP LOWER BRACKET LH	Not Damaged	210.00 FL	*- FL
7	1		*FRONT FENDER LH	Dented	723.40 FL	*723.40 FL
8	1		*FRONT FENDER INNER COWLING LH	Torn	187.60 FL	*187.60 FL
9	1		*FRONT FENDER EMBLEM HYBRID	Necessary	86.50 FL	*86.50 FL
10	1		*FRONT DOOR LH	Repair	894.20 FL	*- FL
11	1		*FRONT DOOR BLACK TAPE	Necessary	60.00 FL	*60.00 FL
12	1		*FRONT DOOR INNER LOCK	Not Damaged	153.60 FL	*- FL
13	1		*FRONT LOWER ARM LH	Not Damaged	451.20 FL	*- FL
14	1		*FRONT KNUCKLE ARM LH	Bent	478.00 FL	*478.00 FL
15	1		*FRONT KNUCKLE ARM BEARING LH	Jammed	298.70 FL	*223.40 FL
16	1		*FRONT SHOCK ABSORBER LH	Bent	422.80 FL	*422.80 FL
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*FRONT FOG LAMP GARNISH CLIPS	No such part	50.00 FS	*- FS
20	1		*FRONT FENDER SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*FRONT DOOR SEALANT	Not Necessary	100.00 FS	*- FS
23	1		*FRONT ALLOY RIM	Cut	680.00 FS	*150.00 FS
24	1		*FRONT TYRE	Not Damaged	380.00 FS	*- FS
25	1		*FRONT BUMPER DAY LIGHT LH	Broken	287.60 FL	*287.60 FL
26	1		*FRONT BUMPER SIDE AIR DUCT LH	Broken	87.60 FL	*87.60 FL
27	1		*FRONT FENDER INNER COWLING BRACKET LH	Broken	68.30 FL	*68.30 FL
28	1		*FRONT BUMPER SIDE AIR DUCT CLIPS	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,711.30	4,741.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,797.83	1,127.78
Total Parts (\$\$)	6,913.47	3,613.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR FRT LH DOOR	New	200.00	200.00
2	R&R FRONT UNDER CARRIAGE	New	150.00	80.00
3	R&R FRONT TYRE AND BALACING	New	100.00	0.00
4	WHEEL ALIGNMENT	New	120.00	60.00
5	UPHOLSTERY	New	200.00	0.00
6	PANEL BEAT	New	1,200.00	800.00
7	RUST PROOFING	New	100.00	0.00
8	CHECK WIRING	New	80.00	30.00
9	SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,350.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >