

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT120009574/UQF3E2  
**Date:** 30/12/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00059782000
<b>Claimant Vehicle No :</b>	FBK3722Z	<b>Insured Vehicle No :</b>	GBK3974M
Date of Loss:	28/07/2020	Nature of Claim:	TP
			Claim No: SNM20D202678/C02/TKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBK3722Z</b>		
Make & Model:	YAMAHA TMAX530, 530cc CVT ABS	Engine No:	J409E058907
Reg. Date:	10/07/2015 (Man. Year: 2015)	Chassis No:	JYASJ099000010360
Colour:	Grey	Odometer:	23643 km
Engine Capacity:	530 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	160/60 R15
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,632.40	1,309.14	323.26	19.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,008.00	350.00	658.00	65.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,640.40</b>	<b>1,659.14</b>	<b>981.26</b>	<b>37.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	2,640.40	1,300.00	1,340.40	50.77
<b>+ GST 7.00/7.00% (S\$)</b>	184.83	91.00	93.83	50.77
<b>Nett Amount (S\$)</b>	<b>2,825.23</b>	<b>1,391.00</b>	<b>1,434.23</b>	<b>50.77</b>

### INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020  
Estimated Period of Repair: 3.0 days

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)  
No. 6 Defu Lane 4  
Singapore 539410

---

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Dec 2020)
<b>Parts:</b>	N/A YAMAHA TMAX530 530cc CVT ABS (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBK3722Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCE HANDLE	Scratched	84.00 F	*84.00 FL
2	1		*BOARD FOOTREST 2	Cut	179.20 F	*179.20 FL
3	1		*BODY COWLING 2 RH	Cut	127.40 F	*127.40 FL
4	1		*BRACKET MUFFLER	Bent	21.00 F	*21.00 FL
5	1		*DAMPER (BOARD FOOTREST 2)	Necessary	2.10 F	*2.10 FL
6	1		*DAMPER 1	Necessary	1.40 F	*1.40 FL
7	1		*DAMPER 2 (BOARD FOOTREST 2)	Necessary	3.50 F	*3.50 FL
8	1		*DAMPER 3 (BOARD FOOTREST 2)	Necessary	10.50 F	*10.50 FL
9	1		*FENDER INNER 2	Cracked	43.40 F	*43.40 FL
10	1		*LED SHIELD 1	Cut	233.80 F	*233.80 FL
11	1		*LEVER 2	Bent	53.20 F	*53.20 FL
12	1		*MOLE SIDE COVER 2	Cut	159.60 F	*159.60 FL
13	1		*PANLE INNER 4	Cracked	12.60 F	*12.60 FL
14	1		*PLATE 2	Bent	35.00 F	*35.00 FL
15	1		*PROTECTOR MUFFLER	Cut	177.66 F	*177.66 FL
16	1		*PROTECTOR MUFFLER (FRONT)	Cut	152.88 F	*152.88 FL
17	1		*PROTECTOR MUFFLER (INNER)	Twisted	52.36 F	*52.36 FL
18	1		*STAND MAIN	Repair	177.80 F	*- FL
19	1		*MIRROR REAR VIEW RH ASSY	Scratched	105.00 F	*105.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,632.40</b>	<b>1,454.60</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	145.46
<b>Total Parts (\$\$)</b>	<b>1,632.40</b>	<b>1,309.14</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	1,008.00	350.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,008.00</b>
				<b>350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >