

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009576/KRS3Q2
Date: 15/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993986
Claimant Vehicle No :	SKT947H	Insured Vehicle No :	SMD9404J
Date of Loss:	03/09/2020	Nature of Claim:	TP
		Claim No:	6976551393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT947H	Engine No:	2AZF366509
Make & Model:	TOYOTA ESTIMA AERAS, 2.4 (A)	Chassis No:	ACR507085244
Reg. Date:	10/06/2010 (Man. Year: 2010)	Odometer:	123122 km
Colour:	Metallic Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Tourador 5 mm	Rear Left Side:	Tourador 4 mm
Front Right Side:	Tourador 5 mm	Rear Right Side:	Tourador 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,543.02	6,597.02	946.00	12.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	1,900.00	1,320.00	40.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,763.02	8,497.02	2,266.00	21.05
Approved Total (Overridden) (S\$)		6,600.00		

(S\$)	10,763.02	6,600.00	4,163.02	38.68
+ GST 7.00/7.00% (S\$)	753.41	462.00	291.41	38.68
Nett Amount (S\$)	11,516.43	7,062.00	4,454.43	38.68
+ Car Rental (9.0 x S\$180.00/day + 7.00% GST) (S\$)		1,733.40		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,831.85		
Global Sum Settlement (S\$)		8,800.00		

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020

Inspected At:

Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,635.00 FL	*1,635.00 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	95.00 FL	*95.00 FL
3	1		*TAILGATE EMBLEM	Necessary	73.00 FL	*73.00 FL
4	1		*TAILGATE BADGE ESTIMA	Necessary	48.00 FL	*48.00 FL
5	1		*TAILGATE BADGE AERAS	Necessary	56.00 FL	*56.00 FL
6	1		*TAILGATE OUTER MOULDING	Serviceable	226.00 FL	*- FL
7	1		*TAILGATE LOCK	Dented	425.00 FL	*371.00 FL
8	1		*TAILGATE LOCK CATCH	Distorted	58.70 FL	*58.70 FL
9	1		*TAILGATE WEATHERSTRIP (50%)	Dented / Cut	268.50 FS	*179.00 FS
10	1		*TAILGATE STOPPER	Missing	14.00 FL	*14.00 FL
11	1		*TAILGATE TRIM BOARD	Mtg Cracked	524.00 FL	*524.00 FL
12	10		*TAILGATE TRIM BOARD CLIPS	Necessary	38.00 FL	*38.00 FL
13	1		*TAILGATE INNER HANDLE GRIP	Missing	48.00 FL	*48.00 FL
14	1		*TAILGATE LOCK COVER	Missing	55.00 FL	*55.00 FL
15	1		*REAR BUMPER	Buckled	595.00 FL	*595.00 FL
16	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
17	1		*REAR BUMPER TOP RETAINER LH	Distorted	54.00 FL	*54.00 FL
18	2		*REAR BUMPER BRACKETS	Repair	204.00 FL	*- FL
19	1		*REAR BUMPER INNER BOOT SENSOR	Dented	245.00 FL	*245.00 FL
20	1		*REAR BUMPER CORNER RETAINER LH	Distorted	40.00 FL	*40.00 FL
21	2		*REAR BUMPER SPONGES	No such part	210.00 FL	*- FL
22	1		*REAR BUMPER TOW COVER	Serviceable	26.00 FL	*- FL
23	1		*REAR BUMPER REFLECTOR	Cracked	75.00 FL	*75.00 FL
24	1		*TAILLAMP LH	Cracked	409.00 FL	*409.00 FL
25	1		*END PANEL	Bent	677.00 FL	*677.00 FL
26	1		*END PANEL INNER PANEL	No such part	302.00 FL	*- FL
27	1		*END PANEL TOP GARNISH	Mtg Cracked	286.00 FL	*286.00 FL
28	1		*END PANEL LOWER GARNISH	Mtg Cracked	301.00 FL	*301.00 FL
29	2		*REAR FENDER TRIM BOARDS	Cracked	1,480.00 FL	*1,480.00 FL
30	1		*SPARE TYRE TOP BOARD	Cracked	855.00 FL	*855.00 FL
31	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*TAILGATE GLASS SEALER	Necessary	30.00 FS	*30.00 FS
33	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*50.00 FS
34	1		*REAR NUMBER PLATE	Bent	45.00 FS	*45.00 FS
35	1		*REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					9,816.20	8,614.70
- List Item Discount on L Items 25.00/25.00% (\$\$)					2,273.18	2,017.68
Total Parts (\$\$)					7,543.02	6,597.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /TRANSFER TAILGATE FITTINGS /ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO DISMANTLE /REFIT TAILGATE GLASS	New	160.00	120.00
3	TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS & TRIMS	New	80.00	80.00
4	TO SUPPLY END PANEL BODY SEALANT	New	60.00	30.00
5	TO CONDUCT REAR ELECTRICAL CHECK, REPLACE REVERSE SENSORS ,MODULE ETC	New	120.00	50.00
6	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO TO RESPRAY /RPELACED /REPAIR PANEL	New	100.00	60.00
7	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL ,SPARE TYRE PANEL ,FLOOR PANEL ,REAR N/S FENDER ETC .CNT ,WELD END PANEL AND PARTS REPLACEMENT	New	1,200.00	700.00
8	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
9	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	350.00	0.00
Gross Labour Cost (\$\$)			3,220.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >