

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20009578/QQF3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00001282000

Claimant Vehicle No : SLG9402K **Insured Vehicle No :** SLA9447M

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: SNM20D203246/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG9402K	Engine No:	LEB4260612
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71041199
Reg. Date:	19/10/2016 (Man. Year: 2016)	Odometer:	253158 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,646.80	4,655.76	2,991.04	39.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,570.00	1,270.00	33.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,486.80	7,225.76	4,261.04	37.10
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	11,486.80	5,800.00	5,686.80	49.51
+ GST 7.00/7.00% (S\$)	804.08	406.00	398.08	49.51
Nett Amount (S\$)	12,290.88	6,206.00	6,084.88	49.51

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020 Inspected At: 60 Jalan Lam Huat #03-35/36
Repairer: Lion City Rentals Pte Ltd (HQ)

Estimated Period of Repair: 7.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2020)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG9402K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,850.00 FL	*1,200.00 FL
2	1		*REAR TAILGATE BACK TRIM COVER	Crumpled	580.00 FL	*480.00 FL
3	1		*REAR TAILGATE LOCK	Jammed	550.00 FL	*200.00 FL
4	1		*REAR TAILGATE LOCK CATCH	Serviceable	158.00 FL	*- FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Crumpled	255.00 FL	*190.00 FL
7	1		*REAR TAILGATE HOLDER COVER	Deformed	80.00 FL	*80.00 FL
8	1		*REAR TAILGATE HONDA EMBLEM	Serviceable	81.30 FL	*- FL
9	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	88.40 FL	*88.40 FL
10	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
11	1		*REAR TRAY BOX	Scratched	620.00 FL	*420.00 FL
12	1		*REAR BUMPER	Crumpled	1,350.00 FL	*1,100.00 FL
13	1		*REAR BUMPER LH SIDE RETAINER	Broken	128.00 FL	*128.00 FL
14	1		*REAR BUMPER RH SIDE RETAINER	Broken	128.00 FL	*128.00 FL
15	1		*REAR BUMPER LH REFLECTOR GARNISH COVER	Deformed	178.00 FL	*178.00 FL
16	1		*REAR BUMPER LH REFLECTOR	Serviceable	250.00 FL	*- FL
17	1		*REAR BUMPER SPONGE	Serviceable	150.00 FL	*- FL
18	1		*REAR END PANEL	Dented	1,200.00 FL	*560.00 FL
19	1		*REAR END PANEL TOP COVER	Crumpled	300.00 FL	*155.50 FL
20	1		*REAR BUMPER TOW COVER	Missing	30.00 FL	*30.00 FL
21	1		*REAR ANTENNA SENSOR	Cracked	200.00 FL	*200.00 FL
22	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
23	1		*SET WINDSCREEN SEALANT	Necessary	120.00 FS	*30.00 FS
24	1		*SET BODY SEALANT	Necessary	300.00 FS	*30.00 FS
25	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
26	1		*SET END PANEL TO GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,338.50	5,739.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,691.70	1,083.94
Total Parts (\$\$)	7,646.80	4,655.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE REAR TAILGATE ,REAR BUMPER ,END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STRAIGHTEN SPARE TYRE PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS	New	1,500.00	1,100.00
2	TO RESPRAY REAR ROOF SPOILER ,REAR TAILGATE ,REAR BUMPER ,END PANEL AND SPARE TYRE PANEL (INNER/OUTER)	New	1,400.00	900.00
3	TO REMOVE & INSTALL REAR WINDSCREEN	New	160.00	120.00
4	TO APPLY RUSTPROOFING /TUFFCOATING TREATMENT TO REPLACED PARTS	New	80.00	40.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
6	TO ACTIVATE AND DEACTIVATE HYBRID BATTERY AS A SAFETY PRECAUTIONS FOR ALL HYBRID CARS }	New	300.00	350.00
7	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS }	New	300.00	0.00
Gross Labour Cost (\$\$)			3,840.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >