



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2008236  
INV Date 10/12/2020  
Reference CC4/LPC20009580/R1gs3q2  
Code LPC2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMT 2214C  
Insured Veh. YP 2606J  
Claim No. 20/20/20/VC05/023539  
Policy No. Z20VC05005264  
Accident Date 13/08/2020  
Inspection Date 09/09/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20009580/R1gs3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 10-12-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YP 2606J	<b>Veh. Inspected</b>	SMT 2214C
<b>Policy No.</b>	Z20VC05005264	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	20/20/20/VC05/023539	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KENNY	<b>Assign Date</b>	08/09/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	VOLVO S60 T4 M	<b>c.c</b>	1969
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	7JRZSALADLG030470	<b>Colour</b>	WHITE
<b>Odometer</b>	8732	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/50 R17	MICHELIN	6 mm
<b>L/H Front Tyre</b>	225/50 R17	MICHELIN	6 mm
<b>R/H Rear Tyre</b>	225/50 R17	MICHELIN	6 mm
<b>L/H Rear Tyre</b>	225/50 R17	MICHELIN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.
---------------------------------------------------------------------------------

### 5. General Information

<b>Accident Date</b>	13/08/2020	<b>Inspection Date</b>	09/09/2020
<b>Survey held at</b>	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>5 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 2214C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER FRT T4 (SN)	DEFORMED	1,989.60	1,790.64
1	BUMPER GRILLE LH T4 (SN)	CUT	97.40	87.66
1	BUMPER BRACKET FRT L (SN)	SERVICEABLE	44.90	-
1	FENDER PANEL FRT LH (SN)	TO REPAIR SEE LABOUR	1,240.60	-
1	FENDER CARRIER FRT L (SN)	SERVICEABLE	173.70	-
1	HEADLAMP LED LH ALL (SN)	SCRATCHED	2,453.20	2,207.88
1	HEADLAMP CONTROL UNI (SN)	SHORTED	480.40	432.36
1	ALLOY RIM 17 T4 S60 (SN)	NOT NECESSARY	965.30	-
1	BUMPER INSTALLING MT (SN)	NECESSARY	87.70	78.93
1	ADHESIVE TUBE CHEMIC (SN)	NOT NECESSARY	725.00	-
10	BLIND RIVET 4.0*21 P (SN)	NECESSARY	32.00	28.80
10	BUMPER CLIP 8X8,5 (SN)	NECESSARY	57.00	51.30
2	EXTERIOR ADHESIVE GL (SN)	NOT NECESSARY	498.80	-
			8,845.60	4,677.57
	<b><u>LABOUR</u></b>			
	TO REPLACE FRONT BUMPER,LHF FENDER,LHF HEADLAMP,LHF FOG LAMP GRILLE,ETC.INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT LH.		2,400.00	1,600.00
	TO PUTTY AND SPRAY PAINT ON FRONT BUMPER,LHF FENDER,ETC.		2,100.00	1,400.00
	TO FOCUS HEADLAMPS.		175.00	175.00
	TO REPLACE LHF RIM.	NOT NECESSARY	50.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	280.00	-
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		525.00	525.00
			-	-
			-	-
			-	-
			5,530.00	3,700.00
	<b>GRAND TOTAL</b>		<b>14,375.60</b>	<b>8,377.57</b>



RECOMMENDED COST OF REPAIRS			8,377.57
-----------------------------	--	--	----------

Report Ref No. CC4/LPC20009580/R1gs3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2214C

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMT 2214C

RE-INSPECTION

