

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Sep 2020 Edit Reg		08 Sep 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by adjuster]				
Insured: LAWRENCE CHIA CHAO XIAN , ID: S7929223J				
Main Claimant: KENT AUTO SERVICE				
Vehicle Reg. No.: SMC1531H		Date of Loss: 05/09/2020 12:00 - :59 [26 Months and 9 Days From LTA Reg Date (Man Yr)]		
Claim Type: TP / 7003723512SG		Policy/Cover Note No.: 2100490795 (Comprehensive)		
Vehicle Reg. No. (Insured): SLH9013U		Policy No. (Claimant):		
		Excess:		
Repairer: Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:				
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL]				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/09/2020]				
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS ☐				View All Search Tasks Create New Task Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

***SMC1531H (7003723512SG)
[SLH9013U]**

TP

KENT AUTO SERVICE

Sep 5 2020 12:00PM

[LAWRENCE CHIA CHAO XIAN]

Kent Auto Services - Kaki Bukit

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/09/20 19:26	General View	 Load JPG	
2	08/09/20 19:26	General View	 Load JPG	
3	08/09/20 19:26	General View	 Load JPG	
4	08/09/20 19:26	Odometer Reading	 Load JPG	
5	08/09/20 19:26	Chassis Number	 Load JPG	
6	08/09/20 19:26	General View	 Load JPG	
7	08/09/20 19:26	General View	 Load JPG	
8	08/09/20 19:26	General View	 Load JPG	
9	08/09/20 19:26	General View	 Load JPG	
10	08/09/20 19:26	General View	 Load JPG	
11	08/09/20 19:26	General View	 Load JPG	
12	08/09/20 19:26	General View	 Load JPG	
13	08/09/20 19:26	General View	 Load JPG	
14	08/09/20 19:26	General View	 Load JPG	
15	08/09/20 19:26	General View	 Load JPG	
16	08/09/20 19:26	General View	 Load JPG	
17	08/09/20 19:26	General View	 Load JPG	
18	08/09/20 19:26	General View	 Load JPG	
19	08/09/20 19:26	General View	 Load JPG	
20	08/09/20 19:26	General View	 Load JPG	
21	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
22	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
23	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
24	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
25	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
26	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
27	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
28	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
29	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
30	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
31	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
32	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
33	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
34	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
35	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
36	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
37	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
38	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
39	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	
40	08/09/20 19:27	Photographs of Damaged Parts	 Load JPG	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	08/09/20 19:27	Photographs of Damaged Parts	Load JPG	☒
42	08/09/20 19:27	Photographs of Damaged Parts	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/09/20 12:12	ACKNOWLEDGEMENT EMAIL TO AIG DD08092020	Load PDF	
2	08/09/20 12:12	EMAIL FROM AIG DD08092020	Load PDF	
3	08/09/20 12:12	TP GIA REPORT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/09/20 14:55	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20009582/ETF3S2**Date:** 18/09/2020**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100490795
Claimant Vehicle No :	SMC1531H	Insured Vehicle No :	SLH9013U
Date of Loss:	05/09/2020	Nature of Claim:	TP
		Claim No:	7003723512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1531H		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB6555358
Reg. Date:	27/06/2018 (Man. Year: 2018)	Chassis No:	GP71212661
Colour:	Silver	Odometer:	205034 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/09/2020	
Date Inspected:	08/09/2020 Inspected At:	Kent Auto Services - Kaki Bukit (HQ) 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Dented	0.00 F	*- F
2	2		*REAR LH DOOR HINGE	Bent	0.00 F	*- F
3	1		*REAR LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
4	1		*REAR LH DOOR GLASS REGULATOR MOTOR	Jammed	0.00 F	*- F
5	1		*REAR LH DOOR RUBBER	Crushed	0.00 F	*- F
6	1		*REAR LH DOOR LOCK	Bent	0.00 F	*- F
7	1		*REAR LH DOOR INNER TRIM BOARD	Crushed	0.00 F	*- F
					Total Parts (\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >