

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20009598/DQF3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant
Vehicle No : SHA9712U

Insured Vehicle No : SLG6649K

Date of Loss: 06/09/2020

Nature of Claim: TP

Claim No: 628341

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA9712U**

Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A)

Engine No: G4LEKU297734

Reg. Date: 10/07/2019 (Man. Year: 2019)

Chassis No: KMHC851CVKU164678

Colour: Yellow

Odometer: 107397 km

Engine Capacity: 1580 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side:

West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side:

West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,926.48	20,910.96	18,015.52	46.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	2,400.00	1,790.00	42.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	43,116.48	23,310.96	19,805.52	45.93
+ GST 7.00/7.00% (\$\$)	3,018.15	1,631.77	1,386.38	45.93
Nett Amount (\$\$)	46,134.63	24,942.73	21,191.90	45.93

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 08/09/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming

Industrial Estate

Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2020)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9712U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,253.80 FL	*- FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	237.40 FL	*- FL
3	1		*BONNET LOCK	Serviceable	127.30 FL	*- FL
4	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
5	1		*RADIATOR GRILLE NEW MODEL	Not Necessary	1,568.60 FL	*- FL
6	1		*RADIATOR GRILLE	Cracked	1,227.50 FL	*1,227.50 FL
7	1		*FRONT NUMBER PLATE GARNISH	Cracked	137.60 FL	*137.60 FL
8	1		*FRONT BUMPER COVER	Torn	418.30 FL	*418.30 FL
9	1		*FRONT BUMPER TOP COVER	Not Necessary	476.30 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	1,075.10 FL	*1,075.10 FL
12	1		*FRONT BUMPER REINFORCEMENT ABSORBER (LH)	Not Necessary	186.50 FL	*- FL
13	1		*FRONT BUMPER TOWING COVER	Not Necessary	29.00 FL	*- FL
14	1		*FRONT BUMPER MOULDING CENTRE UPPER	Distorted	368.50 FL	*368.50 FL
15	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
16	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	365.30 FL	*- FL
17	1		*FRONT BUMPER LOWER GRILLE MOULDING	Not Necessary	127.60 FL	*- FL
18	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
19	1		*FRONT BUMPER BRACKET TOP (LH)	Not Necessary	35.00 FL	*- FL
20	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	28.00 FL	*- FL
21	1		*FRONT BUMPER RETAINER MOUNTING (LH)	Not Necessary	65.30 FL	*- FL
22	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
23	1		*FRONT BUMPER GRILLE (LH)	Not Necessary	186.90 FL	*- FL
24	1		*FRONT BUMPER AIR DUCT (LH)	Not Necessary	153.80 FL	*- FL
25	1		*DAY LIGHT ,LH	Not Necessary	642.50 FL	*- FL
26	1		*DAY LIGHT WIRE ,LH	Socket Broken	585.50 FL	*585.50 FL
27	1		*BUZZER ASSY -PIEZO (LH)	Not Necessary	388.00 FL	*- FL
28	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked / Dented	949.30 FL	*949.30 FL
29	1		*HEADLAMP (LH)	Cracked	3,987.30 FL	*1,198.80 FL
30	1		*HORN UNIT (LH)	Not Necessary	72.80 FL	*- FL
31	1		*HORN WIRE	Not Necessary	386.70 FL	*- FL
32	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
33	1		*COOLANT	Not Necessary	45.00 FL	*- FL
34	1		*FRT PILLAR UPPER COVER -OUTER (LH)	Not Necessary	89.60 FL	*- FL
35	1		*FRONT FENDER (LH)	Repair	490.70 FL	*- FL
36	1		*FRONT FENDER APRON PANEL (LH)	Not Necessary	756.20 FL	*- FL
37	1		*FRONT FENDER SHIELD (LH)	Not Necessary	164.70 FL	*- FL
38	1		*AIRCON CONDENSER	Punctured / Bent	663.60 FL	*663.60 FL
39	1		*BOOT LID	Bent	2,480.40 FL	*2,480.40 FL
40	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
42	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
43	1		*THRD BRAKE LIGHT	Not Necessary	385.60 FL	*- FL
44	2		*BOOT LID LAMP (LH/RH)	Cracked	1,588.80 FL	*1,588.80 FL
45	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
46	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
47	1		*BOOT LID TRIMBOARD ,CENTRE	Not Necessary	159.60 FL	*- FL
48	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	185.00 FL	*- FL
49	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
50	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
51	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
52	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	376.20 FL	*376.20 FL
53	1		*ANTENNA ASSY-SMARTK	Broken	689.50 FL	*689.50 FL
54	1		*REAR BUMPER CENTRE MOULDING ASSY	Distorted	451.25 FL	*451.25 FL
55	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Broken	47.50 FL	*47.50 FL
56	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
57	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Not Necessary	171.60 FL	*- FL
58	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
59	1		*REAR BUMPER UNDER CENTRE	Not Necessary	123.85 FL	*- FL
60	1		*REAR BUMPER SIDE UNDER (LH/RH)	N/S Broken / O/S Not Necessary	246.20 FL	*123.10 FL
61	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
62	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
63	1		*REAR BUMPER TOWING COVER	Distorted	98.80 FL	*98.80 FL
64	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
65	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
66	2		*LICENCE LAMP (LH/RH)	Not Necessary	170.60 FL	*- FL
67	2		*TAIL LAMP (LH/RH)	Mtg Cracked	1,740.80 FL	*1,740.80 FL
68	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	417.80 FL	*- FL
69	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
70	1		*ANTENNA ASSY -TRUNK	Not Necessary	689.50 FL	*- FL
71	1		*REAR PANEL GARNISH	Deformed	346.80 FL	*57.70 FL
72	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
73	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
74	1		*SPARE TYRE PANEL	Repair	892.50 FL	*- FL
75	1		*MEMBER ASSY -REAR FLOOR CENTRE	Not Necessary	863.50 FL	*- FL
76	2		*PANEL ASSY -REAR FLOOR SIDE (LH/RH)	Not Necessary	78.80 FL	*- FL
77	1		*REAR TRAY TOOLS BOX LH	Deformed	693.20 FL	*693.20 FL
78	1		*REAR TRAY LUGGS CENTER	Deformed	354.20 FL	*354.20 FL
79	1		*FRONT NUMBER PLATE }	Broken	25.00 FS	*45.00 FS
80	1		*FRONT NO PLATE TRIM COVER }	Broken	30.00 FS	*- FS
81	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
82	1		*EMBLEM -BLUE DRIVE (LH)	Serviceable	26.60 FS	*- FS
83	1		*REVERSE CAMERA ASSY	Not Necessary	983.20 FS	*- FS
84	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	35.00 FS	*35.00 FS
85	1		*BOOT LID COMFORT CABLINK TEL NO.STICKER	Not Necessary	30.00 FS	*- FS
86	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
87	1		*REAR NO PLATE +TRIM COVER	Broken	45.00 FS	*45.00 FS
88	1		*REAR BUMPER ADVERTISEMENT LOGO	Not Necessary	50.00 FS	*- FS
89	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
90	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
91	1		*SPARE TYRE PANEL TOP COVER SILICON	Not Necessary	250.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
92	2		*FLAP ASSY ACTIVE AIR UPPER (LH/RH)	Broken	1,649.20 FL	*1,649.20 FL
93	1		*UNIT ASSY -SMART CRU (RADAR SENSOR)	Bent / Mtg Broken	2,910.90 FL	*2,910.90 FL
94	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
95	1		*REAR TRAY TOOLS BOX RH	Cracked	675.30 FL	*675.30 FL
96	1		*HEADLAMP (RH)	Cracked	3,987.30 FL	*1,198.80 FL
97	2		*FRONT FENDER ADVERSEMENT LOGO (LH/RH)	Repeated	200.00 FS	*- FS
98	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	48,120.40	25,988.45
- List Item Discount on L Items 20.00/20.00% (S\$)	9,193.92	5,077.49
Total Parts (S\$)	38,926.48	20,910.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,200.00	900.00
3	WIRING CHARGE	New	140.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
7	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
8	REMOVE /REFIX RADIATOR	New	90.00	50.00
9	REMOVE /REFIX AIRCON & REFILL GAS	New	130.00	80.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
11	REMOVE/REFIX REAR WINDSCREEN GLASS UPPER & LOWER	New	240.00	80.00
Gross Labour Cost (S\$)			4,190.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >