

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT120009600/R1YF3E2**Date:** 04/12/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN17644419022

Claimant Vehicle No : SMH6424A **Insured Vehicle No :** GBD5282A

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: SNM20D203255/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH6424A**

Make & Model: NISSAN NOTE, 1.2 CVT (A) Engine No: HR12260323J

Reg. Date: 29/01/2019 (Man. Year: 2018) Chassis No: JN1TAAE12Z0982557

Colour: Grey Odometer: 1024 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,807.52	5,807.52	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,377.00	4,137.00	240.00	5.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,184.52	9,944.52	240.00	2.36
+ GST 7.00/7.00% (S\$)	712.92	696.12	16.80	2.36
Nett Amount (S\$)	10,897.44	10,640.64	256.80	2.36

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 09/09/2020 Inspected At: TC AutoClinic Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2020)
Parts: 144	NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMH6424A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE-RR BUMPER	Deformed	460.00 FN	*460.00 FN
2	1		*PANEL REAR LWR	Bent	552.80 FN	*552.80 FN
3	1		*DOOR BACK TAILGATE	Bent	1,018.20 FN	*1,018.20 FN
4	1		*EMBLEM-BACK DOO LETTERING	Necessary	64.90 FN	*64.90 FN
5	1		*ORNAMENT-BACK D EMBLEM	Necessary	79.90 FN	*79.90 FN
6	1		*GLASS-TAIL GATE	Necessary	1,198.80 FN	*1,198.80 FN
7	1		*ENERGY ABSORBER SPONGE	Cracked	125.30 FN	*125.30 FN
8	1		*BRKT BUMPER RH	Necessary	51.00 FN	*51.00 FN
9	1		*BRKT BUMPER LH	Necessary	51.00 FN	*51.00 FN
10	1		*CAMERA BRACKET	Necessary	20.00 FS	*20.00 FS
11	1		*REAR W/SCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
12	1		*LAMP COMB RR, RH	Scratched	435.80 FN	*435.80 FN
13	1		*PLATE-LUGGAGE BOOT INNER GARNISH	Deformed	68.80 FN	*68.80 FN
14	1		*A LOCK LIFT REAR TAILGATE	Cracked	128.40 FN	*128.40 FN
15	1		*REAR NUMBER PLATE GARNISH	Scratched	255.60 FN	*255.60 FN
16	1		*CLIP BUMPER	Necessary	15.60 FN	*15.60 FN
17	1		*LAMP COMB RR, LH	Scratched	435.80 FN	*435.80 FN
18	1		*ACTUATOR ASSY	Shorted	170.00 FN	*170.00 FN
19	1		*BOX-LUGGAGE	Deformed	143.00 FN	*143.00 FN
20	1		*FINISHER-LUGGAG	Deformed	396.40 FN	*396.40 FN
21	1		*FINISHER-LUGGAG	Deformed	396.40 FN	*396.40 FN
22	1		*CARPET-LUGGAGE	Cracked	433.70 FN	*433.70 FN
23	1		*COVER-ARM, BACK WIPER	Missing	13.10 FS	*13.10 FS
24	1		*ARM ASSY-RR WOW	Scratched	82.00 FS	*82.00 FS
25	1		*MOTOR-WIPER	Shorted	427.30 FS	*427.30 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	7,103.80	7,103.80
- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,296.28	1,296.28
Total Parts (S\$)	5,807.52	5,807.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
2	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	100.00	100.00
3	REPAIR / REPLACE REAR BUMPER, RR END PANEL, RR TAILGATE LH RR FENDER & RH RR FENDER + FLOOR PAN	New	1,680.00	1,680.00
4	REMOVE / REFIX REAR WINDSCREEN	New	150.00	150.00
5	SUPPLY / INSTALL REAR WINDSCREEN TINTED FILM	New	144.00	144.00
6	CHECK ALL LIGHTING AFTER REPAIR	New	48.00	48.00
7	SUPPLY AND INSTALL REVERSE CAMERA	New	240.00	0.00
8	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS (OPC) (REAR)	New	60.00	60.00
9	BREAKSEAL / RESEAL REAR OPC LICENCE PLATE AND SEND FOR VEHICLE INSPECTION (OPC)	New	120.00	120.00
10	REMOVE / REFIX REAR SEAT, UPHOLSTERY, CARPET, TRIM & GARNISH TO FACILITATE REPAIR	New	280.00	280.00
11	RESPRAY REAR BUMPER, END PANEL, TAILGATE, LH RR FENDER AND RH RR FENDER + FLOOR PAN	New	1,500.00	1,500.00
			Gross Labour Cost (S\$)	4,377.00
				4,137.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >