

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMH6424A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/ /
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	/ /
3	ZZ/001	CONDUCT TP CLAIM CNTAIPINGDATE:04/09/2020 TIME: 1750 LOCATION:SLIP RD TO AYE CITY N BOUNA VISTA RD		
4	ZZ/002	REPAIR/REPLACE REAR BUMPER, RR ENDPANEL, RR TAILGATE LH RR FENDER & RH RR FENDER + FLOOR PAN	<del>1400.00</del>	840 + 840 = 1680
5	ZZ/003	RESPRAY REAR BUMPER, ENDPANEL, TAILGATE, LH RR FENDER AND RH RR FENDER + FLOOR PAN	<del>1250.00</del>	750 + 750 = 1500
6	ZZ/004	REMOVE/REFIX REAR WINDSCREEN	150.00	/ /
7	ZZ/005	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	144.00	? / /
8	ZZ/006	CHECK ALL LIGHTING AFTER REPAIR	48.00	/ /
9	ZZ/007	SUPPLY AND INSTALL REVERSE CAMERA	240.00	? XAN
TOTAL LABOUR CHARGES			3387.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMH6424A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	FACE-RR BUMPER <i>de /</i>	85022-5WJOH	460.00 /		
2	PANEL REAR LWR <i>? bt /</i>	79100-3VA0B	552.80 /		
3	DOOR BACK TAILGATE <i>St /</i>	K010M-3VAMA	1018.20 /		
4	EMBLEM-BACK DOO LETTERING <i>neu /</i>	90890-3VA0A	64.90 /		
5	ORNAMENT-BACK D EMBLEM <i>neu /</i>	90892-3VA0A	79.90 /		
6	GLASS-TAIL GATE <i>3/2 photo? neu /</i>	90300-3VA1C	1198.80 /		
7	ENERGY ABSORBER SPONGE <i>? cm /</i>	85090-5WJOA	125.30 /		
8	BRKT BUMPER RH <i>neu /</i>	85220-3VA0C	51.00 /		
9	BRKT BUMPER LH <i>neu /</i>	85221-3VA0C	51.00 /		
10	CAMERA BRACKET <i>? neu /</i>	BRACKET-CAM			20.00 /
11	REAR W/SCREEN SEALANT <i>neu /</i>	SEALANT - 4			80.00 /
12	LAMP COMB RR,RH <i>? scu /</i>	26550-5WK0A	435.80 /		
13	PLATE-LUGGAGE BOOT INNER GARNISH <i>? de /</i>	84992-3VA0A	68.80 /		
14	A LOCK LIFT REAR TAILGATE <i>? cm /</i>	90502-1HM1A	128.40 /		
15	REAR NUMBER PLATE GARNISH <i>? scu /</i>	90810-3VA5C	255.60 /		
16	CLIP BUMPER <i>neu /</i>	01553-10501	15.60 /		
17	LAMP COMB RR,LH <i>? scu /</i>	26555-5WK0A	435.80 /		
SUB TOTAL			4941.90	0.00	100.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			988.38	0.00	0.00
GRAND TOTAL			3953.52	0.00	100.00
OVERALL TOTAL			4053.52		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMH6424A

-----  
TOTAL LABOUR CHARGES                    3387.00  
TOTAL SPARE PARTS CHARGES            4053.52  
-----  
GRAND TOTAL                                7440.52 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME  
SURVEYED DATE  
AUTHORIZED DATE  
EXCESS CLAUSE  
LIABILITY  
REMARKS

: Rasul - Hp 90010068  
: 09/09/2020 @ 1030  
:  
:                    0.00                    6 days + 3 days = 9 days  
:                    0.00  
:  
:                    Reason before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: