

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20009610/QPS3Q2

**Date:** 18/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800106165

**Claimant**  
**Vehicle No :** SHD6260K **Insured Vehicle No :** SMD7975R

Date of Loss: 04/09/2020 Nature of Claim: TP Claim No: 4939309774SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD6260K</b>		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F31010
Reg. Date:	26/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU603089182
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,586.24	774.30	6,811.94	89.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,223.00	680.00	1,543.00	69.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>9,809.24</b>	<b>1,454.30</b>	<b>8,354.94</b>	<b>85.17</b>
<b>+ Car Rental (4.0 x S\$118.77/day) (\$\$)</b>		475.08		
<b>+ Doc/Search Fee (\$\$)</b>		7.00		
<b>Nett Liability (\$\$)</b>		<b>1,936.38</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,890.00</b>		

### INSPECTION

Date of Assignment: 04/09/2020

Date Inspected: 04/09/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER SUB-ASSY ,FR ,RH (DISC 25%)	Crumpled	977.80 F	*733.35 F
2	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	54.60 F	*40.95 F
3	1		*LINER ,FR FENDER RH	Serviceable	202.50 F	*- F
4	1		*RETAINER ,FR WHEEL RH	Serviceable	3.20 F	*- F
5	1		*PROTECTOR ,FR FENDER RH	Serviceable	93.90 F	*- F
6	1		*PAD ,FR WHEEL RH	Serviceable	59.60 F	*- F
7	1		*APRON SUB-ASSY ,FRONT FENDER, RH	Serviceable	979.40 F	*- F
8	1		*WHEEL DISC FRONT	Serviceable	1,879.40 F	*- F
9	1		*HUB & BEARING ASSY ,RH & LH	Serviceable	668.90 F	*- F
10	1		*CAP SUB-ASSY ,WHEEL	Serviceable	211.50 F	*- F
11	1		*TYRE	Serviceable	126.74 F	*- F
12	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Serviceable	1,436.60 F	*- F
13	1		*COVER ,OUTER MIRROR , RH	Serviceable	108.60 F	*- F
14	1		*SUPPORT ,FR BUMPER RH	Serviceable	80.10 F	*- F
15	1		*SUPPORT ,FR BUMPER LH	Serviceable	82.30 F	*- F
16	1		*CLIPS PIECE ,FRT & RR BUMPER	Serviceable	4.50 F	*- F
17	1		*MOULDING ,FRONT BUMPER SIDE ,RH	Serviceable	95.60 F	*- F
18	1		*COVER ,FR BUMPER	Repair	521.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**      **7,586.24**      **774.30**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	1,116.00	400.00
3	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,223.00</b>	<b>680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >