

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20009611/KGA3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800119272

Claimant
Vehicle No : SMQ812E **Insured Vehicle No :** SME6422X

Date of Loss: 05/09/2020 Nature of Claim: TP Claim No: 0947407836SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ812E		
Make & Model:	HONDA CIVIC, 2.0 TYPE-R (M)	Engine No:	K20C11000337
Reg. Date:	30/06/2016 (Man. Year: 2016)	Chassis No:	SHHFK2790FU700197
Colour:	Metallic Pearl White	Odometer:	82784 km
Engine Capacity:	1996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,382.72	496.00	886.72	64.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	560.00	540.00	49.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,482.72	1,056.00	1,426.72	57.47
+ GST 7.00/7.00% (\$\$)	173.79	73.92	99.87	57.47
Nett Amount (\$\$)	2,656.51	1,129.92	1,526.59	57.47
+ Car Rental (3.0 x S\$100.00/day) (\$\$)		300.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,431.92		

INSPECTION

Date of Assignment: 08/09/2020

Date Inspected: 21/09/2020 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	980.00 FL	*- FL
2	1		*REAR BUMPER INNER BRACKET CTR	Serviceable	55.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	31.40 FL	*- FL
4	12		*REAR BUMPER CLIPS	Not Necessary	42.00 FL	*- FL
5	1		*REAR BUMPER LOWER GARNISH	Dented	620.00 FL	*620.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,728.40	620.00
- List Item Discount on L Items 20.00/20.00% (\$)	345.68	124.00

Total Parts (\$)	1,382.72	496.00
-------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	10.00
2	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	500.00	200.00
4	TO SPRAY REAR BUMPER ,REAR BUMPER LOWER GARNISH ,END PANEL	New	500.00	350.00
Gross Labour Cost (\$\$)			1,100.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >