

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20009624/KRS3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800097139
Claimant Vehicle No :	SGH1597M	Insured Vehicle No :	SMD2861T
Date of Loss:	31/08/2020	Nature of Claim:	TP
		Claim No:	6757328078SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH1597M		
Make & Model:	TOYOTA COROLLA, 1.6 (A)	Engine No:	3ZZ4566139
Reg. Date:	31/05/2006 (Man. Year: 2006)	Chassis No:	MR053ZEC107119552
Colour:	Metallic Black	Odometer:	248810 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,416.52	998.40	418.12	29.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	720.00	310.00	30.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,446.52	1,718.40	728.12	29.76
Approved Total (Overridden) (S\$)		1,350.00		

(S\$)	2,446.52	1,350.00	1,096.52	44.82
+ GST 7.00/7.00% (S\$)	171.26	94.50	76.76	44.82
Nett Amount (S\$)	2,617.78	1,444.50	1,173.28	44.82
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,596.50		

INSPECTION

Date of Assignment: 09/09/2020

Date Inspected: 08/09/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Bent	344.40 FL	*344.40 FL
2	1		*FRONT O/S BUMPER SIDE RETAINER	Distorted	41.70 FL	*41.70 FL
3	1		*FRONT BUMPER REINFORCEMENT	Buckled	339.70 FL	*339.70 FL
4	1		*FRONT O/S BUMPER FOGLAMP	Scratched	224.20 FL	*224.20 FL
5	1		*FRONT W/S GLASS WASHER TANK	Dented	49.50 FL	*49.50 FL
6	1		*O/S HEADLAMP	Cut	331.70 FL	*331.70 FL
7	1		*FRONT O/S FENDER	Repair	375.10 FL	* - FL
8	1		*FRONT O/S FENDER INNER SHIELD	Serviceable	182.40 FL	* - FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,888.70	1,331.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	472.18	332.80
Total Parts (\$\$)	1,416.52	998.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	30.00	20.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	550.00	400.00
3	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	450.00	300.00
Gross Labour Cost (\$\$)			1,030.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >